
construction engineering research laboratory



Technical Report M-329 June 1983

31829

PROTECTIVE COATINGS FOR ALUMINUM TORPEDOES



by S. A. Johnston



DTIC FILE COPY

Approved for public release; distribution unlimited.


83

08

25

031

DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official indorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN IT IS NO I ONGER NEEDED DO NOT RETURN IT TO THE ORIGINATOR

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM			
	NO. 3. RECIPIENT'S CATALOG NUMBER			
CERL-TR-M-329 $\cancel{A}\cancel{D}$ - $\cancel{A}\cancel{1}\cancel{3}\cancel{1}$	879			
4. TITLE (and Subtitle)	S. TYPE OF REPORT & PERIOD COVERED			
PROTECTIVE COATINGS FOR ALUMINUM TORPEDOES	FINAL			
	5. PERFORMING ORG. REPORT HUMBER			
7. AUTHON(e)	S. CONTRACT OR GK INT NI MBER(=)			
Susan A. Johnston	MIPR No. N6t0481 MP10005			
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. ARMY	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS			
CONSTRUCTION ENGINEERING RESEARCH LABORATORY				
P.O. BOX 4005, CHAMPAIGN, IL 61820				
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE			
Naval Underwater Systems Center	June 1983			
Newport, RI 02840	130 HOMBER OF PAGES			
14. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Cities	o) 18. SECURITY CLASS. (of this report)			
-	Unclassified			
	TEL DECLASSIFICATION/SOWNGRADING SCHEDULE			
16. DISTRIBUTION STATEMENT (of this Report)				
Approved for public release; distribution unlim 17. DISTRIBUTION STATEMENT (of the chefrect entered in Block 20, If different				
IG. SUPPLEMENTARY NOTES				
Copies are available from the National Technica Springfield, VA				
19. KEY WORDS (Continue on reverse side il necessary and identify by block num torpedoes protective coatings aluminum	ber)			
The U.S. Mavy is now using a proprietary po aluminum torpedoes. Although this costing has g dling and corrosive environments, there are two	lyurethane coating on its ood resistance to rough han-			
1. Some people are highly allergic to the urethane coatings; there is concern that the Occ Administration (OSHA) may restrict the use and a	upational Safety and Health			

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OMOLETE

UNCLASSIFIED

BLOCK 20 (Continued)

SHALL SECTION OF THE PROPERTY OF THE PROPERTY

2. The polyurethane now used is a proprietary material. If it became unavailable for any reason, it would be difficult to select an alternative coating system because there is little experience with other systems in this environment.

To address these problems, the Navy asked the U.S. Army Construction Engineering Research Laboratory to evaluate alternative coatings for aluminum.

The objectives of this study were to select and evaluate aluminum costings and coating systems for their resistance to mechanical handling, and for their capability to protect aluminum from corrosion in seawater and Otto fuel, the torpedo propellant.

Of the 10 coating systems tested for this study, two were found to be suitable for use on torpedo exteriors:

- 1. The epoxy-polyamide coating MIL-P-24441 has excellent corrosion resistant properties. Formula 158 and Formula 152 are the primer and topcoat within the specification which are best suited for use on aluminum substrates. The MIL-P-24441 system has excellent adhesion. The impact resistance of this coating is best if the topcoat is applied at no more than 5 mils dry film thickness. The MIL-P-24441 system had the best overall performance of the 10 candidate coatings for torpedo exteriors.
- 2. The Ameron vinyl system (Amercoat 86 primer and Amercoat 99HS top-coat) provides a high degree of corrosion protection, has good impact resistance and adhesion, and (because it is a solution vinyl) should be easily repaired when the original coating is demaged. A 15-mil thick coat of this vinyl provides much greater protection against demage by impact than does a 10- or 5-mil coat. Adequate drying time must be allowed before putting this coating system into immersion, or premature loss of adhesion may result. The flexibility, repairability, and good performance of this coating make it a good second choice of the 10 candidate coatings for torpedo exteriors.

To coat the lining of a torpedo's internal fuel tank, the MIL-C-4556 system had the best overall performance when applied over the dichromate sealed, hardcoat anodized 7075 series aluminum. When undamaged, this coating is highly resistant to deterioration in Otto fuel, seawater, or a mixture of the two. When the coating is physically damaged, it does not break away from the damaged area, but remains intact even if corrosion has undercut the coating.

FOREWORD

This study was done by the Engineering and Materials Division (%%), U.S. Army Construction Engineering Research Laboratory (CERL) for the Marcal Underwater Systems Center under MIPR No. N660481 MP10005. The Navy technical monitor was Mr. H. Pearl, Code 36622. The Navy funding was provided by Work Unit Mumber (WUN) 106, whose Principal Investigators are Mr. K. J. Haydon, NAVSEA-2MS-402 F12, and Mr. J. R. Quartarone, NUSC 36112.

The assistance of Mr. R. G. Lampo in the preliminary work on this project is acknowledged.

Dr. R. Quattrone is Chief of EM. COL Louis J. Circeo is Commander and Director of CERL, and Dr. L. R. Shaffer is Technical Director.



	CONTENTS
	mp monst 1/70
	DD FORM 1473 FOREWORD LIST OF TABLES AND FIGURES
1	INTRODUCTION Background Objectives Approach
2	MATERIAL SELECTION AND PREPARATION OF TEST SPECIMENS
3	TEST METHODS
4	TEST RESULTS
5	CONCLUSIONS
6	RECOMMENDATIONS
	REFERENCES
	METRIC CONVERSIONS
	APPENDIX A: Gas Chromatographic and Infrared Spectrum Analyses APPENDIX B: Additional Vendor Information
	DISTRIBUTION

是这个人,也是是一个人的,他们也是一个人的,也是一个人的,他们也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的, 第一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个人的,也是一个

TABLES

Mumber		Page
1	Application of the Coatings	15
2	Mean Coating Thicknesses	19
3	Characterization Test Results	29
4	Physical Test Results	32
5	Corrosion Resistance of Specimens During 90-Day Immersion	44
	FIGURES	
1	Solderless Terminal	20
2	Assembly of Galvanically Coupled Specimen	21
3	Scribe Lines	21
4	Location of Pre-immersion Points	22
5	Specimen Corroded at 40 in1b Impact Point	23
6	Specimen Uncorroded After 90-Day Immersion	23
7	Eleganeter Adhesion Tester .	26
8	Scrape Adhesion Tester	26
9	Gardner Impact Tester	27
10	Elcometer Adhesion	36
11	Scrape Adhesion	36
12	Impact, 23°C	36
13	Impact, 40°C	36
14	Elcometer Adhesion Test Results of Task I Urethane Coatings	39
15	Scrape Adhesion Test Results of Task I Urethane Coatings	39
16	Elcometer Adhesion Test Results of Task II Coatings in Four Immersion Tests	41
15	A A.B	61

FIGURES (Cont'd)

Humber			Page
18	Impact at 4°C Test Results of	Task II Coatings	42
19	Specimens After 90-Day Immers	ion	46
20	Bare Aluminum After 90-Day Im	mersion in Seawater	49
21	Hardcoat Anodized Dichromate After 90-Day Immersion in Sea		49
22	Hardcoat Anodized Unsealed Al Immersion in Seawater	uminum After 90-Day	50
23	Chromate Conversion Coated Al Immersion in Seawater	ominum After 90-Day	50
24	Bare Aluminum After 90-Day Im 50 Percent Otto Fuel	mersion in 50 Percent Seawater/	54
25	Hardcoat Anodized Dichromate Immersion in 50 Percent Seava		54
26	Hardcoat Anodized Unsealed Al in 50 Percent Seawater/50 Per	luminum After 90-Day Immersion reent Otto Fuel	55
27	Chromate Conversion Coated Al in 50 Percent Seawater/JO Per	luminum After 90-Day Immersion ccent Otto Fuel	55
A1	Gas Chromotogram: MIL-P-2444	l Formula 158 Primer	62
A2	Gas Chromatogram: MIL-P-2444	il Formula 152 Topcoat	63
A3	Gas Chromatogram: MIL-C-4556	5 Primer	64
24	Gas Chromatogram: HIL-C-4556	5 Topcost	65
A5	Gas Chromatogram: Deft MIL-	P-23377	66
A6	Gas Chromatogram: MIL-C-227	50	67
A7	Gas Chromatogram: Steelcote	100 Percent Solids Epoxy	68
A8	Gas Chromatogram: Americat	86 Primer	69
A9	Gas Chromatogram: Amercost	6 Thinner	7(
A16	Gas Chromatogram: Amercoat	99HS Topcost	7.
A11	Gas Chromatogram: Americat	9 Thinner	72
A12	Gas Chromatogram: Bughson N	S 3236-26 Wash Primer	7:

FIGURES (Cont'd)

Number			Page
A13	Gas Chromatogram:	Hughson TS 3236-23 Topcoat	74
A14	Gas Chromatogram:	MIL-C-83286	75
A15	Gas Chromatogram:	Irathane 155	76
A16	Gas Chromatogram:	BMS-10-11K	77
A17	Gas Chromatogram:	MIL-T-81772/AS Thinner	78
A18	Gas Chromatogram:	Solvent Used for Preparing Samples - Pentane	79
A19	Infrared Analysis:	MIL-P-24441 Primer, Component A	80
A20	Infrared Analysis:	MIL-P-24441 Primer, Component B	81
A21	Infrared Analysis:	MIL-P-24441 Topcoat, Component A	82
A22	Infrared Analysis:	MIL-P-24441 Topcoat, Component B	83
A23	Infrared Analysis:	MIL-C-4556 Primer, Component A	84
À24	Infrared Analysis:	MIL-C-4556 Primer, Component B	85
A25	Infrared Analysis:	MIL-C-4556 Topcoat, Component A	86
A26	Infrared Analysis:	MIL-C-4556 Top coat, Component B	87
A27	Infrared Analysis:	MIL-P-23377, Component A	88
A28	Infrared Analysis:	MIL-P-23377, Component B	89
A29	Infrared Analysis:	MIL-C-22750, Component A	90
A30	Infrared Analysis:	MIL-C-22750, Component B	91
A31	Infrared Analysis: Component A	Steelcote 100 Percent Solids Epoxy,	92
A32	Infrared Auglysis: Component B	Steelcote 100 Percent Solids Epoxy,	93
A33	Infrared Analysis:	Americat 86, Liquid, Pigment Removed	94
A34	Infrared Analysis:	Amercour 6 Thinner	95
A35	Infrared Analysis:	: Amercoat 99HS, Liquid, Pigment Removed	96
A36	Infrared Analysis:	: Amercoat 9 thinner	97
A37	Infrared Analysis:	: Hughson TS 3236-26 Wash Primer, Component A	98

FIGURES (Cont'd)

Number		Page
A38	Infrared Analysis: Hughson TS 3236-26 Wash Primer, Component B	99
A39	Infrared Analysis: Hughson TS 3236-23 Topcoat, Component A	100
A40	Infrared Analysis: Hughson TS 3236-23 Topcoat, Component B	101
A41	Infrared Analysis: MIL-C-83286, Component I	102
A42	Infrared Analysis: MIL-C-83286, Component II	103
A43	Infrared Analysis: Irathane 155, Component A	104
A44	Infrared Analysis: Irathane 155, Component B	105
A45	Infrared Analysis: BMS-10-11K, Component A	106
A46	Infrared Analysis: BMS-10-11K, Component B	107
A47	Infrared Analysis: MIL-T-81772/AS Thinner	108
Bl	Vendor Information: MIL-P-24441	109
В2	Vendor Information: Ameron System	116
83	Wendor Information: MIL-C-4556	121

PROTECTIVE COATINGS FOR ALUMINUM TORPEDOES

1 INTRODUCTION

Background

When aluminum alloys are selected, their strength is often considered first, while the environment to which they will be exposed is a secondary consideration. In seawater, for example, the 6000 series alloys have good corresion resistance while the 7000 series alloys do not; however, the 7000 series is often used because it is stronger.

Since the Navy's MK48 torpedoes are typically manufactured with 7000 series aluminum, the exteriors must be coated to protect against corrosion caused by seawater. The internal surface of the aluminum fuel tank must also be coated. This coating must be resistant to the corrosive properties of Otto fuel (the torpedo propellant) and of any mixture of Otto fuel and seawater. Although gouging and abrasion are not a problem inside the fuel tank, the coating must be highly adherent and nonflaking because any loose particles could enter the propulsion mechanism and cause a malfunction.

The Navy is now using a proprietary elastomeric polyurethane coating on its aluminum torpedoes. Although this coating has good resistance to rough handling and corrosive environments, there are two drawbacks:

- 1. Some people are highly allergic to the isocyanate materials in urethane coatings; there is concern that the Occupational Safety and Health Administration (OSHA) may restrict the use and availability of these coatings.
- 2. The polyurethane now used is a proprietary material. If it became unavailable for any reason, it would be difficult to select an alternative coating system because there is little experience with other systems in this environment.

To address these problems, the Navy asked the U.S. Army Construction Engineering Research Laboratory (CERL) to evaluate alternative coatings for aluminum.

Objectives

A STANDARD CONTRACTOR OF THE STANDARD CONTRACTOR

The objectives of this study were to select and evaluate a very limited number of coatings and coating systems for aluminum that are resistant to mechanical handling and seawater corrosion (Task I), and to protect aluminum from corrosion in seawater and Otto fuel (Task II). Emphasis was placed on nonpolyurethane coatings. The candidate coatings were to be selected based on major differences in polymer composition and physical properties. The results are to be used for direction in developing more effective organic coatings.

Approach

Task I: Nine potentially suitable candidate coating systems for torpedo exteriors were selected for this study. These coatings were tested, evaluated, and ranked in order of effectiveness. Some proprietary coatings were evaluated, but priority in selection was given to applicable Federal or military specification materials. No specific repairability tests were included, but priority was given to organic coatings that might be easily repaired after they were damaged. To help ensure that the same paint is obtained in the future, physical and chemical tests were performed to characterize and identify the major constituents and their concentrations. Additional characterization of constituents was obtained from pertinent vendor data and material safety sheets. The testing and evaluation of the performance of the coatings exemined mechanical strength; impact, adhesion, and corrosion resistance; as well as electrical measurements of the impedance, resistance, and capacitance of the paint systems on anodized or chromate conversion pretreated 7075-T6 aluminum panels before, during, and after a 90-day immersion in serated synthetic seawater. The effect of coating thickness and/or the nature of the substrate pretreaments was determined. The presently used elastomeric polyurethane coatings and other types of polyurethanes were tested to compare their performance. The corrosion performance of unpainted specimens was also observed.

Task II: The candidate coatings for the torpedo fuel tanks were selected, tested, and evaluated. These coatings were ranked for adherence, nonflaking, and corrosion protection for anodized or chromate conversion pretreated 7075-T6 aluminum alloy specimens in seawater, Otto fuel, or a mixture of 50 percent seawater and 50 percent Otto fuel. Tests conducted include impact, adhesion, immersion, and electrical evaluations similar to those for Task I. The corrosion performance of unpainted specimens immersed in the pertinent liquids was determined.

Selection of the Coatings

To select the coatings to be evaluated, CERL searched the Federal and military paint specifications to find those appropriate for the given exposures. Epoxy primer, military specification MIL-P-23377, was used for all tested coatings (both specification and proprietary), unless a different primer was needed for a given system. Based on this search, CERL found that it would be worthwhile to evaluate the following coatings for Task I:

1. Nonurethane:

- Epoxy-polyamide
- Epoxy-polyamine
- "Flexible" epoxy
- 100 percent solids epoxy
- Vinyl.

2. Urethane:

- Currently used elastomeric system
- -- Currently used elastomeric topcoat over MIL-P-23377 primer
- Nonelastomeric urethane system
- High-build urethane system,

For Task II, it was decided to select coatings designed for fuel tank linings. All coatings chosen were epoxy materials.

The coatings selected for evaluation are discussed below. The basis for selection and the source of sample materials are given.

Task I

Nonurethane Coatings. Six different coatings were selected for this part of the study.

1. Epoxy-polyamide meeting MIL-P-24441. It was known that this specification material has excellent seawater and chemical resistance. However, CERL had to find out whether this coating has the necessary flexibility, gouge, and impact resistance. This specification is subdivided into various formulas for different topcoats and primers. Formula 158 primer was selected since it is specifically formulated to be used over aluminum and with the MIL-P-24441 top-coats.

Samples of the Formula 158 primer (yellow) were obtained from:

Matcote Company P.O. Box 10762 Houston, TX 77018

Sampl_ of the Formula 152 topcoat (white) were obtained from:

Mobil Chemical Company 901 North Greenwood Kankakee, IL 60901

2. Epoxy coating system meeting MIL-C-4556. This coating specification is really a coating system. That is, the specification covers both an epoxy-polyamide primer and an epoxy-polyamide topcoat. This system is meant for fuel tanks, and therefore has excellent chemical resistance and adhesion. Several paint manufacturers recommend this specification for both the exterior of torpedoes and the interior of the fuel tanks. This coating was evaluated for both Task I and Task II. If the performance were acceptable in both exposures, only one coating system would need to be specified for the torpedoes.

The sample for this evaluation was obtained from:

Plas Chem Coatings 6300 Bartmer Industrial Drive St. Louis, MO 63130

The primer tested was orange in color, and the topcoat was white.

- 3. "Flexible" epoxy meeting MIL-C-22750. As with most epoxy-polyamide coatings, this was expected to have good seawater and chemical resistance. The advantage of this material is that it can be made more flexible than MIL-P-24441 epoxy. Chemrex Specialty Coatings Company, El Paso, TX, prepared a sample in its laboratory. The sample was formulated to provide good flexibility and to meet Federal Standard 595 color #14062 (dark green).
- 4. A 100 percent solids epoxy coating. Steelcote Manufacturing Company, Saint Louis, MO, claims to have an epoxy coating that has: (1) the needed resistance to seaw ter corrosion, (2) an inherent flexibility and toughness, and (3) no volatile solvents. CERL tested a sample made in Steelcote's laboratory and pigmented to meet color #14062.
- 5. The MIL-P-23377 epoxy primer. This was tested at a thickness of 5 mils and without a topcost. The coating was obtained from:

Deft, Inc. 17451 Von Karman Avenue Irvine, CA 92714

This primer is yellow.

6. Vinyl coating system. Solution vinyl coatings are typically tough and flexible, and have reasonably good chemical resistance. One advantage is that they can be applied over an old vinyl coating with no intercoat adhesion problems providing the old surface is clean.

A vinyl coating system manufactured by Ameron, 201 North Berry Street, Brea, CA 92621, was selected for this study. The system includes a synthetic resin inhibitive primer, Americat 86, and a topicat, Americat 99HS. These materials are standard off-the-shelf products. The topicat is Ameron's color, medium green, which is lighter than the \$14062 color. The primer color is red oxide.

Urethane Coatings. Four different coating systems were evaluated.

- 1. Currently used urethane system. This consists of a vinyl butyral phosphoric acid wash-primer first coat (Lord, Hughson identification #TS 3236-26, yellow) and an elastomeric topcoat made from an aliphatic polyiso-cyanate and a butyl ketoxime blocked aromatic polymine (Lord, Hughson #TS 3236-23A/B, revision #1, color #14062) manufactured by Lord Corporation, Chemical Products Group, Erie, Pennsylvania 16514.
- 2. Currently used wrethane system topcoat manufactured by Lord Corp. over MIL-P-23377 primer obtained from Deft, Inc.
- 3. Nonelastomeric aliphatic urethane coating meeting military specification MIL-P-83286. This coating is a topcost material only; it was applied over MIL-P-23377 primer. A single, small sample of this coating in color #14062 could not be obtained in an acceptable time at a reasonable cost. However, the manufacturer, Deft, Inc., maintained is making the correct color should not be hard, and that the pigmentation are ference should not be a great factor in its performance properties. A sample is a white coating pigmented with titanium dioxide, conforming to MIL-P-85.
- 4. High-build elastomeric polyurethane. A yellow topcoat, Irathane 155, was applied over the MIL-P-23377 yellow primer. The topcoat was obtained from Irathane Systems, Inc., Hibbing, MN.

Task II

是一个时间,一个时间,一个时间,他们的时候,一个时间,他们的时间,一个时间,他们的时间,他们的时间,一个时间,他们的时间,他们也可以是一个时间,他们也可以是一个时间 一个时间,一个时间,一个时间,他们也是一个时间,他们也是一个时间,他们也是一个时间,他们也是一个时间,他们也是一个时间,他们也是一个时间,他们也是一个时间,他们

Three coatings were selected for this portion of the study.

- 1. Flexible epoxy-polysmide meeting MIL-C-22750. In the technical manual on Otto Fuel II, an epoxy coating meeting MIL-P-22808 is listed as an acceptable tank lining. However, MIL-P-22808 has been cancelled and replaced by MIL-C-22750. MIL-C-22750 was also evaluated as a coating for the torpedo exteriors. Chemrex supplied a sample for testing. The topcoat meets color #14062.
- 2. Epoxy coating meeting military specification MIL-C-4556. This coating might be expected to have slightly better chemical resistance than the

¹ Otto Fuel II: Safety, Storage, and Handling, NAVSEA OF 3368 Fifth Revision (Naval Sea Systems Command, 15 January 1973, Change 1, 15 May 1975).

MIL-C-22750 costing. MIL-C-4556 is a primer and a topcost system. This costing also was evaluated for torpedo exteriors. Plas Chem supplied samples of the orange primer and a white topcost formulation.

3. Amine-cured epoxy coating meeting Boeing Aircraft specification #BMS-10-11K. It was thought worthwhile to include in this study an industry specification material used for lining tanks which may contain material similar to the Otto fuel. The Boeing specification material is a readily available, conventionally pigmented coating. It is self-priming and need not be copcoated as long as the material is not exposed to sunlight. This coating was obtained as an off-the-shelf product from Deft, Inc. The coating is light green in color.

Aluminum Test Specimens

THE REPORT OF THE PARTY OF THE

All aluminum test specimens were 3 in. by 6 in. by 0.125 in. aluminum alloy 7075-T6. The panels were divided among three groups. Throughout this report, these three pretreatments will be called substrates a, b, and c:

substrate a -- 7075-T6 with a 2 (± 0.5)-mil-thick Type III, class 1, dichromate sealed, hardcoat anodizing in accordance with MIL-A-8625C, 15 January 1968 and amendment 1, 13 March 1969.

substrate b -- 7075-T6 with a 2 (± 0.5)-mil-thick Type III, class 1, unsealed, hardcoat anodizing in accordance with MIL-A-8625C, 15 January 1968 and amendment 1, 13 March 1969.

substrate c - 7075-T6 with a chromate conversion coating, class 1A, in accordance with MIL-C-5541, 30 June 1970 and amendment 2, 30 November 1972.

为人们的人的人们是一个人们的人们是一个人们的人们是一个人们的人们是一个人们的人们是一个人们是一个人们是一个人们的人们的人们是一个人们们的人们的人们的一个人们们的

The test panels were made from the same batch of stock material. All edges were deburred and rounded. A single 1/4-in. hole was drilled in each specimen centered on the 3-in. side and 1/4 in. from the edge. The panels were degreased, cleaned, and blasted on all sides and edges with silica sand to a white metal finish and a mean surface profile of approximately 1 mil before treatment. The specimens were supplied by:

The Metaspec Company P.O. Box 27707 San Antonio, TX 78227

Application of the Coatings: Techniques and Observations

All coatings in this study were applied by conventional suction-cup air spray equipment, except as noted in Table 1.

To evaluate the effect of film thickness on coating performance, almost all the nonpolyurethane coatings for Task I were applied at topcoat dry film thicknesses of 5, 10, and 15 mils. The urethane coatings were applied at a topcoat dry film thickness of 5 mils — except for the high-build urethane system, which was applied at 15 mils. The urethanes were applied over substrates a, b, and c. Successful preliminary results on the MIL-P-24441 epoxy

Table 1
Application of the Coatings

Coating	Thinner	Equipment	Pot Life	Problems
KIL-P-24441 topcoat and primer	None	Conventional	5 hours	Hene
NIL-C-4556 topcoat and primer	None	Conventional	6 hours	None
HIL-P-23377 primer	None	Conventional	8 hours	Boes not dry to a smooth finish over anodizing
HIL-C-22750	HIL-T-81772	Conventional	6 hours	Air bubbles if more than a very thin coat is applied
100% solids epoxy	None	Conventional airspray fitted with a pressure pot	1-1/2 to 2 hours	Sagging, dripping
Amercost 86 primer	Amercont 6	Conventional air- spray fitted with a pressure pot and a fine tip	Unlimited	Cobvebe
Amercoat 99HS topcoat	Amercoat 9	Conventional air- eptay fitted with a pressure pot	Unlimited	Finholes if not thinned sufficiently
Hughson wash primer	None	Conventional	8 hours	None
Hughson polyurethene topcost	None	Conventional	2 hours	None
MIL-C-83286	None	Conventional	6 hours	Air bubbles if more then a thin coat is applied
Irathane 155	None	Conventional	3 hours	None
BMS-10-11K	Mone	Conventional	8 hours	Must be applied in sultiple thin costs to avoid surface tension problems

system and the Ameron vinyl system suggested that these coatings be evaluated over all three substrates.* Other coatings in Task I were evaluated on substrate a only.

Task II coetings were applied at the thickness suggested by the manufacturer or by the military specification. These coatings were applied to all three substrates.

The techniques used to apply each coating are discussed below. This information is summarized in Table 1.

では、日本のでは、日本には、日本ので

MIL-P-24441: Both the primer and the topcoat were easily mixed and applied without thinning. Each coat was allowed to dry overnight before recoating. Each coat dried to a thickness of about 3 mils.

MIL-C-4556: Both the primer and the finish coat sprayed easily with conventional suction-cup spray. Thinning was not necessary. The primer was applied at approximately 2 mils dry film thickness. Each coat of the topcoat was about 5 mils dry film thickness. Each coat was allowed to dry overnight before recoating. The system became very hard and brittle as it cured.

MIL-P-23377: This primer was used with several different topcoats. It was applied at a thickness of 1 mil with no thinning. Some difficulty was encountered in applying the primer to the anodized aluminum panels, both with and without the dichromate sealing. These surfaces are somewhat porous, and the solvents in the primer were absorbed into the surface as the coating was applied. The primer dried with a sandy, rough surface when applied at a 1-mil thickness over anodizing. Applying a somewhat heavier coat prevented much roughness, but the coating still did not have the smooth surface that normally would be expected. There was no problem in applying this primer over the nonanodized chromate conversion coated panels.

以及公司的政策,以及公司,以及国际的政策,是国际政策的政策,是是国际政策的政策,但是国际政策的政策,是国际政策的政策,是国际政策的政策,并且国际政策的政策,是国

MIL-C-22750: This coating was very difficult to spray. When more than a mist coat was applied, air bubbles up to 1/8 in. in diameter appeared on the surface about a minute after spraying. This happened whether the coating was thinned or unthinned, or was applied on smooth metal, sandblasted metal, or over the MIL-P-23377 primer. Acceptable results were obtained only with very careful work. The coating was thinned to 18 seconds on a #4 Ford cup with the EIL-T-81772 thinner recommended in MIL-C-22750. The first coat was applied as a very thin mist and allowed to dry for 1 hour before recoating. This coating was chosen for testing in Tasks I and II. Task I required coating thicknesses of 5, 10, and 15 mils. Since the coating could only be applied in coats of less than 1 mil, it was difficult and time consuming to obtain the necessary film build. The Task II specimens were costed according to MIL-C-22750 directions with a mist coat and one more cost. The total thickness of the topcoat was 0.9 to 1.2 mils.

The 100 percent solids epoxy coating: This coating was applied using conventional spray equipment fitted with a pressure pot. A pressure of about 15 psi was applied to the pot. To apply a 5-mil coat, the coating was sprayed to give a "spattered" coat which did not cover the entire surface. Within a

^{*} Both coatings were rated highly on physical tests performed before immersion.

few seconds this coat flowed together smoothly and uniformly. The coating has some tendency to sag and drip, even at 5 mils. It was not possible to spray the panels at a thickness of less than 5 mils. Each coat was allowed to cure overnight before recoating.

Ameron 86 and Ameron 99HS: The primer, Amercoat 86, was thinned to 25 seconds on the #2 Zahn cup with Amercoat 6 thinner. It was difficult to get good atomization of this paint with conventional spray equipment. The best results were obtained using the pressure pot and a fine atomizing tip on the spray gum. Two fast passes of the spray gum gave an even coat about 1.5 mils thick. The first pass was allowed to dry a few minutes before the second coat was sprayed on. The primer was messy to apply; during spraying, semidry paint particles and cobwebs filled the air. The topcoat was thinned to 90 seconds on the #2 Zahn cup; about one part paint was mixed with one part thinner. Without this much thinning, the coating had many pinholes. Each coat dried to a thickness of about 1 mil. The topcoat dried rather quickly, so several coats could be applied with only a few minutes' drying time between coats. The topcoat dried to a very dull finish.

Hughson TS 3236-26 and TS 3236-23: Both the wash primer and the topcoat were easy to apply; mixing and spraying presented no particular problems. The wash primer was applied in one thin cost and dried quickly. The topcoat was easily applied over both the wash primer and the MIL-P-23377 epoxy primer. A film build of 5 mils was achieved by applying six costs with a few minutes drying time between each coat.

MIL-C-83286: No thinning was necessary when applying this polyurethane coating. The first coat had to be a very thin mist coat, otherwise, bubbles formed in the coating. The mist coat was allowed to dry for about 1 hour before recoating. A third coat was applied after overnight drying to give a 5-mil dry film thickness. Many of the panels had pinholes, but these flaws did not appear to go through all coats. There were no pinholes in the MIL-P-23377 primer.

是一个人,我们就是一个人的,我们就是一个人的人,他们就是一个人的人,他们就是一个人的人,他们就是一个人的人,也可以是一个人的人,也可以是一个人的人,也可以是一个人 第一个人的人,也可以是一个人的人,也可以是一个人的人,也可以是一个人的人,也可以是一个人的人,也可以是一个人的人,也可以是一个人的人,也可以是一个人的人,也可以是

Irathane 155: There were no particular problems with either mixing or spraying. No thinning was required. A dry film thickness of 4 to 5 mils was applied for each coat.

EMS-10-11K: This coating was easy to apply with no thinning; as recommended, no primer was used. Two thin coats were applied to give a diagram thickness of about 1 mil. When one heavier coat was applied, surface insion gave the coating an alligator-skin appearance.

Preparation of the Panels for Immersion

Thickness Measurements

AND THE STATE OF THE PROPERTY OF THE PROPERTY

The thickness of the coating on each panel was determined by measuring the total thickness of the coated panel, then subtracting the thickness of the uncoated panel, and dividing by two to get the coating thickness on each side. The measurements were made using a gauge calibrated in mils. The gauge was bolted to a stationary support. The movable disl was rotated to read zero thickness for an uncoated panel. The disl was recalibrated for each substrate

(anodized sealed, unsealed, and chromate conversion coated). This method of measuring total coating thickness assumes that each uncoated panel is the same thickness, and that the film on one side of the panel is the same thickness as that on the other side. The thicknesses of several uncoated panels were measured; the differences between them were minimal. Three measurements were recorded for each panel, about 1 in. from the long edge at the total middle, and bottom of the panel. The number of panels per test and the panels thickness measurement values are included in Table 2. It was different in coating the coatings at the exact film thicknesses desired. The panels in coating thicknesses were normally less than 1.5 to 2.0 mils.

Preparation of Panele for Electrical Measurements

To attach electrical leads to a specimen, part of the coatia; and anodizing was removed at the top of each panel. A steel template with a 1/2-in.— dismeter hole at the top was placed over the panel, and the coating was removed by sandblasting. This technique removed the coating from a small area without damaging the rest of the panel. A 1/8-in. hole was drilled in the center of the clean area, and a solderless terminal was riveted in place (Figure 1). Before it was attached, the terminal was dipped in a conductive silver paint. The bare metal areas were then covered with silicone sealant to protect the connection from the corrosive seawater and Otto fuel.

Galvanically Coupled Panels

THE REPORT OF THE PARTY OF THE

では、これでは、10mmのでは、10mm

The state of the state of

Each of the coated specimens in this phase of the testing was galvanically coupled to two brass panels of the same size as the specimen. Leads were soldered to the brass panels; a longer lead coupled one brass panel to the coated panel. Each coated panel was sandwiched between the two brass panels and bolted together using nylon nuts, tolts, and washers (Figure 2). Four washers were inserted between each panel to provide 1/8-in. spacing. The leads from the brass and coated panel were cut to 6 in.; the ends were stripped, twisted together, and soldered. The assembled panels were suspended in the tanks with the coupled ends of the wires well above the surface of the immersion liquid. These panels did not require electrical measurements and did not have to be disassembled satil the testing was completed. The length of the wires allowed the panels to be twisted apart enough to observe the condition and appearance of the costing during immersion.

間ではないでは、100mmのでは、100mmのは、100mmのでは、100

Scored Specimens

Some of the coated specimens were scored with a diamond-tipped cutting tool. Two parallel 3-1/2-in.-long scribe lines were cut 1 in. spart on each face of the panel (Figure 3). The top of each scribe line was 1 in. from the top edge of the panel. On each panel, the left-hand scribe line was cut through to bare metal; the right-hand scribe line was cut through all layers of the coating to the anodizing.

Table 2
Mean Coating Thicknesses

Coating	šubstrate	Intended Thickness (mils)	f of Panels	Mean Thickness (mils)	Standard Deviation	
		Tsek 1: No	nurethese			
					······································	
HIL-P-24441		6	16	5.4	0.75	
SYET		11	16	10.9	1.01	
MIL-7-24441		16	16	14-0	1.29	
	ь	*	16	5-7	0-86	
	ь	žΙ	16	10.4	1-18	
	<u>,</u>	16	3.6	14.5	1.25	
	č	6	16	5.0	0-56	
	ē	11	16	9.5	0.83	
	č	16	16	13.1	2.04	
MIL-C-4556	4	6	16	6.0	0.70	
OAGL	4	11	16	10.5	1.07	
HIL-C-4556	_	15	16	10.6	1.19	
UTD_0-4334	•		10			
MIL~C-22750		6	16	4.2	0-57	
OVET	2	11	16	8.4	0-74	
HIL-P-23377		16	16	12-4	0.40	
100% Solide		6	16	5.7	G.93	
OYET		11	16	5.5	0.65	
HIL-P-23377	2	16	15	16-3	1.64	
HIL-F-23377	æ	6	16	6.6	0.59	
	ь	6	16	5.4	0.60	
	è	6	16	₹-1	0-65	
Americant 9985	å	6	16	5.4	0.82	
9465		11	16	5.7	0.69	
Americant 86		16	16	15.4	1.13	
	Ē	6	16	7.4	0.96	
	b	11	16	12.5	0.95	
	b	16	16	18-0	1.07	
		6	16	8.3	0.80	
	¢	11	16	12.7	0.81	
	e c	16	16	21-9	1.75	
		Teak I:	Urethenes			
		•	14	7.3	0.54	
Mughson		6	16		0.64	
TS 3236-23	Ъ	6	16	8.2		
over TS 3236-26	c	6	16	8.0	0-51	
Hughtea		6	16	4.1	0-41	
TS 2236-23	, b	5	16	4.9	0.45	
	č	6	16	4.5	0.55	
over NIL-P-23377	c	v	••		*	
Irethane 155		16	16	13.7	2.58	
DARE 133	5	16	16	18.4	2.17	

Table 2 (Cont'd)

Costing	Substrate	intended # of Mean Thickness (mils) Fanels Thickness (mile		Standard Deviation		
		Tael	k II	**************************************	7.00	
H1L-C-22750	a b	2 2	26 26	2.2 3.4	0-58 0-51	
MIL-F-23377	c	2	26	2.8	0.56	
MIL-C-4556 over	5 b	9 9	26 26	8.6 8.6	1.36 1.54	
MIL-C-4556	¢	•	26	7.1	0.98	
BMS-19-11K	å 6	1 1 1	26 26 26	1.2 2.2 2.0	0.50 0.46 0.61	




Figure 1. Solderless terminal.




Figure 2. Assembly of galvanically coupled specimen.

AND THE PROPERTY OF THE PROPER



Figure 3. Scribe lines.

Some of the coated specimens were impacted before immersion. This was dene with a Gardner Heavy-Duty Variable Impact Tester. Four points in predetermined locations on each panel were impacted with forces of 5, 10, 20, and 40 in.—1b as shown in Figure 4. Since most coatings fail in the range of 5 to 40 in.—1b, each panel had at least one actual coating failure among the four points of impact. Figure 5 shows a specimen which corroded only at the point which was impacted with a force of 40 in.—1b. The specimen was galvanically coupled and immersed in seawater for 90 days.

Undamaged Specimens

Some of the specimens were not damaged prior to immersion. Figure 6 shows a specimen coated with MIL-P-24441 which did not visibly corrode during 90-day immersion in seawater. The specimen was galvanically coupled.




Figure 4. Location of pre-immersion points.




Figure 5. Specimen corroded at 40 in.-1b impact point.




Figure 6. Specimen uncorroded after 90-day immersion.

3 test methods

More than 900 aluminum panels were coated and tested. Most of the specimens were immersed for 90 days in seawater, Otto fuel, or a mixture of the two. Some specimens were damaged before immersion by impact or by score lines cut into the coating surface. Some of the damaged and undamaged test specimens were galvanically coupled to 60/40 bronze during the immersion period to accelerate the corrosion processes. Electrical measurements of resistance, capacitance, and loss factor at 1 kHz were made on 250 panels weekly during the 90-day immersion period. After the immersion period, each panel was examined to evaluate its condition. The results of the electrical measurements were tabulated, and the resistance and capacitance were plotted versus time of immersion. These plots were not found to give valuable information about the deterioration of the coatings within the 90-day immersion period. The results were not used because the data indicated the immersion time was too short to provide useful information.

Four destructive physical tests were performed on the specimens after immersion and on those specimens that were not immersed:

- 1. Elcometer adhesion test
- 2. Scrape adhesion test
- 3. Impact at room temperature (23°C)
- 4. Impact at 4°C.

STATE OF THE PROPERTY OF THE P

Characterization tests were performed on each coating to provide a basis for comparing any batches of that coating procured by the Havy or CERL in the future with the samples already evaluated by CERL. The pigment content, total solids, and nonvolatile vehicle content of each coating were measured, and infrared and gas chromatographic analyses were performed.

Physical Test Procedures

Elcometer Adhesion Test

Originally, the adhesion of the coatings was to be tested using a tape adhesion method. For this test, two parallel cuts, 1/8 in. spart, and a third line perpendicular to the other two are cut into the coating. A piece of masking tape is firmly placed over the score lines and then peeled back to remove the coating. However, this test was shown to be ineffective because it would not remove many coatings. Therefore, CERL substituted the Elcometer Adhesion Tester. The test method involved using an epoxy glue to cement circular aluminum dollies to the coated surface. The dollies were lightly sand-blasted on the contact surface to ensure good adhesion of the glue. The paint surface was also slightly roughened with sandpaper. Weights were placed on the dollies while the glue was curing. All specimens were allowed to cure overnight. A l-in. hole saw attached to an electric hand drill was used to cut through the coating around the dolly. The dolly could then be pulled from the specimen with the adhesion tester, and the force at which the dolly was

pulled from the specimen was read in units of pounds per square inch. On most specimens, the dolly pulled all or part of the paint system from the pauel. However, on some of the strongest coatings, the epoxy glue broke before the paint system, and the paint was left intact. The adhesion tester had a range of 0 to 1000 psi; the glue typically broke at 700 to 900 psi. Thus, this test did not distinguish between the highly adherent coatings, but it did indicate coatings with poor adhesion. One drawback of this test method is that the solvents in the glue might affect the characteristics of the coating system. For most coatings in this study, solvents would not be expected to have much effect because two-component cured coatings usually are solvent-resistant; however, the solution vinyl coating by Ameron is not. Thus, the Elcometer adhesion test may give false low readings for this coating in particular. Figure 7 is a photo of the test equipment after a test was performed.

Scrape Adhesion Test

A scrape adhesion test was performed with a balanced-beam scrape adhesion tester in accordance with American Society for Testing and Materials (ASTM) D 2197-68, Method A.²

ASTM D 2197-68A does not clearly state when the test should end; successively larger loads are to be used until the coating is removed or until the maximum load of 10 kg has been added. It is unclear whether the endpoint is the removal of the entire coating system from the substrate, or the removal of a portion of the topcoat from the surface. For the purposes of this testing, removal of any part of the coating constituted failure. (If the endpoint were removal of the entire coating system, many of the coatings would have exceeded the 10-kg limit of the apparatus.) The load was determined only to the nearest 0.5 kg because tests at smaller weight increments were not reproducible. The equipment at the conclusion of a test is shown in Figure 8.

Impact Test

THE REPORT OF THE PARTY OF THE

An impact test was performed in accordance with ASTM D 2794-69.3 The test was performed at a room temperature of $25 \pm 1^{\circ}$ C, and again on specimens cooled to $4 \pm 3^{\circ}$ C for 1 hour. The test was done on a Gardner Heavy-Duty Variable Impact Tester. A specimen was set over a 0.640-in.-diameter hole in a die mounted on the base of the apparatus. A spherical tipped punch of 0.625-in. diameter was placed on the specimen. A 2-1b weight was raised to a desired height (up to 40 in.) in a graduated tube; this weight delivered a maximum force of 80 in.-1b. The equipment is shown in Figure 9.

According to the test method, cracking of the coating constitutes impact failure. However, since some of the coatings in this study are so elastic that they will not crack, the endpoint was chosen as any of the following types of failur: cracking on the impacted side, cracking on the reverse side, puncture of the topcoat, and debonding ("blistering") of the impact area.

^{2 &}quot;Standard Test Methods for Adhesion of Organic Coatings," D 2197 (American Society for Testing and Materials [ASTM], 1968).

^{3 &}quot;Resistance of Organic Coatings to the Effects of Rapid Deformation (Impact)," D 2794 (ASTN, 1969).



Figure 7. Elcometer adhesion tester.




Figure 8. Scrape adhesion tester.





Figure 9. Gardner impact tester.

Electrical Measurements

It was originally thought that studying the resistance and capacitance properties of the coated aluminum specimens during immersion in seawater would yield valuable information about the deterioration of such specimens. The test method was based on previous studies of the electrical properties of polybutadiene coatings on steel. However, the test method did not give useful results for the coatings tested. A piece of stainless steel the same size and shape as the test specimen was used as a reference electrode. The distance between the reference electrode and the test specimen being measured was kept constant with three nylon screws set into the face of the reference electrode. Capacitance and impedance measurements were made with a General Radio Type 1600-A Impedance Bridge at a frequency of 1000 Hz. To prevent any errors caused by changes in the level of the immersion fluid, both the sample and the reference electrode were completely immersed. Measurements were made on each panel daily for the first 3 days, and then weekly for the rest of the 90-day testing period. It was expected that after a time the measured resistance between the specimen and electrode would drop sharply as the coating on the specimen deteriorated. The capacitance between the two would begin to rise at the same time. The data for this series of experiments did not show the



とは、とうごうののです。 見をする とびないがた かいたのでは 自然 きんどうどう 神動した なうになる 無難 だっさいかい 蘇 取るりこれ ア

-.*

以外一個人 的人的人

Figure 9. Gardner impact tester.

Electrical Measurements

It was originally thought that studying the resistance and capacitance properties of the coated aluminum specimens during immersion in seawater would yield valuable information about the deterioration of such specimens. The test method was based on previous studies of the electrical properties of polybutadiene coatings on steel. However, the test method did not give useful results for the coatings tested. A piece of stainless steel the same size and shape as the test specimen was used as a reference electrode. The distance between the reference electrode and the test specimen being measured was kept constant with three nylon screws set into the face of the reference electrode. Capacitance and impedance measurements were made with a General Radio Type 1600-A Impedance Bridge at a frequency of 1000 Hz. To prevent any errors caused by changes in the level of the immersion fluid, both the sample and the reference electrode were completely immersed. Measurements were made on each panel daily for the first 3 days, and then weekly for the rest of the 90-day testing period. It was expected that after a time the measured resistance between the specimen and electrode would drop sharply as the coating on the specimen deteriorated. The capacitance between the two would begin to rise at the same time. The data for this series of experiments did not show the

expected trends. There were no significant increases or decreases in the values recorded during the 90-day testing period, even when there were visible areas of corrosion or coating deterioration on the specimens. Initial measurements of capacitance ranged from 0.2 to 5 microfarads. Initial measurements of resistance ranged from 10 to 250 ohms. The highest initial resistance values were for the MIL-P-4556 epoxy system. However, there did not appear to be a strong correlation between coating performance and electrical measurements. A 90-day immersion probably is not long enough to show significant changes in the electrical properties of the coated aluminum.

Characterization of the Coatings

To characterize each sample of paint tested for this study, the pigment content, total solids, and nonvolatile vehicle content of each coating component were measured (Table 3). An infrared spectrum (IR) and a gas chromatographic (GC) analysis of each coating were done to "fingerprint" the samples evaluated in the laboratory. The results of the IR and GC work are shown in Appendix A. The laboratory procedures used are described below. Additional vendor information and safety sheets for the MIL-P-24441, Ameron, and MIL-P-4556 systems are included in Appendix B.

Test Methods

1. Pigment content (Federal Test Method Std. No. 141B, Method 4021, 1 February 1979).

Apparatus: IEC International Centrifuge, Size 2, Model K, 8-unit head. Sartorius Analytical Balance.

Extraction mixture: 50 percent toluene, 50 percent acetone.

Procedure: In a weighed centrifuge tube, approximately 15 g of the sample (coating or coating component) were weighed to the nearest 0.0001 g. Twenty-five milliliters of the extraction mixture were added and mixed thoroughly with a glass rod. The rod was washed with more of the mixture from a wash bottle. The material was centrifuged 30 minutes at 2000 rpm, and the clear supernatant liquid was decanted. These steps were done twice more with 35 ml of the extraction mixture. After the liquid was drawn off for the last time, the tube was set in a steam bath for 10 minutes, put in a 105°C oven overnight, cooled in a dessicator, and weighed. The percentage of pigment was calculated.

2. Total solids

Apparatus: Sartorius Analytical Balance, Aluminum Evaporation Dishes.

Procedure: Into 2 weighed evaporating dish, approximately 0.5 g of the sample was added and quickly weighed to the nearest 0.0001 g; the dish was put in a 105° C oven for 1-1/2 hours, cooled, and weighed. The percentage of total solids, by weight, was calculated.

Table 3
Characterization Test Results

Coating	Component	Total Solids, Percent	Pigment, Percent	Nonvolatile Vehicle, Percent
MIL-P-24441	A	73.3	50.6	46.0
Formula 158	В	76.7	29.3	67.0
MIL-P-24441	A	68.8	50.9	36.5
Formula 152	В	70.8	27.7	59.6
MIL-P-23377	A	63.7	40.3	39.2
	В	20.5	0.0*	20.5
MIL-C-22750	A	70.8	5 - 8	69.0
	В	47.2	9.3	41.8
MIL-C-4556	A	68.1	48.4	38.2
Primer	В	82.5	0.0	82.5
MIL-C-4556	A	59.4	33.9	38.6
Topcoat	В	62.5	0.0	62.5
Steelcote	A	96.4	0.0	96.4
100% Solids	В	97.1	23.7	96.2
Ameron 86	*	33.3	17.8	18.9
Ameron 99HS	*	67.4	36.4	48.7
TS3236-26	A	32.9	15.7	20.4
Wash Primer	В	1.7	0.0	1.7
TS3236-23	A	64.6	4.4	63.0
Topcoat	В	16.1	0.0	16.1
MIL-C-83286	A	65.7	32.7	49.0
	В	34.1	0.0	34.1
Irathane 155	A	74.0	4.8	72.7
	В	17.6	0.0	17.6
BMS-10-11K	A	63.5	45.1	33.5
	В	1.7	0.0	1.7

^{*}Not applicable.

3. Nonvolatile vehicle content (Federal Test Method Std. No. 141B, Method No. 4053, I February 1980). This method was used to calculate the non-volatile vehicle (NVV) content from the sum of volatile matter and the pigment solids content:

$$2 \text{ NVV} = \frac{2 \text{ total solids} - 2 \text{ pigment}}{100 - 2 \text{ pigment}} \times 100$$

4. Gas chromatographic analysis. A gas chromatogram of each mixed coating (as a liquid before curing) and of each thinner was prepared using the following apparatus and conditions:

Instrument: Hewlett-Packard model 5880A
Detector: Thermal conductivity detector

Column: Carbowax 1500, 10 ft

Carrier gas: Helium

調がいいとは、一般などのなど、一般などのなどは、一般などのなどは、一般などのなどのでは、一般などのなどのでは、一般などのなどのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、

では、100mmので

Oven temperature profile: Initial value = 80°C

Initial time = 3.00 minutes

Temperature increase rate = 200/minute

Final value = 249°C Final time = 7.50 min.

Detector temperature: 225°C Injector temperature: 225°C Sample size: 2.5 µl

Sample preparation: Approximately 0.5 ml of the mixed sample was thoroughly mixed with 3 ml of clean pentane in a test tube. The sample was centrifuged at high speed for 10 minutes to remove the resins, pigments, and other nonvolatiles from the solution. A sample of the top layer of the solution was drawn with a syringe and injected into the chromatograph. The gas chromatographic analyses are shown in Appendix A.

5. Infrared analysis. For future reference, infrared spectra were taken of (1) the uncured coating vehicles and (2) the thinners used for their application. The spectra were recorded from 4000 to 200 cm⁻¹ on a Perkin Elmer 283B infrared spectrophotometer equipped with an accessory infrared data station.

The clear liquid vehicles and thinners were analyzed in a demountable liquid cell with potassium bromide windows and a 0.010-mm Teflon spacer. Pigmented materials were centrifuged for 5 minutes in a Sharples Super Centrifuge Model #T-41-24 to obtain a vehicle suitable for infrared transmission analysis. Except for removal of the pigments, the vehicles were not altered. The instrumental settings were as follows:

Scan time — 12 minutes
Slit program — normal
Response — 1
Ordinate expansion — 1
Abscissa expansion — 1
Suppression — on.

The infrared analyses are shown in Appendix A.

4 TEST RESULTS

This chapter presents and discusses the physical performance of unpainted and painted specimens before and after immersion in selected liquids, as well as corrosion resistance of each coating during the testing. It includes tabular summaries, general comments, observations, and statistical analyses. Care must be taken when comparing coatings of different types because there were different modes of failure. For example, in the Elcometer adhesion test, some coating systems broke cleanly from the substrate, while other coatings broke between the primer and the topcoat. In the impact tests, some flexible coatings, such as Irathane 155, failed when the topcoat was punctured. Brittle coatings, such as MIL-C-4556, usually failed when the coating cracked at the impact point. It seems acceptable to compare similar coatings when they are applied over the same coating, or over different substrates.

Physical Tests

Tabular Summary - Tasks I and II

Table 4 summarizes the results of the four different tests done on each specimen tested in Tasks I and II.

General Comments

別語では、他のないのは、一般のないのでは、これに対している。これに対している。「はないないない」というないのでは、これには、これにはないのでは、これにはないない。これには、これに対している。これには、これに対している。

The results of duplicate tests have been averaged. For the Elcometer adhesion test, the units are given in hundreds of pounds per square inch. A (+) in Table 4 indicates a case in which the glue broke before the paint failed. The glue used for this experiment generally broke at 700 to 900 psi. For the scrape adhesion test, the maximum of the testing apparatus was 10 kg. Specimens which did not fail at 10 kg are marked 10+. Results of the impact tests are given for room temperature (23°C) and 4°C; units are in inch-pounds. The maximum range of the test was 80 in.~1b.

Some of the physical test data were analyzed for significant differences by using analysis of variance techniques. Pertinent averages of test results for the various costings, various thicknesses, and various substrates were compared; the effect of immersion was also evaluated. Interactions among these factors were examined. Tests of significance were conducted at the 0.05 level (i.e., it is 95 percent certain that the differences observed were significant). To simplify the task, only the two best of the five epoxy coatings in Task I were evaluated by this method. The Ameron vinyl system, all of the urethane systems, and all of the Task II candidate coatings were also evaluated.

Performance - Task I: Nonpolyurethane-Coated Specimens - Observations and Statistical Analyses

1. MIL-P-24441 and MIL-C-4556 Systems. A statistical analysis was performed on the physical test data of these two epoxy-polyamide coating systems. The MIL-P-24441 primer and topcoat system was compared with the MIL-C-4556 system for 5-, 10-, and 15-mil thicknesses, and immersed versus not immersed for substrate a. Of the five epoxy systems tested in Task I, these two were

Table 4
Physical Test Results

System	Thicknors (mils)	Sub- strate*	Immersion (Yes, No)	Ad	ometer hesion eat**	Scrape Adhesion Test ⁴⁸⁸	Impact Test (23°C)	Impect Test (4°C)	Inpect Failuse Type
		··	Ta	ek Z:	Honurethe	nes			····
MIL-P-24441	5	8	N	+	XA	10+	20	26	Crack
OVOE	ś	4	Ÿ	8.3	Primer	10+	32	28	(all
NIL-2-24441	10	ī	ģ	+	NA.	30+	24	28	specimens)
	10		1	÷	NA	10+	33	23	,,,,,,,
	15		¥	+	KA	10+	22	22	
	15		r	+	XA	10+	26	23	
	5	ь	k	+	MA	10+	28	28	
	5	5	Y	7.7	Primer	16+	39	27	
	10	5	K	_+.	XA.	10+	36	26	
	10). b	Y M	8.5 +	Primer	10+ 10+	29 26	25 20	
	15 15	b	Ÿ	+	XA XA	10+	26 31	20	
	.,	É	H	¥	AA	10+	24	20	
	ś	ċ	7	+	XA.	10+	21	24	
	ıć	č	ż		KA	16+	22	28	
	10	č	Ť	+	MA	10+	25	21	
	15	c	ĸ	+	AE	10+	26	22	
	15	c	Y	+	MA	10+	27	19	
HIL-C-4556	5	4	g	5.5	Topcost	10+	24	58	Crack
1940	5		Y	6-8	-	10+	21	27	(=1)
MIL-C-4556	10	e	×	6.4	-	10+	24	24	spēcimens)
	10	*	Y	7.2	_	104	27	39	
	15 15	4	n T	4.1 5.5	•	10+ 10+	34 11	30 2 9	
MIL-C-22750	5	_	×	2.5	Primer	7.3	6	3	Debond
	5	•	Ÿ	1.7	LLYBER	7.5 7.6	16	10	between
over HEL-P-2337?	10		× ,	1.5	-	7.0	20	10	primer and
1166-1-23313	10	Ā	Ÿ	1.4	-	7.6	7	8	Lopcost
	15		ä	0.3	•	10+	18	12	coptone
	15	A	Y	C.5	-	7.5	9	8	
1002 solide	5	4	ø	+	NA.	5.0	10	4	Deboad
1940	3		Y	7.3	Primer	7.0	5	4	between
HIL-P-23377	10		Ħ	+	NA	9.0	4	6	primer and
	10	•	Ţ	9.0	friner	8.1	4	. 4	Topcoat
	15	*	×	5.5		6.1	ze	14	(41)
KIL-P-23377	15 5	4	Y #	6.9 1.0	Priser	3.3 10+	8 10	8 6	apecimens) Debond
ETT-1 The	ś	ì	Ÿ	2.9		10+	10	8	between
	3	b	ĸ	5.3	•	10+	6	14	primer and
	5	ь	Ť	8.2	-	10+	10	11	topcoat
	5	c	p	+	XA	10+	26	12	(all
	\$	c	Y	*	AM	19+	18	32	specimens)
Americant 99HS	5		×	2.6	Primer	10+	12	14	Puncture
ovet	. 5	e	Y	2.3	Topcost	10-	14	13	(all
Americant 86	10	*	7	2.2	Priner	104	14	18	epecimens)
	10	•	H Å		Topcost	10+	15	19	
	15 15	•	7	2.4 2.3	Prizer Prizer	10+ 10+	32 29	30 33	
	· ;	\$ 5	N N	2.2		10+	12	14	
	ś	6	Ť	2.2		10+	10	20	
	ιó	ь	×	2.5		10+	16	22	
	is	h	Ť		Topcoat	19+	19	79	
	15	ь	K	2.4		8.0	34	48	
	15	ь	4		Priser	8.9	32	52	
	5	c	×	3-1		10+	12	24	
	5	c	Y		Topcost	10+	13	40	
	10	c	N		Topcost	10+	20	36	
	10	c	Y		Torcost	10+	20	33	
	15	c .	N	1.6	Primer	8-5	38	SC	
	15	c	r	2.0	Priper	6.0	41	55	

Table 4 (Cont'd)

System	Thickness (ails)	Sub- attace*	Immeratos (Yes, No)		icometer Wheelon Test**	Scrape Adhesion Test**	Test (23°C)	Impact Test (4°C)	ispact Failure Type
				Teek 1	: Urethan	15			
				, ,				_	
llughaon polyurethane	5 5	•	F Y	4.3 5.4	Priser	10+ 10+	20 . 50	5 7	Puscture (ali
bothersaue	\$	a b	'n	2.6	-	10+	49	á	specimens)
Hughson	5	ь	Ÿ	7.6	•	10+	56	9	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
vash priser	5	c	*	+	KA	10+	80	10	
	5	c	Y	9.4	Primer	10+	60	10	
Hughson	5	a	ĸ			10+	22	12	Puncture
polyuret <u>d</u> anc	5	4	Ÿ	3.6	Prizer	10+	50	17	(all
over	5	b	×	1.1	-	10+	16	8	specimens)
MIL-P-233//	3	ь	Ť	4-1		10+	49	16	
	5 5	ç	¥ Y	+	XA	10+	18	24	
	,	c	•	+	XA	104	76	60	
HIL-P-83286	3	£	*	2.6	friner	7-5	6	2	Debond between
over	5		Y	2.6	-	4.0	5	4	primer and
HIL-P-23377	5 5	b b	# Y	2.9 5.4	_	8.5 5.8	6 3	6	topcoat
	5	c	; X). -	NA	3.8 10+	24	3 28	(all specimens)
	ś	č	Î	*	AX AX	9.6	8	8	
		-					_		
Isathano 155	15		×	+	MA	30	40	50	Tuncture
OA\$L	15		Y	9.6	Topcoat	₹.1	21	28	(all specimens)
MIL-P-23377	15	b	¥	*	NA.	5.0	12	10	
	15	b	¥	8.6	ft iper	5-1	18	20	
	15 15	c c	¥ T	÷	XA XA	5.0 5.2	14 15	12 13	
				·					
	· · · · · · · · · · · · · · · · · · ·			7	ask II				
MIL-C-22750	2		None	9.1	friner	10+		4	Dahard
946L	2	•	Sratester	0.7		7.0	6	- 1	Debond st
H11-P-23377	ž		Fuel	0.8	•	6.0	š	3	primer and
	2	a .	30/30	0.3	-	6.0	Ž.		Sopcoat
	2	ь	Mone	0.3	-	3.5	2	2	(all specimens)
	2	ь	Seawater	2.4	-	7.7	ě	5	,,
	2	5	Feel	0.9	-	5.9	2	3	
	2	ь	50/30	0.5	-	5-1	4	4	
	2	c	None	*	XÀ	10+	28	62	
	. 2	c	Seguster		MA	10+	38	67	
	2 2	e e	Fuel 30/50	+	ar An	10+ 10+	25 12	62 65	
							-		
HIL-C-4556	\$ *	*	None	*	NA *******	10+	12	14	Crack
over MIL-C-4556	8	3	Seawater	8.1	frines	10+	7	13	(All specimens)
011/25-4339	8 8	*	F2el 35/30	7.8 9.0	•	10+ 10+	7	11 7	
	8	ĥ	99/90 Fane	y.u +	NÁ	10+	10	19	
	ē	h	Seavater	2.5	frimer	10+	6	8	
	8	5	Fuel	7.7	-	100	5	ÿ	
	ğ	Þ	50/50	8.9	•	10+	6	á	
	8		Nour	4	NA	10+	A	10	
	Ė	5	Seaweter	2.6	frimer	10+	•	ii	
	-	-			* - +		•		
	8	ċ	Fuel 50/50	7.6		10+ 10+	Š	•;	

Table 4 (Cont'd)

System	Thickness (mils)	Sub- strate*	Immersion (Yes, No)	24	cometer lesion lest ^{an}	Scrape Adhesion Testess	Impact Test (2)°C)	Impact Test (4°C)	Impact Failure Type
PMS-10-11K	1		None	1.7	Topcoat	5.0	44	40	Debond
2.12 14 11	i	_ &	Seavater	1.6	* •	5.6	40	47	within
	i		fuel	1.0	-	5.3	3	9	topiosi
	1		50/50	0.8	-	3.8	5	10	layers
	1	ь	ench	1.2	-	6.5	14	16	(all specimens)
	i	b	Seaveter	1.4	-	4.8	4	9	
	1	ь	Fuel	0.7	-	5.7	3	2	
	1	ь	50/50	1.0	-	5.2	2	3	
	i	6	Non€	+	-	9.0	12	20	
	i	c	Segvater	4.9	-	7.8	26	39	
	i	ě	Tuel	6.9	-	7.5	17	24	
	1	c	50/50	5.7	-	8.3	33	38	

^{*} a = hardcost anodized dichromate scaled; b = hardcost anodized unscaled; c = chromate conversion costed.

* a "+" signifies that the glue broke before paint failed.

*** 10+ signifies that the adhesion of the coating exceeded the range of measurement of the testing apparatus.

NA -- not applicable; data not obtained.

obviously the best. Figures 10 through 13 show the data for these two coating systems.

- a. Elcometer adhesion test: no analysis performed because MIL-P-24441 was obviously better.
- b. Scrape adhesion test: no analysis performed because the two coatings are equivalent within the measuring range of this test.

4

- c. Impact test, 23°C: differences were not statistically significant.
- d. Impact test, 4°C: differences were not statistically significant. Averages are shown below (in.-lbs):

		Impact,	Impact,
MIL-P-24441		26.2	25.0
MIL-C-4556		23.2	34.5
Thickness:	5 mils 10 mils	24.2 26.5	34.8 28.5
	15 mils	23.2	26.0
Immersed:	Yes	25.0	28.2
	No	24.3	31.3

2. MIL-P-24441. Because the MIL-P-24441 system performed better than the MIL-C-4556 system in one of the physical tests and was equal to the MIL-C-4556 system in the other tests, the MIL-P-24441 data were analyzed again as a separate group. The data were statistically tested to see if thickness, substrate, or 90-day immersion in seawater affected the performance of the system in the physical tests. No statistically significant differences were found. Thus, for MIL-P-24441, the thickness and substrate do not matter, and immersion of the specimen in seawater for 90 days has no effect. Averages for the four physical tests are given below:

	Thickness (mils)				Substrate a b c			Immersed	
	5	10	15	≛	<u>b</u>	Ē	Yes	No	
Adhesion (psi x 100)	+	+	+	+	+	+	+	+	
Scrape adhesion (kg)	10	10	10	10	10	10	10	10	
Impact, 23°C (in1b)	25.8	27.8	26.3	26.2	29.7	24.2	28.2	25.1	
Impact, 4°C (in1b)	25.5	25.2	21.3	25.0	24.7	22.3	23.6	24.4	

⁺ means strength of coating exceeded range of adhesion tester.

		MIL-F 2444		MIL-C- 4556		
		IMMER	RSED	IMMERSED		
		YES	NO	YES	NO	
Thickness !	5	+	+	6,8	5.5	
Thickness (mils)	10	+	+	7.2	6.4	
	15	+	÷	5.5	4.1	

Figure 10. Eleometer adhesion.

		ML-P 2444	- I	MIL-C- 4556		
		IMMER	RSED	IMMERSED		
		YES	NO	YES	NO	
Thiskess	5	10	Ю	Ю	10	
Thickness (mils)	10	10	10	10	10	
	15	10	10	Ю	10	

Figure 11. Scrape adhesion.

		MIL-F		MIL-C- 4556 IMMERSED		
		IMMER	RSED			
		YES	NO	YES	NO	
Thickness (mils)	5	32	20	21	24	
	10	33	24	27	22	
	i5	26	24	11	34	

Figure 12. Impact 23°C.

		MIL-F 2444		MIL-P- 4556 IMMERSED		
		IMME	RSED			
		YES	NO	YES	NO	
Thickness (mils)	5	28	26	27	58	
	10	23	28	39	24	
	15	23	22	29	3 0	

Figure 13. Impact 40°C.

- 3. Ameron Vinyl System. The data for the vinyl system, Amercoat 99HS over Amercoat 86, were also analyzed to see if thickness, substrate, or immersion had any significant effect.
- a. Elcometer adhesion test: no statistically significant differences were found for this test. The results of this test are rather low, but as previously stated, the glue used to bond the circular dolly to the coating surface may have more of an effect on this coating than on other types. Averages (psi x 100) are:

rsed	Imme	Substrate I			(mils)	Thick		
No	<u>Yeş</u>	<u>c</u>	<u>b</u>	<u>a</u>	<u>15</u>	<u>10</u>	<u>5</u>	
2.4	2.4	2.3	2.7	2.3	2.6	2.2	2.4	

b. Scrape adhesion test: since 14 of the 18 data points were 10 or greater, no comparisons were made. Averages (kg) are:

rsed	<u>Immer</u>		ubstra	<u>S1</u>	(mils)	kness	Thic
No	Yes	<u>c</u>	<u>b</u>	<u>a</u>	<u>15</u>	<u>10</u>	<u>5</u>
9.6	9.4	9.1	9.5	10	8.6	10	10

c. Impact test 23°C: statistically significant differences were found among substrates and among thicknesses. The 15-mil thickness and substrate c proved to be the best. Immersion in segwater had no effect on the impact resistance at room temperature. The average test values (in.-lbs) are:

Thic	kness	(mils)	<u>St</u>	ibstrat	<u>e</u>	Immers	
<u>5</u>	<u>10</u>	<u>15</u>	<u>a</u>	<u>b</u>	<u>c</u>	Yes	No
12.2	17.3	34.3	19.3	20.5	24.0	21.4	21.1

d. Impact test, 4°C: statistically significant differences were found for both substrates and thicknesses. As in the impact test at 23°C, 15 mils and substrate c were the best. Averages (in.-lbs) are:

Thic	kness	(mils)	<u>St</u>	ibstrat	<u>te</u>	Imae	rsed
<u>5</u>	<u>10</u>	<u>15</u>	<u>a</u>	<u>b</u>	<u>c</u>	Yes	Ño
20.8	26.2	46.0	21.2	30.8	41.0	32.2	29.3

The physical test data for the other three nonurethane Task I coatings were not analyzed statistically. However, general comments about the test results follow.

4. MIL-C-22750 Topcoat Over MTL-P-23377 Primer. This epoxy system has very poor adhesion and impact resist are when applied on anodized aluminum (substrate a and b). In the Elcometer adhesion test, the entire coating system was removed, leaving the substrate exposed. During the impact tests, the

coating debonded within the primer layer in an area around the point of impact.

- 5. Steelcote 100 Percent Solid Topcoat Over MIL-P-23377 Primer. The major drawback of this coating is its poor resistance to damage by impact. The adhesion of this coating is fair, but not as good as many of the other coating systems.
- 6. MIL-P-23377 Primer No Topcoat. The Elecometer adhesion test results of this coating are good when the coating is applied over chromate conversion coated aluminum. Scrape adhesion test results were good over all substrates. Impact tests over chromate conversion coated aluminum were slightly better than over anodizing.

Performance - Task I: Polyurethane Coated Specimens - Observations and Statistical Analyses


Test data for the four urethanes were compared to see if differences existed among them or among the three substrates. The effect of immersion was also examined.

- 1. Elcometer adhesion test: the Irathane 155 coating system was best; substrate c gave significantly better results. The results are shown in Figure 14.
- 2. Scrape adhesion test: coatings were significantly different and the coating/substrate interaction was significant. The Hughson topcoat over the Hughson wash primer and the Hughson topcoat over the MIL-P-23377 primer with substrate c gave the best results. The results are shown in Figure 15.
- 3. Impact, 23°C: the only statistical significance was found for the following coatings whose averages were:

Hughson over Hughson	52.5	in15
Hughson over 23377	38.5	in1b
MIL-C-83286	8,7	in1b
Irathane 155	20.0	in1b

4. Impact, 4°C: no statistically significant differences were found; the four coatings gave similar results, the three substrates gave similar results, and immersion had no effect.

The overall results indicate that all of the polyurethane coatings performed best in the physical tests when applied over chemical conversion coated aluminum (substrate c). The currently used Hughson system performed well in the scrape adhesion and impact tests. The Hughson topcoat over the MIL-P-23377 primer also did well in these tests. The Irathane 155 system was best in the Elcometer adhesion test. The Irathane system is designed to be a high-build polyurethane and was applied at a thickness of 15 mils. Although the test results for the scrape adhesion of the Irathane 155 were somewhat low, the additional thickness of this coating offers protection when the surface has been damaged.



COATING. A HUGHSON TOPCOAT AND PRIMER

B HUGHSON TOPCOAT/MIL-P-23377

C MIL-C-83286 MIL-P-23377

D IRATHANE 155/MIL-P-23377

Figure 14. Elcometer adhesion test results of Task I urethane coatings.




Figure 15. Scrape adhesion test results of Task I urethane coatings.

The MIL-P-83286 topcoat applied over MIL-P-23377 primer performed fairly well when applied over substrate c. However, the impact resistance of the coating noticeably decreased during the 90-day immersion period in seawater.

Performance - Task II: Nonpolyurethane-Coated Specimens - Observations and Statistical Analyses

The physical test results for the MIL-C-4556 system, the MIL-C-22750 top-coat over MIL-P-23377 primer, and the BMS-10-11K coatings were compared for the three substrates and for the following four immersion levels:

Immersion Level 1: not immersed Immersion Level 2: seawater Immersion Level 3: Otto fuel

Immersion Level 4: 50 percent seawater, 50 percent Otto fuel

a. Elcometer adhesion test: statistically significant differences were found among coatings, among substrates, and among immersion levels. The coating/substrate and coating/immersion level interactions were significant (see Figure 16). Overall averages (psi x 100) are:

Coating	Average	Substrate	Average	Immersion <u>Level</u>	Average
MIL-C-22750	3.9	a	3.5	1	5.9
MIL-C-4556	7.8	ъ	3.2	2	3.8
BMS-10-11K	3.1	c	8.1	3	4.8
				4	5.1

Overall, the MIL-C-4556 system and substrate c are best. Immersion in seawater contributes most to poor adhesion.

2. Scrape adhesion test: statistically significant differences were found among coatings and among substrates. The MIL-C-4556 system had the best scrape adhesion properties, and all of the coatings adhered best to substrate c, chemical conversion coated aluminum. Figure 17 shows the relationship between coatings, substrates, and scrape adhesion. The average test results (kg) are:

Coating	Average
MIL-C-22750	7.6
MIL-C-4556	10+
BMS-10-11K	6.4
Substrate	Average

a 7.6 b 7.0 c 9.4




Figure 16. Elcometer adhesion test results of Task II coatings in four immersion tests.




Figure 17. Scrape adhesion test results of Task II coatings.

3. Impact test, 23°C: Impact resistance is not as important for Task II coatings as it is for Task I. The coatings for Task II are tested for application on the interior of torpedo fuel tanks, where the coated surfaces would not be subjected to impact forces. However, for the sake of completeness, these tests were conducted and the the results analyzed. There were no significant differences found among coatings. However, substrate c gave significantly better results than substrates a or b. Averages (in.-lbs) for the different substrates are:

<u>Substrate</u>	Average
a	11.8
Ъ	5.3
c	18.4

4. Impact test, 4°C: significant differences were found among coatings and among substrates. The interactions between Task II coatings, substrates, and impact test results are shown in Figure 18. The best impact resistance was seen for the MIL-C-22750 system over substrate c. Average test values (in.-lbs) for the coatings and substrates are:

Costing	Average
MIL-C-22750	22.1
MIL~C-4556	9.8
BMS-10-11K	22,1

Substrate	Average
a	14.5
Ъ	6.7
С	32.8




Figure 18. Impact at 40°C test results of Task II coatings.

Immersion Tests

Tabular Summary - Tasks I and II

Table 5 summarizes the results of the immersion tests. Test specimens were immersed for 90 days. Task I specimens were immersed in aerated synthetic seawater. Task II specimens were immersed in seawater, Otto fuel, or a mixture of 50 percent Otto fuel and 50 percent seawater.

Basis for Rating

After 90 days of immersion in seawater, Otto fuel, or a 50/50 mixture of the two, the conditions of each panel were rated according to the following criteria:*

Excellent -- No visible damage to the aluminum substrate. Impact points are not corroded or pitted, although the paint surface may be damaged. The score lines may have some oxides, but there is no pitting or widening of the lines.

Good — Less than 5 percent of the surface area is corroded. The 20 or 40 in.-1b impact points show some corrosion extending not more than 1/8 in. from the center of the impact point. Score lines widen to no more than 1/8 in. across.

Fair -- 5 to 8 percent of the surface area of the specimen is corroded. The 20 and 40 in.-1b impact points show corrosion 1/8 to 1/4 in. from the center of the impact and usually show a penetration through the panel. Five and 10 in.-1b impact points show a smaller area of corrosion. Score lines widen up to 1/4 in. across and may contain some areas of penetration through the panel.

Poor — More than 8 percent of the surface area of the specimen is corroded. Forty and 20 in.—1b impact points are corroded more than 1/4 in. from the center of the impact point and penetrate through the panel. Five and 10 in.—1b impact points also may penetrate through the panel. Score lines widen to more than 1/4 in. across and penetrate through the panel along much of their length.

These criteria were used for all specimens including damaged and undamaged specimens, specimens that were galvanically coupled, and specimens that were not galvanically coupled. Examples of specimens illustrating the above criteria are given in Figure 19. The examples shown are panels which have been damaged prior to immersion. The panel on the left was impacted, and the panel on the right was scored prior to immersion. In Figure 19 the reverse side of the impacted panel is shown on the left. At the point of 40 in.—1b impact the coating has broken away from the panel. However, the anodizing is completely intact and no damage has occurred to the aluminum substrate. Each

^{*} ASTM D 1654-79 describes a standard method for evaluating coated specimens exposed to corrosive environments. The standard was not used because it is more appropriate for evaluating specimens less severely corroded than the galvanically coupled specimens in this study.


Table 5

Corrosion Resistance of Specimens during 90-Day Immersion


	Topcost Thickness	Sub-		Uncoupled			Coupled	
System	(mils)	strate	Undamaged	Scored	Impacted	Undamaged	Scored	Impacted
			Tasi	t I: Nonureti	names			-
MIIP-24441	5	8	Excellent	Excellent	Zxcellent	Excellent	Good	Feir
over	10	A	Excellent	Excellent	Excellent	Excellent	Good	Fatr
MIL-P-24441	15	a	Excellent	Excellent	Excellent	Excellent	Good	Fair
	5	ъ	Excellent	Excellent	Excellent	Excellent	Good	Fair
	10	ь	Excellent	Excellent	Excellent	Good	Good	Good
	15	b	Excellent	Excellent	Excellent	Excellent	Poor	Fair
	5	c	Good	Excellent	Excellent	Excellent	Good	Fair
	10	c	Excellent	Excellent	Excellent	Excellent	Fair	Poor
	15	c	Excelient	Excellent	Excellent	Excellent	Good	Poor
HIL-C-4556	5	٨	Excellent	Excellent	Good	Excellent	Yeir	Good
over	10	a	Excellent	Excellent	Good	Good	Fair	Good
M11C-4556	15	6	Excellent	Excellent	Good	Excellent	Feir	Good
HIL-C-22750	5	A	Excellent	Excellent	Cood	Excellent	Fair	Fair
over	10		Good	Excellent	Good	Excellent	Poor	Poor
HIL-P-1.377	15	8	Good	Excellent	Good	Excellent	Foor	Fair
100% Solids	5		Excellent	T	01	N		
Over Solids	10	a	Excellent	Excellent	Good	Good	Fair	Fair
HIL-P-23377	15	4		Excellent	Good	Excellent	Fair	Good
NLL-Y-233//	15		Excellent	Excellent	Good	Fair	Fair	Fair
MIIP-23377	5		Fair	Excellent	Good	Excellent	Good	Good
	5	ь	Fair	Excellent	Fair	Excellent	Good	Cood
	5	c	Good	Excellent	Good	Excellent	Good	Good
Amercost 99HS	5	4	Excellent	Excellent	Good	Good	Fair	72aF
over	10	•	Excellent	Excellent	Good	Good	Fair	Fatr
Amercoat 86	15	a	Excellent	Excellent	Good	Good	Fair	Good
	5	ъ	Excellent	Excellent	Excellent	Fair	Good	Poor
	10	ь	Excellent	Excellent	Excellent	Good	Good	Fair
	15	ъ	Excellent	Excellent	Excellent	Excellent	Good	Good
	5	¢	Excellent	Excellent	Excellent	Fair	Good	Poor
	10	c	Excellent	Excellent	Excellent	Good	Gocd	Poor
	15	c	Excellent	Excellent	Excellent	Excellent	Good	Good
Hughson polyurathane	5	a	Good	Fair	Excellent	Fair	Fair	Good
over Hughson	5	ъ	Excellent	Fair	Excellent	Fair	Poor	Poor
wash primer	5	c	Excellent	Excellent	Excellent	Fair	Fair	Good
Hughson polyurethane	5	8	Excellent	Excellent	Excellent	Good	Pair	Good
Javel	5	ъ	Good	Excellent	Excellent	Good	Good	Poor
HIL-P-23377	5	С	Excellent	Excellent	Excellent	Excellent	Fair	Cood
MIL-P-83286	5	a	Good	Good	Good	Fair	Fair	Good
over	5	b	Excellent	Good	Good	Poor	Fair	Fair
H11P-23377	5	c	Excellent	Excellent	Excellent	Fair	Fair	Good
Irathane 155	15	ń	Excellent	Excellent	Excellent	Excellent	Fair	Good
over	iś	 b	Excellent	Excellent	Excellent	Excellent	Fair	Goed
HIL-P-23377	15	c	Excellent	Excellent	Excellent	Excellent	Good	Excellent
		-						

Table 5 (Cont'd)

Topcost Thickness		Sub-	Uncoupled		Coupled			
System	(mils)	strate	Undamaged	Scored	Impacted	Undamaged	Scored	Impacted
				Task II				
		· 		(day II				
HIL-C-22750	Seawater	a	Excellent	Excellent	Poor	Poor		
over	Otto fuel	a	Excellent	Excellent	Excellent	Excellent		
HTL-P-23377	50/50	ā	Good	Excellent	Poor	Poor		
	Seavater	ь	Good	Excellent	Poor	Poor		
	Otto fuel	b	Excellent	Excellent	Excellent	Excellent		
	50/50	ь	Good	Excellent	Fair	Poor		
	Seawater	c	Excellent	Excellent	Poor	Fair		
	Otto fuel	c	Excellent	Excellent	Excellent	Excellent		
	50/50	c	Good	Excellent	Poer	Poor		
MIL-C-4556	Seavater	a	Excellent	Excellent	Fair	Fair		
over	Otto fuel	a	Excellent	Excellent	Excellent	Excellent		
HIL-C-4556	50/50	a	Good	Good	Excellent	Poor		
	Seavater	ь	Excellent	Good	Good	Fair		
	Otto fuel	b	Excellent	Excellent	Excellent	Excellent		
	50/50	ь	Excellent	Good	Good	Poor		
	Seawater	c	Excellent	Good	Fair	Good		
	Otto fuel	ε	Excellent	Excellent	Excellent	Excellent		
	59/50	c	Good	Good	Fair	Poor		
BHS-10-11K	Senwater	4	Excellent	Excellent	Fair	Fair		
	Otto fuel	а	Good	Excellent	Excellent	Excellent		
	50/50	a	Excellent	Excellent	Poor	Poor		
	Seavater	ъ	Excellent	Excellent	Poor	Good		
	Otto fuel	ъ	Excellent	Excellent	Excellent	Excellent		
	50/50	ь	Excellent	Excellent	Poor	Poor		
	Seawater	c	Excellent	Excellent	Poor	Poor		
	Otto fuel	c	Excellent	Excellent	Excellent	Excellent		
	50/50	e	Excellent	Excellent	Poor	Poor		




a. Excellent




b, Good

Figure 19. Specimens after 90-day immersion.



c. Fair



d. Poor

Figure 19. (Cont'd).

of the scored panels in Figure 19 was scored twice on each side. The score line on the right side of the specimen was cut down to bare aluminum. The score line on the left of each specimen was intended to be cut down to, but not through, the anodizing or conversion coating. However, it was difficult to control the depth of the cut and the bare aluminum substrate was often exposed. Some of the score lines cut to bare aluminum did not corrode significantly during immersion. When the bare aluminum is exposed to seawater some oxides form on the surface of the metal. A scored panel could still meet the criteria for excellent immersion resistance if the corrosion has not extended beyond the original score line in width or in depth. Most of the nongalvanically coupled scored specimens were able to meet this criteria as did many of the coupled specimens. This may have been due to the corrosion inhibitive properties of the coatings and the aluminum pretreatments.

Performance - Task I: Uncoated Specimens - Undaraged

Uncoupled: Bare aluminum panels correded in seawater over their entire surface, but there was no pitting. Harcoat anodized sealed panels and unsealed panels performed very well with only a few minor areas of corrosion at the edges. Chromate conversion coated panels had a few areas of minor corrosion on their surface and near the edges.

Coupled: Bare aluminum panels that were immersed in seawater for 90 days corroded and pitted over their entire surface (Figure 20). Hardcoat anodized scaled panels corroded only on their edges (Figure 21). Hardcoat anodized unsealed panels corroded on their edges and at a few surface spots where the anodizing might have been flawed or damaged (Figure 22). The chromate conversion coated panels had light corrosion on their surface. None of these spots were large, but there were many of them (Figure 23).

Performance - Task I: Nonpolyurethane-Coated Specimens - Observations

The corrosion performance of the nonpolyurethane-coated paint specimens in Task I is described for each coating, coupled and uncoupled, damaged and undamaged.

1. MIL-P-24441.

Uncoupled: Layers of topcost were lost at impact points on all panels. The damage caused by impact was more severe on the panels with a 10- and 15-mil topcoat thickness than on the 5-mil-thick costed panels. However, corrosion of the aluminum substrate was minimal. The primer that remained intact protected the substrate from corrosion in the seawater. Neither the scored nor the undamaged panels exhibited corrosion or loss of adhesion. Nearly all specimens in this test were rated excellent.

Coupled: The chemical conversion coated panels corroded more at impact points than did the anodized sealed and anodized unsealed panels. Thickness had less effect. Areas of penetration through the panel at impact points were quite large, up to 1/3 in. from the impact point. Panels coated with 5 mils




Figure 20. Bare aluminum after 90-day immersion in seawater.




Figure 21. Hardcoat anodized dichromate sealed aluminum after 90-day immersion in seawater.




Figure 22. Hardcoat anodized unsealed aluminum after 90-day immersion in seawater.




Figure 23. Chromate conversion coated aluminum after 90-day immersion in seawater.

of topcoat showed better corrosion resistance at score lines than did the 10and 15-mil coated panels. Undamaged panels showed only occasional small areas of corrosion at corners, and most were rated excellent.

2. MIL-C-4556

Unccupled: There was no corrosion or loss of adhesion around the score lines. Impacted panels showed the removal of the topcoat at 20 and 40 in.-1b impact points, but only the 40 in.-1b area corroded during immersion. The 10-mil-thick coated panels seemed to have better resistance to impact damage than either the 5- or 15-mil-thick coatings, but all three were rated good.

Coupled: Coating thickness had no effect on the corrosion at score lines or impact points. Impact points corroded more on the reverse of the point of impact than on the front. Undamaged panels were rated good to excellent.

MIL-C-22750.

Uncoupled: This coating adhered very poorly. Scratching with a fingernail could remove large sections of the coating along a score line. The primer readily debonded from the substrate (anodized chromate sealed aluminum).
Blisters up to 3/4 in. in diameter formed around impact points and at edges.
The aluminum beneath the blisters was significantly pitted and corroded.
Coating thickness did not appear to affect the deterioration of the specimen.

Goupled: Blisters formed around score lines and impact points. Pitting at impact points was severe. Thickness had no apparent effect on the coating's rate of deterioration.

4. The 100 Percent Solids Epoxy Coating

Uncoupled: Panels showed no blistering or corrosion except at impact points. The 10-mil-thick costed panels showed greater resistance to corrosion at impact points than did either the 5- or 15-mil-thick coatings, but the differences were small. The thinner coating did not cover adequately, and the thicker coating was more likely to crack.

Coupled: Impact points corroded to the extent that the aluminum was penetrated except on the 15-mil-thick coating. Scored panels corroded equally for all thicknesses and were rated fair.

5. MIL-P-23377.

Uncoulled: Undamaged and impacted panels were fair to good, but scored panels were rated excellent. The color was somewhat faded because the chromates leached into the seawater. Impact points corroded on the reverse side of the panel. Some pitting of the aluminum was observed at these points.

Coupled: Chromate conversion coated panels showed greater resistance to corrosion at points of impact than did either of the anodized substrates. However, the differences observed were quite small. Score lines showed excellent resistance to corrosion over all three substrates.

6. Ameron Vinyl System

Uncoupled: Overall, this coating had good resistance to corrosion in seawater. There was no loss of adhesion around score lines, except when thicker coatings (10 or 15 mils) were applied over the chemical conversion treated aluminum. Impact points exhibited some corrosion over anodizing. Resistance of the impact points to corrosion depended on coating thickness. Fifteen mils of topcoat provided the best protection from impact damage.

Coupled: Coating thickness had little effect on the corrosion caused by score lines. All were rated fair to good. However, thicker coatings did provide greater corrosion protection at impact points. The Ameron coating was applied to one group of panels very early in the panel preparation period, and to the rest of the panels several weeks later. Thus, some of the panels were allowed a much longer drying time before immersion. Those with the shorter drying period tended to blister, and those with the longer drying period did not. Although there were few blisters, it would be advisable to allow the longest possible drying time before putting Ameron-coated torpedoes in seawater.

Performance - Task I: Polyurethane-Coated Specimens - Observations

1. Hughson Polyurethane Topcoat

The Hughson polyurethane topcoat TS 3236-23 A/B Revision was applied over both the Hughson wash primer TS 3236-26 and the Deft HIL-P-23377.

Uncoupled: Test panels primed with the wash primer had more of a tendency to form small blisters between the primer and the substrate. Also, hardcoat anodized panels had more blisters than did the chromate conversion costed panels. In all other ways the panels seemed to perform equally in a 90-day seawater immersion.

Coupled: All panels had a tendency to blister along the edges, corners, and impa t points. However, the panels primed with the Hughson wash primer formed more randomly located blisters on the surface of the panels. The best system for resistance to corrosion at score lines was the MIL-C-23377 primer over the anodized unsealed aluminum, but this system had the least resistance to corrosion around impact points. Overall, the MIL-C-23377 primer performed better than the wash primer, and both systems performed better when applied over chromate conversion coated aluminum.

2. MIL-C-83286.

Uncoupled: The panels pretreated with hardcoat anodizing (sealed or unsealed) exhibited loss of adhesion around score lines, but were still rated good to excellent. The chromate conversion coated panels had no such loss of adhesion. The chemical conversion coated panels also showed no corrosion at impact points (rated excellent), while the other panels showed some pitting (rated good). Undamaged panels performed well over all three substrates.

Coupled: All types of panels showed corrosion at edges and corners; thus, none was rated excellent. The chromate conversion coated panels had the greatest corrosion resistance at impact points. Scored panels showed equal performance over all three substrates and were rated fair.

3. Jrathane 155.

Uncoupled: The coating looked dirty after immersion and did not come clean when the panels were rinsed. Overall, the corrosion resistance of the coating was excellent. There was no blistering or corrosion anywhere. All uncoupled panels were rated excellent. There was no loss of adhesion of the coating near the score lines. All three substrates showed equally excellent performance. Impact areas had a break in the topcoat, but the primer was intact, and no corrosion was evident.

Coupled: Impact points had high resistance to corrosion and were rated good to excellent. Scored lines had fair to good corrosion resistance. Chromate conversion coated panels were rated higher than anodized sealed and anodized unsealed panels.

Performance - Task II: Uncoated Specimens - Observations

Seawater: For a discussion of the performance of uncoated specimens in seawater, see Performance - Task I: Uncoated Specimens.

Otto Fuel: None of the specimens, uncoupled or coupled, corroded in Otto fuel.

Fifty percent seawater/50 percent Otto fuel: Uncoupled bare aluminum panels corroded over the otto fuel layer. There was no deep pitting. Uncoupled hardcoat and dized sealed and unsealed panels did not visibly corrode. Uncoupled chromate conversion coated panels corroded in a few areas in both the seawater and the Otto fuel layer. Coupled bare aluminum corroded heavily in the seawater layer and more lightly in the portion immersed in the Otto fuel layer (Figure 24). The coupled anodized sealed aluminum test panels corroded on the edges at the warer/fuel interface and slightly in the seawater layer (Figure 25). The coupled anodized unsealed panels corroded more than the sealed panels, and they corroded mostly on the edges (Figure 26). The coupled chromate conversion coated panels were corroded over much of the surface exposed to the seawater, with more concentrated areas of corrosion at the seawater/fuel interface (Figure 27).




Figure 24. Bare aluminum after 90-day immersion in 50 percent seawater/50 percent Otto fuel.




Figure 25. Hardcoat anodized dichromate sealed aluminum after 90-day immersion in 50 percent seawater/50 percent Otto fuel.




Figure 26. Hardcoat anodized unsealed aluminum after 90-day immersion in 50 percent seawater/50 percent Otto fuel.




Figure 27. Chromate conversion coated aluminum after 90-day immersion in 50 percent seawater/50 percent Otto fuel.

Performance - Task II: Nonpolyurethane- Dated Sperimens - the routins

The coatings discussed below were tested for use on the interior of the torpedo fuel tanks. These coatings were immersed in artificial seawater, Otto fuel, and a mixture of 50 percent Otto fuel and 50 percent seawater. The seawater tanks were aerated; for the seawater and Otto fuel mixture, the seawater layer (the upper layer) was continuously aerated.

1. MIL-C-22750.

Seawater: Uncoupled panels had excellent resistance to corrosion. However, this coating system adhered very poorly. One's fingernail could be used to easily peel paint from the anodized sealed and unsealed panels. The chromate conversion coated panels had good adhesion between the primer and substrate. Coupled panels performed very poorly. There was much loss of metal, and many panels had holes penetrating through the aluminum to the other side. With anodized aluminum, blisters spread out from impact points and score lines. The blisters did not seem to greatly accelerate the corrosion of the area — the anodizing was still intact on the surface of the aluminum.

Otto fuel: This coating is compatible with Otto fuel. No corrosion or softening of the film was evident.

Fifty percent seawater/50 percent Otto fuel: Anodized sealed and unsealed panels suffered more corrosion at edges and corners than did chemical conversion coated panels. However, the chromate conversion coated panels corroded more at the Otto fuel/seawater interface than did the anodized panels. Uncoupled panels were rated good to excellent. Coupled panels were rated fair to poor.

2. MIL-C-4556.

は、これでは、100mのでは 100mのでは、100mの

Seawater: There was some loss of adhesion near score lines on uncoupled panels. This problem was more severe on chromate conversion coated panels than on hardcoat anodized panels. Undamaged panels showed no corrosion. Coupled panels corroded only at score lines, and the extent of corrosion was equal for all three substrates. Uncoupled panels were rated good to excellent. Coupled panels were rated fair to good.

Otto fuel: Uncoupled and coupled panels showed no corrosion, loss of adhesion, or deterioration of the coating.

Fifty percent seawater, 50 percent Otto fuel: Uncoupled scored panels showed some small blistered areas along the fuel/seawater interface. Undamaged panels had no blisters. Coupled panels showed the greatest corrosion on the chemical conversion coated panels; the damage on these panels was quite severe — nearly 70 percent of the coating was removed and much of the aluminum had corroded away. On the anodized unsealed panels about 20 percent of the coating was removed, and on the anodized sealed panels about 5 percent was removed. Uncoupled panels were rated good to excellent. Coupled panels were rated fair to excellent if undamaged, and poor if scored before immersion.

3. BMS-10-11K.

Seawater: Uncoupled panels showed no corrosion and no loss of adhesion around score lines. Undamaged panels also were rated excellent. Coupled panels were rated poor to fair. Pits up to 1/4 in. in dismeter were spread over the entire surface of the panels. This coating was applied as a one-coat system without a primer; any small pinholes or other defects in the film were not covered by additional coats. Coupled panels with score lines had fewer pits, but much corrosion of the scored area. The anodized panels performed somewhat better than the chromate conversion coated panels; there were still corroded areas, but there were fewer corrosion pits.

Otto fuel: Both coupled and uncoupled panels showed excellent resistance to Otto fuel. There was no evidence of coating deterioration or substrate corrosion.

Fifty percent seawater/50 percent Otto fuel: Uncoupled panels showed only some minor areas of corrosion on the edges and at corners, and were rated good to excellent. Coupled panels were all very corroded and received a rating of poor. Anodized sealed panels performed slightly better than anodized unsealed panels; chromate conversion coated panels had the poorest performance. The worst areas were at the fuel/seawater interface and the air/seawater interface.

5 conclusions

Task 1: Torpedo Exterior Coatings

- l. The epoxy systems, MIL-P-24441 and MIL-C-4556, were obviously the best of the five epoxy coatings that were tested in Task I. Both of these epoxies and the epoxy primer MIL-P-23377 had excellent scrape adhesion. MIL-P-24441 was superior to all coatings in the Elcometer adhesion test. The impact strength of MIL-P-24441 and MIL-C-4556 were approximately the same before immersion in seawater. MIL-C-4556 was not quite as resistant after immersion. The impact resistance of MIL-P-23377 was much inferior to either of the other two epoxies. There was no advantage gained in performance when MIL-P-24441 was applied in thicknesses greater than 5 mils. Actually, the surface of the coating chipped more easily at the greater thicknesses. The MIL-P-24441 also had the best corrosion resistance. Based on the test results, the MIL-P-24441 system has the best overall performance of all of the ten candidate coating systems tested for Task I.
- 2. The Ameron vinyl system (Amercoat 86 primer and Amercoat 99HS top-coat) provides a high degree of corrosion protection, has good impact resistance and adhesion, and (because it is a solution vinyl) should be easily repaired when the original coating is damaged. A 15-mil-thick coating of this vinyl provides much greater protection against damage by impact than does a 10- or 5-mil coat. However, the 15-mil-thick coat has a much longer drying time; adequate time must be allowed before immersing this system. Although the MIL-C-4556 system may have had a slightly better overall performance than the Ameron system, the latter is preferred. The MIL-C-4556 system has corrosion resistance, impact resistance, and adhesion which are only slightly inferior to the MIL-P-24441 system. The Ameron system has properties of flexibility and repairability which are not seen in the two epoxy systems. These properties make the Ameron system a good second choice of the ten systems tested for Task I.
- 3. Of the four polyurethane systems tested for Task I, Irathane 155 had the best adhesion according to the Elcometer adhesion test. Irathane 155 applied over MIL-P-23377 primer showed superior corrosion resistance during the 90-day seawater immersion tests. The Irathane coating is a high-build polyurethane topcoat and was applied at a dry film thickness of 15 mils. The Irathane polyurethane system would be ranked third among the candidate coatings for Task I.

化二氯乙烷 化二氯化氯化氯化 医二氏性 化邻硫酸 医二甲甲基 医阿尔尔氏

- 4. The MIL-P-23377 primer does not adhere well to anodized surfaces. If it is to be used, it should be applied only to chromate conversion coated aluminum. When this primer was applied to anodized surfaces, there were more blisters and much poorer adhesion and impact resistance than when it was applied to the chromate conversion coated aluminum.
- 5. The effect of coating thickness or type of substrate on performance depends on the specific coating system that is used. There is no one thickness or aluminum pretreatment that is best in all cases.

Task II: Torpedo Interior Fuel Tank Coatings

Of the three candidate coating systems for Task II, the MIL-C-4556 system had the best overall performance when applied over the dichromate sealed, hardcoat anodized 7075 series aluminum. When undamaged, this coating is highly resistant to deterioration in Otto fuel, seawater, or a mixture of the two. When the coating is physically damaged, it does not break away from the damaged area, but remains intact even if corrosion has undercut the coating.

6 RECOMMENDATIONS

This study was very limited in the number of coating systems evaluated. The coatings tested represent different types of coatings and different physical properties. The results of the tests on these coatings may be used to select additional coatings for testing to find the coating system which will best protect torpedo exteriors and the interior fuel tank. Consideration should be given to the following types of coatings:

- 1. Vinyl-modified epoxies. Coatings of this type are rather new, but have potential. Epoxy coatings have a high degree of chemical resistance, but they tend to be somewhat brittle and inflexible. Incorporating vinyl polymers into epoxy coatings could increase the flexibility and impact resistance of epoxy coatings, while retaining seawater immersion resistance.
- 2. Vinyl coating systems. The high solids vinyl system manufactured by Ameron performed well, but was somewhat difficult to apply and required a lot of thinning. Alternate vinyl systems should be evaluated, including some low-solids vinyl topcoats.
- 3. Alternative primers. The MIL-P-23377 epoxy primer manufactured by Deft does not adhere well to anodized surfaces. It is recommended that other primers be evaluated to find a suitable substitute that will have satisfactory adhesion to anodized aluminum. Possible primers include the Boeing specification BMS-10-11K, MIL-P-24441 Formula 158, or possibly a wash primer such as DOD-P-15328.
- 4. Alternative application methods. The initial study was limited to coatings applied by conventional spraying methods. Possible alternative coatings may include electrostatically applied epoxy coatings, plasma-sprayed coatings, or low-level heat cured coatings.

In addition to materials, there are several recommendations regarding test procedures. These include both modifications to test procedures previously used and the development of new test procedures. The following changes are recommended:

- 1. The number of test specimens per coating should be increased from 16 to 18. Six panels each should be allowed for nonimmersion, galvanically coupled immersion, and uncoupled immersion tests. Previously only four panels were allowed for nonimmersion tests. Statistical comparisons are more useful when equal numbers of specimens are used for each test.
- 2. The characterization of the candidate coatings by standard gas chromatographic analysis is only able to determine the number and relative amounts of volatile materials in each coating. An alternative procedure called pyrolysis gas chromatography is now possible on equipment recently acquired by CERL. In this technique, a solid sample of coating film is pyrolized under controlled conditions, and the volatile pyrolysis products are analyzed by gas chromatography. The resulting chromatogram is characteristic of the particular coating formulation. This characterization method should be used in conjunction with the infrared analysis techniques used in this study.

3. The major limitation of the Elcometer adhesion test is the adhesive used to bond the aluminum dolly to the surface of the coating. Although the best available adhesives were used, it was found that their strength was often less than the bond strength of the test coatings to the subtrate. This test does, however, differentiate between coatings with very low adhesion and those with good adhesive strength. This test therefore continues to be an acceptable method for measuring the adhesive strengths of coatings.

REFERENCES

- Otto Fuel II: Safety, Storage and Handling, NAVSEA OP 3368 Fifth Revision (Naval Sea Systems Command, 15 January 1973; Change 1, 15 May 1975).
- Standard Test Methods for Adhesion of Organic Coatings, D 2197 (American Society for Testing and Materials [ASTM], 1968).

Resistance of Organic Coatings to the Effects of Rapid Deformation (Impact), D 2794 (ASTM, 1969).

METRIC CONVERSIONS

1 in. = 25.4 mm

1 in.-1b = 1.1298 x 106 dyne centimeters

 $1 \text{ mil} = 2.54 \times 10^{-5} \text{ m}$

l psi = 6.9 kPa

APPENDIX A:

GAS CHROMATOGRAPHIC AND INFRARED SPECTROM ANALYSES




Figure Al. Gas chromatogram: MIL-P-24441 Formula 158 primer.

```
Mic-9-24441 #099518 .52
         9.59
          2.35
        DY: START PROM PATE 1
                            3.91
         5.75
         OV: START FINAL TIME 1
         8.38
         3:38
9:47
          10.15
          10.79
       199: $76P PUN
IND 1 5880F MANUAL INJECTION 9 09:40 JUN 21, 1982
APEA 🧐
                  APEA TYPE
                                AREA %
            1329960.00
                                 63.978
                         PB
  3.91
                                  8.245
  5.75
-.23
               5287.27
                         84
              33165.70
                                 1.537
                         υV
  7.6€
                         ٧P
                                  8.994
              2:439.90
              16186.38
                         pp
                                 €.75€
  3.89
             255532.99
                         PY
                                 11.845
  3.78
  9.92
             223118.00
                          ŲΨ
                                 10.342
                                 6.588
  9,47
             142119.00
                         ÝΡ
              28784.60
                          54
                                  1.334
 19.15
              5:653.40
                                  2.394
 10.70
TOTAL AREA = 2157350.00
MULTIPLIEP = :
```

Figure A2. Gas chromatogram: MIL-P-24441 Formula 152 topcoat.

```
3.55

3.71

4.23

4.57

5.76

5.20

7.27

7.51

5.10

9.50

10.18

10.74

11.21
```

The I 1888A MANUAL INJECTION @ 87:29 Jun 23, 1982 AREA 1.

47	ARE.A	TYPE	APEA %
3.71	128008.00	PF	6.883
4.27	23703.30	PP	1.274
4,67	55637.30	ρy	2.992
5.76	12686.80	99	0.658
5.20	301262.00	P8	16.198
7.23	41022.28	γÞ	2.206
7.61	42478.69	Pγ	2.282
5.10	54579.20	44	2.935
3.32	640754.88	44	34.452
9.18	87240.60	ΑĀ	4-691
9.59	193639.28	44	18.412
19.12	72798.90	γÿ	3.914
10.74	:45917.90	99	7.846
::.31	60765.20	γp	3.267

TOTAL PPEA * 1859949.00 MULTIPLIER * 1

Figure A3. Gas chromatogram: MIL-C-4556 primer.





Figure A4. Gas chromatogram: MIL-C-4556 topcoat.




KHP% 5860A MANUAL INJECTION 9 12:22 JUN 31: 1982 PPSA :

ş-	AREA	TYPE	AREA 🖫
3.80	621120.00	26	32,970
5.76	474452.98	94	25.184
6.21	651345.00	₩	34,974
7.21	91883.48	Vγ	4.877
7.53	:2663.20	79	€.672
á. 57	16357.60	ev	0.268
9.95	16095.49	48	9.854

"OTA_ AREA = 1883910.00 "ULTIPLIEP = 1

Figure A5. Gas chromatogram: Deft MIL-P-23377.



7.619 3.73 263260.00 P8 2.089 72161.99 BH 4,67 5.:1 297.41.99 5.865 HH 62057.30 53867.08 5.75 нн 1.313 6.13 7.35 1.794 JL. 51.302 2121139.00 ы. 15.497 7.69

535031 00

39441.79

45495.18

Hh

нΗ

нн

TOTAL AREA = 3455090.00 MULTIPLIER = 1


3.75

9.44

Figure A6. Gas chromatogram: MII-C-22750.

1.433

STEELECOTE 100% SOLIDS



Chp 3 5380A MANUAL INJECTION $\mathfrak C$ 06:43 JUN 23, 1982 1983 $\mathfrak C$

2 ਵ	AREA	TYPE	AREA %
5.08	260:2.40	нн	5.258
5.75	56357.40	HH	11.391
5.25	412373.00	нн	83.351
TOTAL APEA	= 494743.00		

:91PL RPER = 494743.00 MULTIPLIEP = 1

Figure A7. Gas chromatogram: Steelcote 100 percent solids epoxy.




Figure A8. Gas chromatogram: Americat 86 primer.

```
OVEN TEMP FINAL TIME 15
AMERCOAT 6 THINNER
          1.45
         OV: START PROM RATE 1
          5.03
_W: :TAPT FINAL TIME 1
            3.32
            3.51
             10.24
                 > 11.13
                   12.39
             12.75
              > 17.44
             14.13
              14.75
              15.47
        TV: STOP PUR
1993 $8809 MANUAL INJECTION 9 18:81 JUN 21: 1982
    97
                      AREA TYPE
                                      AREA %
                 44177.69
                                      0.47<del>9</del>
26.222
                              нн
    5.03
               2418440.06
                              14:4
    6.96
               2:83030.00
                                      22.802
    7.94
                              HH
    8.82
                  56467,50
                              нн
                                       0.812
                                       0.915
1.779
    9.51
                  84794.39
                 154118.. 952623.00
   18.24
                              HH
V
   .:.13
                                      10.329
                1091270.06
                                       11.832
   :2.99
   :2.75
                 155446.00
                                        1.685
                 765326.00
                              HH
                                        3.299
                                       3.945
5.531
6.456
   1.13
                 290371.80
                              нн
                 510150.00
596370.00
                              HH
   15.47
                              нн
  1374U AMER = 9223100.00
```

فهمه المستعمل والبهاري المستعدية والمستعدد والمستعدد والمستعد والمستعدد والمستعدد والمستعدد والمستعدد

Figure A9. Gas chromatogram: Amercoat 6 thinner.

```
2.35
3V: STAPT PROM PATE 1

4.71

5.18

0W: START FINAL TIME 1

7.27

8.15

10.36

11.76

17.07

0V: STOP PUN
```

the: 3 58804 MANUAL INJECTION @ 08:17 JUN 21, 1982 ANGA 1

27	APEA	TYPE	area %
4.71	160277.00	ρų	7.769
5.18	783571.00	VB	37.982
7.27	569786.00	87	32.466
7.44	33596.79	77	4.052
7,÷3	115664.00	YP.	5.607
8.15	142907.00	89	5.927
10.23	35510.00	PY	1.721
11.76	47935.30	77	2.289
13.07	24678.79	٧P	1.196

TOTAL APEA = 2067038.00 MULTIPLIER = 1

Figure AlO. Gas chromatogram: Americat 99HS topcoat.


Figure All. Gas chromatogram: Amercoat 9 thinner.

5.23

MULTIPLIER = 1

TOTAL AFEA = 19585300.00

TS3236-26 HASH PRIMEP



In 1 58888 MANUAL INJECTION 9 89:07 Jun 23, 1982 APER χ

RT	APEA	TYPE	AREA %
1.13	428829.00	44	11.475
2.64	834794.89	48	22.339
4.79	490960.00	57	13.138
5.12	22791.80	44	9.619
5.41	91133.40	VV	2.439
7.47	1839450.00	VB.	49.223
9.90	19025.00	PH	0.777

TOTAL AREA = 3736980.00 MULTIPLIER = :

Figure Al2. Gas chromatogram: Hughson TS 3236-26 wash primer.

HUGHSON POLYUPETHANE TOPCOAT




Figure Al3. Gas chromatogram: Hughson TS 3236-23 topcoat.





Figure A14. Gas chromatogram: MIL-C-83286.



EMP\$ 57:00 MANUAL INJECTION 9 13:34 JUL 12: 1982

APEA	ZAYT	AREA %
:944130.00	46	74.689
466762.00	34	17.730
27155.90	VΥ	1.832
97410.00	ΑĄ	3.700
48510.90	٧¥	1.843
12494.18	88	9.475
:6109.30	28	9.612
	1964130.00 466762.00 27155.90 97410.00 48510.90 12494.10	1964130.00 V8 466762.00 BY 27155.90 VY 97410.00 VV 48510.90 VV 12494.10 BP

OF STOR BUY

Figure Al5. Gas chromatogram: Irathane 155.

Figure Al6. Gas chromatogram: BMS-10-11K.




Figure Al7. Gas chromatogram: MIL-T-81772/AS thinner.

PENTANE

0.59

2.37

1.39

2.37

1.39

2.37

1.39

2.37

1.39

2.37

1.39

2.37

1.39

2.37

1.39

2.37

1.39

2.37


1.39

2.37

TOTAL APEA = 9.00 MULTIPLIER = 1

PAGE

Figure Al8. Gas chromatogram: solvent used for preparing samples - pentane.



Agure A19. Infrared analysis: MIL-P-24441 primer, component A.





Figure A20. Infrared analysis: MIL-P-24441 primer, component B.



igure A21. Infrared analysis: MIL-P-24441 topcoat, component A.





Figure A22. Infrared analysis: MIL-P-24441 topcoat, component B.



igure A23. Infrured analysis: MIL-C-4556 primer, component A.




Figure A24. Infrared analysis: MIL-C-4556 primer, component B.





Figure A25. Infrared analysis: MIL-C-4556 topcoat, component A



'igure A26. Infrared analysis: MIL-C-4556 topcoat, component B.







Figure A27. Infrared analysis: MIL-P-23377, component A




igure A28. Infrared analysis: MIL-P-23377, component B




Agure A29. Infrared analysis: MIL-C-22750, component A.




Pigure A30. Infrared analysis: MIL-C-22750, component B.



Steelcote 100 percent solids epoxy, component A. Infrared analysis: Flgure A31.



<u>a</u> Steelcote 100 percent solids epoxy, component Infrared analysis: Figure A32.



Americant 86, liquid, pigment removed Infrared analysis: Figure A33.





Figure A34. Infrared analysis: Amercoat 6 thinner.



Amercoat 99HS, 11quid, pigment removed Infrared analysis:







Figure A36. Infrared analysis: Amercoat 9 thinner.




Hughson TS 3236-26 wash primer, component Infrared analysis:



TS 3235-26 wash primer, component Hughson. Infrared analysis:



Hughson TS 3236-23 topcoat, component Infrared analysis:



TS 3236-23 topcoat, component Hughson Infrared analysis:




Figure A41. Infrared analysis: MIL-C-83286, component I.







Figure A42. Infrared analysis: MIL-C-83286, component II.



igure A43. Infrared analysis: Irathane 155, component A



gure A44. Infrared analysis: Irathane 155, component B.



igure A45. Infrared analysis: BMS-10-11K, component A.




Figure A46. Infrared analysis: BMS-10-11K, component B.




Figure A47. Infrared analysis: MIL-T-81772/AS thinner

APPENDIX B:

ADDITIONAL VENDOR INFORMATION

MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Appendig by U.S. Department of Labor "Country's Soule" to Forc (1894-35)

GSF

	Section	<u> </u>			
www.scruessawe Mobile Paint M	fg. Co., Inc.		DATE OF	me 02/1	16/83
STREET ADDRESS P. O. Box 717	an.	STATE, MO 2# CO	∞ Theodo	re, AL.	36590
енеясенсу теценноме но (205) 653- веояматюм теценноме но (205) 653-		ucians Ci	atalyst		
MANAGEMENT COCK DESTRICTION 35-EF-5	1 1840		-P-24441 ponent B	/2A, 3A,	4A, 5A, 6
Section	II-HAZARDOUS	SINGRED	ENTS		
HUROENT	C.A.S. NO.	PERCENT BY WT.	TLV PPM	/-TWA Mg/H ³	VAPOR PRESSURE
Super Hi Flash Naphtha	64742-94-5	24.8	35	NA*	3.0
*Not applicable					
				Į.	
e	ction III—PHYSIC	AL DATA		!	
DEHIG ALVICE 315-400°F	Y	OR DENOMY	Bremen	DUCHTER 1	MA MA
VAPCRATICH FATE DEASIER DIKOWER THAN ETHER	PCP 811	CEH YOURE	GALLON WEISHI P	10.17	
Section IV—F	IRE AND EXPLO	SION HAZ	ARD DATA	\	
AMMABERTY CLASSIFICATION OSHA COmbus Class	tible Liquid II	rian fond *	r 120°C	·u	0.5
iteguseng nega	-	,021/11	,		
tom Kincolar Most	XONY	Owaten FOS	Dones		
ecomposition products may numediately apparent. Obta losed. Isolate from heat, losed containers may explo ot surfaces requires speci	in medical att electrical ed de when expose	n hazard tention. quipment, ed to exi	. Sympto: Keep co . sparks	ms may no ontainers and open	tightly flame.
Full protective equipme			onland b		2002424

Full protective equipment including self-contained breathing apparatus should be used. Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

Figure Bl. Vendor information: MIL-P-24441.

Section V--HEALTH HAZARD DATA 35-EF-51

EFFECTS OF CHENDROSUME

Inhalation: Anesthetic. Excessive inhalation can cause irritation of the respiratory tract, or acute nervous system depression characterized by the following progressive steps: Headache, dizziness, staggering gait, confusion, unconsciousness, coma and even asphyxiation.

Skin Contact: Moderate irritation, defatting, dermatitis. May be a sensitizer in some individuals.

Eye Contact: Severe irritation, redness, tearing, blurred vision. May be a sensitizer in some individuals.

Ingestion: Gastrointestinal irritation, nausea, vomiting, and diarrhea.

if breathing is difficult. Restore breathing if necessary. Treat symptomatically. Consult a physician.

Splash (skin): Wash affected areas with scap and water. Remove and launder contaminated clothing. Consult a physician if irritation persists.

Splash (eyes): Flush immediately with large amounts of water for at least 15 minutes. Take to a physician for medical treatment.

Ingestion: Drink 1 or 2 glasses of water to dilute. Do not induce vomiting. Aspiration of material into lungs due to vomiting can cause chemical pneumonitis which can be fatal. Consult physician or poison control center immediately. Treat symptomatically.

Section VI-REACTIVITY DATA

STANCET DUSTANCE XIMALE COMMON High temperatures accomplished when heated to decomposition as in welding.

HUZANDOUS POLYMENTATION DIMAT OCCUP. MEMEL NOT CCCUP.

Section VII—SPILL OR LEAK PROCEDURES 35-EF-51

THE TORIMINAL SERVICES PAGE Remove all sources of ignition (flame, hot surfaces, and electrical, static, or frictional sparks.) Avoid breathing vapors. Ventilate area. Contain and remove with inert absorbent and non-sparking tools.

Dispose of in accordance with local, state, and federal regulations. Incinerate in approved facility. Do not incinerate closed containers.

Section VIII-SPECIAL PROTECTION INFORMATION

In outdoor or open areas use Bureau of Mines approved mechanical filter respirator to remove solid air borne particles of overspray during spray application. In restricted ventilation areas use Bureau of Mines approved chemical-mechanical filters designed to remove a combination of particulate and gas and vapor. In confined areas use Bureau of Mines approved air line type respirators or hoods.

WHILLIAM All application areas should be ventilated in accordance to OSHA Regulation 29CFR 1910.94, 1910.107, 1910.108. Remove decomposition products formed during welding or flame cutting on surface coated with this product. If baking vent fumes.

motion continuous Recommended influencies Safety eyewear influency splash guards or side shields recommended

の政権が対象的に対象が対象が対象を対象を対象を対象を対象

wear and prevent prolonged skin contact with contaminated clothing.

Section IX—SPECIAL PRECAUTIONS

mcunosing intermediac motions. Do not store above 120°F. Store large quantities only in buildings designed to comply with OSHA 1910.106. Keep closures tight and container upright to prevent leakage. Do not store or use near heat, sparks or flame. Never use pressure to empty. Drum must not be washed out or used for other purposes. Drums of this material should be grounded when pouring.

Do not get in eyes. Avoid skin contact. Can cause allergic respiratory reaction. Can cause allergic skin reaction. Prevent prolonged or repeated breathing of vapor or spray mist. Avoid breathing of sanding dust. Close container after each use. Do not handle until the manufacturers safety precautions have been read and understood. Keep out of reach of children.

MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

Papered by U.S. Department of Labor "Lacomody Simbo" to Form (\$944.25).

GSF

	Section				
www.cr.#crswwc Mobile Paint Mf	g. Co., Inc.		BATE OF F	PREP	
STREET ADDRESS P. O. BOX 717	Off,	stapl and 24 coc	theodor	e, AL.	36590
еменденсу піценоне на. (205) 653—(монилом піценоне на. (205) 653—(110	MIL-1	poxy Coat P-24441/:	3A White	T/C Formu
MARIACTURENS COOR BENTFENTON 40-AW-23		152-C	omponent	λ	
Section	II—HAZARDOUS	INGREDI	ENTS		
KADUA	C.A.S. NO.	PERCENT BY WT.	TLV- PPM	-TWA Mg/H3	VAPOR PRESSURE
-Butyl alcohol		30.8	50*	150*	6.5
*This is a ceiling limit					
Sec	tion III-PHYSIC	AL DATA			
240-247°F	***	OR DELIGITY)	presen	DUGHTER TO	WH AR
rentement percently retents elikhostarom		COM VOLUNE COUNT C.E	MEGHAM SATON	11.94	
Section IVFI	RE AND EXPLOS	SION HAZA	RO DATA		
numburroussection OSHA - Combust Class 2		RAMASHI *	F 105°F ASH)	ıtı	1.4
iom Karcolor, Kool increme arou	Mary :)=1(A	Dones.		
ecomposition products may ommediately apparent. Obtailosed. Isolate from heat, losed containers may explodot surfaces requires specia	mergency conc ause a health n medical at electrical ed be when expose	itions of hazard.cention.quipment,ed to ext	overexpos Symptom Keep co	ns may no ontainer: and open	s tightly n flame.
Full protective equipments	t including	elf-cont	ained br	eathing	apparatus

Full protective equipment including self-contained breathing apparatus should be used. Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

Section Y-HEALTH HAZARD DATA

40-AW-23

EFFECTS OF OMENOMORAN

Inhalation: Anesthetic. Excessive inhalation can cause irritation of the respiratory tract, or acute nervous system depression characterized by the following progressive steps: Headache, dizziness, staggering gait, confusion, unconsciousness, come and even asphyxiation.

Skin Contact: Hoderate irritation, defatting, dermatitis. May be a sensitizer in some individuals.

Eye Contact: Severe irritation, redness, tearing, blurred vision. Hay be a sensitizer in some individuals.

Ingestion: Gastrointestinal irritation, nausea, vomiting, and diarrhea.

if breathing is difficult. Restore breathing if necessary. Treat symptomatically. Consult a physician.

Splash (skin): Hash affected areas with soap and water. Remove and launder contaminated clothing. Consult a physician if irritation persists.

Splash (eyes): Flush immediately with large amounts of water for at least 15 minutes. Take to a physician for medical treatment.

Ingestion: Drink 1 or 2 glasses of water to dilute. Do not induce vomiting. Aspiration of material into lungs due to vomiting can cause chemical pneumonitis which can be fatal. Consult physician or poison control center immediately. Treat symptomatically.

Section VI-REACTIVITY DATA

STABLET CONSTANT XSTART CONTROL TO CONTROL T

HIZHOOUS POLINE MEATON CHATOCOLA MINEL HOT OCCUR

Section VII-: , " OR LEAK PROCEDURES 40-AW-23

Surfaces, and electrical. As a functional sparks.) Avoid breathing vapors. Ventile - & contain and remove with inert absorbent and non-sparking to) a

and the state of t

Dispose of in acc dance with local, state, and federal regulations. Incinerate in as word facility. Do not incinerate closed containers.

Section VIII-SPEC.AL PROTECTION INFORMATION

In outdoor or open areas use Bureau of Mines approved mechanical filter respirator to remove solid air borne particles of overspray during spray application. In restricted ventilation areas use Bureau of Mines approved shemical-mechanical filters designed to remove a combination of particulate and gas and vapor. In confined areas use Bureau of Mines approved air line type respirators or hoods.

Regulation 29CFR 1910.94, 1910.107, 1910.108. Remove decomposition products formed during welding or flame cutting on surface coated with this product. If baking vent fumes.

monthetants Recommended transferor Safety eyemear including splash quards or vide shields recommended

wear and prevent prolonged skin contact with contaminated clothing.

Section IX—SPECIAL PRECAUTIONS

only in buildings designed to comply with OSHA 1910.106. Keep closures tight and container upright to prevent leakage. Do not store or use near heat, sparks or flame. Never use pressure to empty. Drum must not be washed out or used for other purposes. Drums of this material should be grounded when pouring.

Do not get in eyes. Avoid skin contact. Can cause allergic respiratory reaction. Can cause allergic skin reaction. Prevent prolonged or repeated breathing of vapor or spray mist. Avoid breathing of sanding dust. Close container after each use. Do not handle until the manufacturers safety precautions have been read and understood. Reep out of reach of children.

0291		LIMBRES	al Tec	HNICAL DATA	40-8N-5 Page 3 of 3
	MODUCT			Industrial McPoxY Coat 40-AW-23, #G-8H-5 with	
	TYPE VEHICLE			Epoxy/Polyamide	
]	WEIGHT PER GALLON			Haze Gray 10.1-10.6 #- #-White 10.3-11.3#	Oark Gray 10.0-10.3
,	NON-VOLATILE NEY WT.	·		71.0% 2 1.0% 55.5% ± 0.5%	
	THEORETICAL SPREADING RATE F	OR .		890 Square Feet	
	SUGGESTED DRY FILM THICKNESS PER COAT			2-3 mils	
DATA	SPREADING RATE - Loss must be and separate	considered d	hor to test	urt, percelly, our structural stape 70% to 80% of shearstest coverage	of surface, weather conditions, as fewers front above.
ESSENTIAL DATA	DRY TO TOLICH OR HANDLE (Ners DRY TO RECOAT (Nermel Condition	nul Condition		2 hours 8 hours	
128	COLSAS	·		Kaze Gray, White, Dari	Gray
-	траннея			McPoxY Thinner 75-37 f	
Ì	GLOSS OF DRY PART			White - Semi-Gloss Haze Gray and Dark Gra	y-Low Semi-Gloss
	ONY FILM RESISTANT TO FLASH POINT OF L S PAINT			Water, chemicals, abra	iston
	TYPICAL SURFACE	Interfer	Colorina	Understat fine	es de
Ì	3000 54rs	No	Но		
Ì	Trim, Panading, Dears				
í	Stringles, States		 		
_	Figure, Perthes, 300s	<u> </u>	<u> </u>		
0	914		, 		
5	Steel, tran (Particle)	Yes	Yes	40-C4-1 (MIL-P-2444)/	
FOR USE ON	Salvanizeo Steel			40-CM-1 (MIL-P-24441/) 40-CM-1 (MIL-P-24441/)	
	MASONEY, PLASTER ETC.	1.	1		
	Planter	Yes	1 NC	Self Prime	
ı	Concrete, Mesonry	Yes Yes	Yes		
	Authoritos Stand & Shington	Yes	Yes Yes	Self Frime	
	Cypoum Sound (Drymit)	Yes	lo lo	Self Prime	
	Fiber Board (Massacks)	Yes	Yes	Self Prime	
1	Gen Testured Stock	Tes	Yes	Fill is of Prime	
i	France, Partition, Stage	Yes	Tes	(東) 作(東	
	Metal sacrair sain				
	Udday' Varcent' pela				

Figure Bl (Cont'd).

Amercoat 99HS

Vinyl Chloride Copolymer

สไทายาบท.

High solids, high build, sprayable viny! topcoet Economical - 5 mile in a single cost

Resistant to a wide range of chemicals

All purpose maintenance coating for protection on primed steel, concrete, aluminum and gelvanized surfaces

Conforms to U.S. Department of Agriculture requirements for use on ateel in most packing plants

A feet-drying coeting which can be applied over inorganic zinc

Typical Uses

Protection against splash, spitage and turnes of corrosive chemicals, water, weathering and abrasion on primed steel, concrete, aluminum, galvanizing. Dimetoxe⁸ surfaces, chemical process plants, paper mās. marine structures and tank

Outstanding Characteristics Americal 99HS is a

high-performance chemical- and corresion-resistant very chience copplymen The cost is lower per square foot due to its high solids content and high build per coat necessitating fewer coats to achieve the desired thickness. It is resistant to a variety of chemical and weather environments and STREET SES COOK AND SUMBCE appearance Americal 99HS is a fast-drying.

all-purpose maintenance coacho which can be applied over

morganic as well as organic zinc

Application Data Summary

For complete information on procedures, equipment and salety precautions, see delated Application Instructions Americal 99HS must be applied as recommended to obtain maximum performarics. Surface Preparation—Refer to Americal 99HS Application instructions or primer to be used Equipment.--Use standard industrial soray equipment, either ainess of conveniences Safety—Since improper use and handing of American 99HS can be hazardous to hearth and cause hire or exploys in, safety precautions included with the Applications instructions must be observed during all storage. handing.use and drying periods

Physical Data

Finish	Flot
Celor	White; see color cord for
	feli range of industrial
	colors
Surface	
	5 mile (125 µ) per ceet
After the profession has	a and surless irrestabilities.

	(conventionel)
Calculated enverage at 5 mil (25 µ)	. #41 ac 9/ gal (16 aq m/lb)
	.129 on 9/gai (3.2 oq m/lir)
	.Airtees or conventional
	oproy

Americant 8 (above 76°F)
Americant 10 (below 70°F)

12 room!

5-gas wink (26.0 kg)

.1 year from shipment when stored indeors

Registança Table

	Splash and Spelage	Atmospheric
Acids	Good	Excellent
Afrais	Good	Excellent
Alcohols	Good	Good
Sais	Excellent	Excellent
Petroleum products	Good	Good
Food products	Good	NA.

rock! 9945 phoust not be exposed to become, estern or hydrocarbons of hydr ARTERIO COMMI

Figure B2. Vendor information: Ameron system.

Amercoat* 99HS

Recommended Systems Using Americal 90HS

Substrate	Primer	No. of Costs for Americal 99HS
Dimetcote*		1-2
Steel	86, 62, 185, 160, 71	1-2
Concrete, Sigmourn galvanizing	85. 185	1-2

This chart and resistance table are only guides to show typical recommendations for Americal 99% in specific espoisizes and recommendations, presest contact your Americal appresentative who will help you evaluate your personal contours protection reads.

"When Americal 98+5"-is applied directly over inorganic prics or binc-rich primers a "mall cost" may be required to minimize application bubbling. See Application Instructions.

Warranty

Ameron's products are warranted to be free of defects in material or workmanship if a product does not conform with this Warranty. Suyer must notify Ameron webso five days of discovery of the defect, but in no event later than one year after desivery date or after expiration of the applicable shedilite, whichever is shorter. Ameron's sole obligation under this Warranty shall be at its cotion, to credit Buyer's account, or to succely replacement material or repair, Failure to notify Ameron of nonconforming goods under this Werranzy, within the time specified above, shall bar Buyer from recovery hereunder.

It is expressly understood that Ameron makes no other warranties concerning the goods, and the sole remedy of the Buyer and the sole liability of Ameron for product detect shall be an act forth above. No other warranties, express or implied, whether of merchantability or of fitness for any perticular use shall apply. Ameron shall not be responsible for consequential demages.

Any recommendation or suggestion relating to the tips of the products made by Arraron either in technical literature or in response to specific inquiry is given in good faith, but it is for Buyer to satisfy itself of the suitability of the goods for its own perfectly purpose and it will be deemed to have done so.



C 1884 Armer 18 April Appropriate 1844 Appropriate 1844

Application Instructions Amercoat* 86 Synthetic resin inhibitive primer

Amercoat 86 is a synthetic resin inhibitive primer used as a maintenance or marine primer for a wide range of topcoats.

To obtain the maximum performance for which Americat 86 is formulated, strict adherence to all application instructions, precautions, conditions and limitations is necessary.

Surface Properation

Steel

Nonmmersion—New steel without pits or debrussions; blast in accordance with SSPC-SP6*, Commercial Blast. Previously painted or pitted steel; blast in accordance with SSPC-SP10*, Near White, For mild exposures; power tool cleaning in accordance with SSPC-SP3* is acceptable.

Immersion.—Stast all steel in accordance with SSPC-SP10*, Near White as a minimum. Blast to achieve a 1 mil (25 µ) profile as determined with a Keane-Tator Surface Profile Comparator or similar instrument. Permove attrasive residue and dust from surface. Apply Americal 36 as soon as possible to prevent rusting or other recontamination.

Newly gelvanized surfaces—Remove any ollor soap lim with neutral detergent or emission deaner. Use zinc treatment such as Galvaprep by Amchen Products, Ambier, PA.

Weathered galvanized surfaces—if galvanizing has been exposed to exterior weathering for 6 months or more, remove corrosion with hand or power sander. Remove any of or crease.

Dimetople*--Surface must be clean and dry Remove any confamination including ouring residue, if surface is glazed, roughe 1 by sweep-blasting

"Sied Seucones Pilliang Council Specifications

Refer to application instructions for the particular Dimeticate for any other special lopopating requirements.

and the same of the same of

Aluminum surfaces—Remove oil, grease, etc. Apply chromate-type conversion treatment such as Alodine 1200 by Amchern Products, Ambler, PA, or lightly blast with fine sand.

Previously coated surfaces—All surfaces must be tree of oil and grease. Soot blast to exposed metal or mechanical process to other contaminants. Before using Americal 86, test to see if scivaries in Americal 86 will cause winding, bleeding or lifting of coating.

Environmental Conditions

Air temperature—35 to 120°F (1.7 to 49°C)

Surface temperature -- 35 to 120°F (1.7 to 49°C)

The surface temperature must be at least 5°F (3°C) above the dew point to prevent mosture condensation.

Application Equipment

The lottowing equipment is listed as a partial guide and suitable equipment from other in liabilities may be used. Adjustments oil pressures and change of to size may be needed to achieve the proper spray characteristics.

Airless spray—Standard airless spray equipment such as Graco Buildog Hydra-Spray or larger with a 0-013-in to 0-015-in onlice

Conventional spray—Industrial equipment such as DeVitoss MBC or JGA spray gun. Separate regulators for as and fluid pressure, mechanical pot agriator and a mosture and oil trap in the main as supply line are recommended.

Power more—More such as Jilly More, manufactured by the Jilly More

Company, Inc. San Francisco California powered by an exprosion-proof electric motor

Application Procedure

- 1 Clean equipment with American 12 before use
- Str material thoroughly with a power mixer until uniformly blended to a workable consistency
- 3 Thin with up to 1 pint Americant 9 per gallon of Americant 86 for brush or roller, 1 quart Americant 9 per gallon of Americant 86 for spray Use only Americant 9 for thinning
- 4. Apply a heavy, well coat in even, parallel passes overlapping each pass 50% to avoid holidays, bare areas or pinholes.
- 5 Double coat all weids, rough spots, sharp ediges and corners, rivels, boils, are
- 6 For concrete surfaces, thin first coat with equal parts of Americal 9 only. Apply by brush. Apply second coat by spray brush or roller. Extremely rough, pried or porous concrete may require additional coats.
- 7 Allow at least one rour at 70°F (21°C) before recoating or handling
- 8 Clean all equipment with American 12 immediately after use

Safety Precautions

Cautorii Combustible Contains MiBK, cyclonexanone and glycol ether ester lintating to skin, eyes and mucous membranes. Innatation of high cyncentrations of vapors can cause headache. Hausea or dizzness. Keep away from open fame, heat or spanis. Avoir) breathing of vapor or skin and eye contact. Keep container closed when not in use. Use abequate ventilation. Year approved respiratory equipment and skin and eye protection.

First aid.—Excessive exposure to vapor, provide fresh air. Give artificial respiration if breathing is labored. For skin contact, wash thoroughly with soap and water for eyes, flush immediately with plenty of water for at least 15 minutes and get medical attention. Launder contaminated clothing before reuse.

In case of fire—blanket flames with dry chemical, carbon dioxide or foam. Wear self-contained breathing apparatus

in case of spillage -- eliminate all sources of ignition Absorb and dispose of an accordance with all applicable regulations improper use and randing of this productican be nazardous to health and cause fire or explosion. Consult Code of Federal Requisitions Title 29. Labor, parts 1910 and 1915 concerning occupational salety and health standards and regulations, as well as any applicable state and local requiations on safe practices in coating operations. Necessary safety equipment must be used and ventialism requirements Carefully observed, especially in confined or **EDCXXSECLSORCES**

If you do not fully understand these warrangs and instructions, or if you cannot strictly comply with them, do not use the product.

THE RESERVOIS OF THE PROPERTY OF THE PROPERTY

Notice—This product is for industrial use only

Warrant

Ameron's products are warranted to be free of defects in material or workmanship If a product does not conform with this Warranty, Buyer must notify Ameron within five days of discovery of the defect, but in no event later than one year after delivery date or after expiration of the applicable shelf Me, whichever is shorter Ameron's sole obligation under this Warranty shall be at its option, to credit Buyer's account, or to supply repracement material or repair Parture to notify Ameron of nonconforming goods under this Warranty, within the time specified above, shall bar Buyer from recovery Name of

It is expressly understood that Ameron melies no other warranties concerning the goods, and the sole remedy of the Buyer and the sole liability of Ameron for product defect shall be as set forth above, No other warranties, express or implied, whether of merchanishity or of fitness for any particular use shall appty. Ameron shall not be responsible for consequential demages.

Any recommendation or suggestion relating to the use of the products made by Ameron wither in technical literature or in response to specific inquiry is given in good faith, but it is for Buyer to satisfy itself of the suitability of the goods for its own particular purpose and it will be deemed to have done so.

2011-John Berry Steel Bey Carbonia 20121



g did Amer (QC) nament (QC) Senten (QC)

Safety Precautions

To protect personnel against toxic hazards

To prevent fire or explosion

Whenever coatings containing vo latile solvents or toxic substances are used, proper ventilation and protective measures must be provided during application and drying to keep solvent vapor concentrations within safe limits and to protect personnel against toxic hazards. This is especially true in contined spaces such as tank interiors. Consult Code of Federal Regulations Title 29, Labor, parts 1910 and 1916 concerning occupational safety and health standards and regulations, as well as any applicable state and local regulations on safe practices in coating operations. Necessary safety equipment must be used and ventilation requirements carefully coserved, expecially in confined or enclosed spaces.

Keep solvent-containing materials away from heat, sparks, and open flame. Avoid innalation of vapors or spray mist. Avoid contact with eyes or skin. Keep containers tightly closed and upright to prevent leakage when not in use

Refer to application instructions for the material being applied for further detailed safety precautions. Department of Labor Material Safety Data Sheets are available on request.

If you do not fully understand these wernings and instructions, or if you cannot strictly comply with them, do not use the product.

Notice — This product is for industrial use only

201 North Serry Street Bree, California 97521 (714) 529-1901



ay processors are to Amend a g S SS-

MATERIAL SAFETY DATA SHEET

NPCA 1-

FOR COATINGS, RESINS AND RELATED MATERIALS

DATE OF PREP 5-13-81	eix of Labor "Essentiali	y Similar In Form	OSHA-20:		······································
	Section I				1071-248
PLAS-CHEM COATINGS	5901 W. Beav	04) 786-0121 er Street	l		
	(904) 786	0121			
PRODUCT CLASS			E IDENTIFICATION	H	
2 Component Epoxy TRADENAME	21	35-1 White	F1N15N		
MIXED Section II — H.	AZARDOUS I	NGREDIE	NTS		
INGREDIENT	PERCENT	PPM SI	in me/m²	LEL	e 20 VAPOR
2-Ethoxy Ethanol	less than	100	370	1.0	5.3 @ 25° (
SC-100	30	100	***	1.0	< 1
N-Butyl Alcohol	less than	50	150	25° C	4.39
NButyl Acetate	iless than	150	710	1.7	7.8
Coaling	II — PHYSICA	N. OATA			
BOILING FANGE	WPORDE		HEMIER	LICHTE	THAN AIR
243-262° F EVAPORATION RATE RASTER X SLOWER THAN ETHER	PERCENT VOLATI BY VOLUME	LE 52	WEIGHT FER GALLON	10.2 ±	.15
Section IV — FIRE	AND EXPLOS	ION HAZ	ARD DATA		
COT CATEGORY Flammable Liquid-Class 1 C EXTINGUISHING MEDIA	FLASH POI	нт 76° F	TCC		LEL 1.0
Chemical Extinguishers Foam, Sand , CO ₂					
unusual fire and explosion hazards None					
SPECIAL FIRE FIGHTING PROCEDURES					
Prevent spread of fire by cooling adjacent	containers w	ith water	fogging or	removal	if

Figure B3 (Cont'd).

possible.

Section V — HEALTH HAZARD DATA
THRESHOLD LIMIT WALUE
EFFECTS OF OVEREXPOSURE
Inhalation: Dizziness, headache
Skin Contact: Redness, rash
EMERGENCY AND FIRST AID PROCEDURES
Inhalation: Fresh air
Skin contact: Wash with soap and water; apply hand cream
Eye contact: Rinse with large amounts of water
Section VI — REACTIVITY DATA
STABILITY UNSTABLE XX STABLE CONSTTONS TO AVGIO
INCOMPATABILITY (Meterola to guida) MAZARDOUR DECOMPORITION PRODUCTS
Carbon monoxide and carbon dioxide
MAZARDOUS POLYMERIZATION MAY OCCUR XX WILL NOT DCCUR CONDITIONS TO AVOID
Section VII — SPILL OR LEAK PROCEDURES
steps to be taken in case material is released on spriled
Scoop up in container - Sinse with water
Burying or incineration in accordance with local, state, and federal regulations
Section VIII — SPECIAL PROTECTION INFORMATION
RESMRATORY PROTECTION
Not normally necessary when working with small amounts. For large spray applications, BU Mines filter respirator for organic solvents is edvisable.
YENTRATION
Exhaust ventilation from enclosed areas recommended
PMOTECTIVE OLOVES protective hand cream
EVE PROTECTION GOGGT ES
other protective eguipment
Section IX — SPECIAL PRECAUTIONS
PRECAUTIONS TO BE *** THIN HANDLING AND STORING
Do not see in direct sun. Keep protected from exposure to heat.
OTHER PRECAUTIONS

Figure B3 (Cont'd).

Do not use in c represently to heat and open flame welding and other ignition hazards.

MATERIAL SAFETY DATA SHEET

NPCA 1-

FOR COATINGS, RESINS AND RELATED MATERIALS

DATE OF PREP 5-13-81	ent of Labor "Essential	y Similar 10 Form	O\$HA-20;		·
	Section I				1071-249
PLAS-CHEM COATINGS	P.O. Box 4024 (94 5901 W. Beav (904) 786	04) 786-012: er Street	1		
PRODUCT CLASS	MANUI	ACTURERS CO	E IDENTIFICATIO	M	
2 Component Epoxy TRADENAME	21	35-1 White	Finish		
MIXED Section II — HA	AZARDOUS	NGREDIE	NTS		
INGREDIENT	PERCENT	PPM S	uy cin _{mg/m} ,	LEL	2 ZAMESEURE
2-Ethoxy Ethanol SC-100 N-Butyl Alcohol NButyl Acetate	less than 5 30 less than 5 less than 5	100 100 50 150	370 150 710	1.0 1.0 1.2 @ 25° C	5.3 @ 25° <1 4.39 7.8
Section !	II — PHYSIC				
BOILING RANGE 243-262° F EVAPORATION RATE RASTER X SLOWER THAN ETHER	PERCENT VOLATI		MEIGHT PER GALLON		.15
Section IV — FIRE	AND EXPLOS	SION HAZ	ARD DATA		
COT CATEGORY Flammable Liquid-Class 1 C EXTINGUISHING MEDIA Chemical Extinguishers Foam, Sand, CO2 UNUSUAL FIRE AND EXFLOSION HAZARDS None	FLASH PO	нчт 75° F	TCC		ιει 1.0
SPECIAL FIRE FIGHTING PROCEDURES				_	

Figure B3 (Cont'd).

possible.

Section V — HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE See Section II
Errectsorovemearcosume Inhalation: Dizziness, nausea, headache
Ingestion:
Skin contact: Eczema, rash
EMERGENCY AND PIRST AID PROCEDURES
Eye contact: Flood with stream of water Inhalation : Fresh Air
Ingestion ; Call Physician for advice. DO NOT induce vomiting Skin contact. Wash off with solvent, followed by soap and water
Section VI — REACTIVITY DATA
STABILITY UNSTABLE WAS STABLE AT NORMAL CONDITIONS TO AVOID INCOMPREABILITY (Materials Responsion Conditions Extreme heat
HAZARDOUS DECOMPOSITION PRODUCTS
Carbon Mono and Dioxide.
MAY OCCUR TO AYOIC
Section VII — SPILL OR LEAK PROCEDURES
STEPS TO BE TAKENING CASE WATERIAL IS RELEASED OF SPILLED SCOOP up in container using non-sparking tools. Soa remainder up with sand. Keep waste in closed container for disposal. Clean with suitable solv
under proper ventilation.
: wastedisposal method. Dispose of waste by burying or incineration in accordance with local, state and federal regulations.
Section VIII — SPECIAL PROTECTION INFORMATION
RESPIRATORY PROTECTION Bu Mines approved filter respirator for organic solvents.
VENTILATION SHUllion ventilation from lower reaches of enclosed areas.
PROTECTIVE GLOVES Protective skin cream recommended.
EVERNOTECTION GODD SS
OTHER PROTECTIVE FOUNDMENT
Section IX — SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store in well ventilated area protected from undue exposure to heat, sun and freezing.
отмहक PRECAUTHY Use explosion proof lights abd motors in work areas. Avoid welding and other ignition hazards in vicinity of use or handling.



Plas-Chem Coatings TECHNICAL BULLETIN

Chem-Pon 2135 Epoxy Lining System

6-15-80

GENERAL DESCRIPTION

The Chem-Pon 2135 coating system consists of one primer and one finish. It is a unique, modified epoxy-polyamide that combines a rapid cure with unusually long pot life. This system is specifically designed to resist all types of aviation fuels, water and aliphatic solvents in immersion service. It also has good resistance to many herbicides, fungicides, pesticides and fumigants. Chem-Pon 2135 has outstanding adhesion, impact resistance and resistance to steam. It complies with MILC-4556C and is on the qualified product listing for aviation fuels.

As a lining system over sandblasted metal to line tanks, for jet and aviation fuels, gasoline, aliphatic hydrocarbons, water and salt water subject to temperatures up to 140° F. It may also be used as a lining material for certain herbicides, fungicides at various concentrations. Chem-Pon 2135 may be used for external and splash zone use in the same application as well as splash zone protection for alkali or acid environments.

PHYS'CAL PROPERTIES

Chemical Resistance: Acids - Good

Alkalis - Very Good

Water - Excellent

Solvents - (Aliphatic) Excellent

Salts - Excellent Herpicides - Very Good * Pesticides - Very Good *

200° F. Continuously; 230° F. Intermittently Temperature Resistance:

Flexibility: Good

Very Good (Moderate Chalking) keathering:

Abration Resistance: Excellent

Primer - 68% 1 by weight, 50% 1 by volume Solids (Catalyzed 4:1 by volume):

Finish - 62%-1 by weight, 50%-1 by volume

Theoretical Coverage: 802 mil square feet per gallon

Recommended Coverage: Minimum 3 mils per coat (Fuel Service)

Standard 5 mils per coat

Number of Coats: I each of primer and finish

SSPC-SP5-63 for immersion lining applications Surface Preparation:

Plas-Chem Coatings • 1001 West Beaver Street • Jacksonville, Florids 32205 Mailing Address: P.O. Box 40246 * Jacksonville, Florida 32203 ● Telephone (904) 786-0121

g dag an bang da kata pangang in palang ang ang ang ang maring matan as a mag (ang naman ing bangan) na gamai ang bang da da nai da Pagat pagang in canagga bang marca or mag "banag campang naran matang da a kanaganggan in hai ma product in campa

PHYSICAL PROPERTIES (cont'd)

Colors:

Primer - Orange

Finish - Off White

Flash Point:

 $95^{\pm}5^{0}$ F. Pinsky Martin 115-50 F. COC

APPLICATION

Method:

Spray, brush or roller

Pot Life:

Minimum of 8 hours

Mixing Ratio:

4 parts of base to 1 part of catalyst by

Dry Time:

18 hours @ 75° F. between coats Final - 36 hours @ 75° F.

Thinner:

Standard: No. 146 Thinner

Military Thinner: Chem-Pon 2136 Thinner

Clean Up:

MEK or any of the above thinners

ORDERING INFORMATION

Availability:

lk gal. kits (1 gal base and k gal catalyst) 5 gal kits (4 gal base and 1 gal catalyst)

Approximate shipping weight:

Primer Base 12.5 lbs. per gal. Finish Base 11.7 lbs. per gal. Catalyst 2.5 lbs. per quart

Freight Classification:

Paint compound NOIBM Non-Red Label

*Due to many types and variations of these materials, contact Plas-Chem Coatings. Technical Services Dept. for specific recommendations before using in immersion service.



Plas-Chem Coatings APPLICATION INSTRUCTIONS

CHEM-FON 2135
MEETS MIL-C-4556 C
FOR JET FUEL SERVICE

2-1-83

SURFACE PREPARATION

- 1. Immersion Service
 - a. Sandblast to white metal in accordance with Steel Structures Painting Council Blast Specification (SSPS) SPS-63T. Mil profile shall be a minimum of 1.5 -2 mils.
 - b. Remove all loose dirt and abrasive media by vacuuming or sweeping.
 - c. Apply prime coat of material as soon as possible after blasting to prevent re-rusting.
 - d. If re-rusting has occurred, surface should be reblasted.
- 2. Non-Immersion Service
 - a. Sandblast in accordance with SSPC SP6-63 Commercial Blast.
 - b. Remove blasting dust by blowing surface with clean dry air free of oil and moisture.
 - c. Paint surfaces before re-rusting occurs.

HIXING

- Hix materials (base and catalyst) as supplied in kit form. Hixing ratio is 4 parts base to 1 part of catalyst by volume.
- 2. After mixing base and catalyst, allow 1/2 hour induction time before applying.

POT LIFE: Less than 15 % viscosity increase in 6 hours at 750 F.

THINNING: None normally required. However, if circumstances should dictate, use only a thinner and amounts listed below.

- a. Military Specification: Use only Chem-Pon 2135 M.S.T. Thinner up to 1/2 pint per gallon of mixed material.
- b. Non-Military Specification: Use Plas-Chem No. 146 Thinner up to 1/2 pint per gallon of mixed material.

Plas-Chem Coatings • 5901 West Beaver Street • Jacksonville, Florida 32205 Mailing Address: P.O. Box 40246 • Jacksonville, Florida 32203 • Telephone (994) 786-0121

These also der bestrag on vigity provided to improdue and are grown on communications. The constitution are to begand an expert and desired and extends any edition of confidence of the confide

APPLICATION

AIRLESS

Pump: 30:1 or larger

Oriface: .013-.029 depending on volume

requirements

Angle: 40 ~ 60 depending on surface requirements. Work close to surface to minimize drift and

drop out.

Hose: 5/16" STD High Pressure Fluid

Pressure: 2600-3000 PSI

Thinning: None normally required

CONVENTIONAL AIR

Pressure pot or 2:1 fluid pump

Guns: 3inks 7, 18, 19, 62 DeVilbiss JGA, MBC or PMBC

Fluid Tip: .041-.070

Air Cap: 7-13 CFM

Hose: 3/8" ID Fluid Hose

Pos Pressure: 5-20 PSI depending on

hose length.

Atomizing Pressure: 45-65 PSI

Thinning: None normally required

Brushing or rolling is not recommended for immersion applications and should be used for touch up work only. Use High Quality natural bristle brush of medium length. Apply by flowing long strokes. Avoid re-brushing. Rolling - Use lambswool or mohair phenolic core roller of appropriate knapp length. Roll in one direction. Avoid "scrubbing" of surface.

THEORETICAL COVERAGE: 800 mil square feet per gallon.

INTER-COAT TIME: 18 hours at 75° F (Military Specification).

12 hours at 90° F

CURING: If possible, due to the slow suivent system used, it is advisable to force high volumes of slightly warm air at 750-850 F for two hours through enclosed tanks. Increase temperature to 1150-1250 F for 8 - 10 hours.

CURE TIME: 3 days at 750 F

For shorter time see "CURING".

CLEAN-UP: Plas-Chem No. 146 Thinner, Mil Spec Thinner, or MEK.

CAUTION:

1. Contains flammable solvent.

- Keep away from open flame and sparks. Use only approved explosion proof equipment. In tank lining applications workmen must wear Air Respirators provided with a source of fresh air.
- 3. Remove any spilled catalyst from hands or skin at once with water, then wash with soap and water.
- If catalyst is spilled on clothing, remove clothing at once, wash skin as above.
 Hix and apply Chem-Pon 2310 in a well ventilated area. Keep away from sparks and open flame. In tank lining applications, workmen must wear air respirators
- equipped with a source of fresh air.
 HYPERSENSITIVE PERSONS SHOULD WEAR GLOVES OR USE PROTECTIVE CREAM. ALL ELECTRIC EQUIPMENT AND INSTALLATIONS SHOULD SE MADE AND GROUNDED IN ACCORDANCE WITH THE NATIONAL ELECTRICAL CODE. IN AREAS WHERE EXPLOSION HAZARDS EXIST, WORKHEN SHOULD BE REQUIRED TO USE NON-FERROUS TOOLS AND WEAR CONDUCTIVE AND NON-SPARKING SHOES,

CERL DISTRIBUTION

	OBKE DISTRIBUTION	
Chief of Engineers	ēth USA, * crea	HINC
ATTN: Tech Monteur ATTN: DAEN-ASI-L (2)	ATTN EAFE-H 96271 ATTN: EAFE-P 26259 ATTN: EAFE-T 96212	ATTH: HTMC-SA 20315
ATTH: GAEN-CCP	ATTN: EAFE + 76259	ATTH: facilities Engineer
ATTH: DAEN-CH	MISA: CM.C-1 ABCIC	Oakland Army Sase 94626 Bayonne MQT 07002
ATTS: DAEN-GYE	ACK/US Combined Forces Compand 36301	Sunny Point HOT 28441
ATTE: DAGE-COR-G	ATTN: EUSA-AMC-CFC/Engr	Jumy 1 47/11 Car Car
ATTN: DAEN-CZO		MARAGOM, ATTM: 00094A-F 071160
ATTN: DAEN-COP ATTN: DAEN-EC	USAJ) magal Agu	
ATTK: DAEN-ECC	Ch. FE DIY, AIEX-FE 96341	TARCOM, Fac. 01v. 48090
ATTX: DALM-ECE	Fac ingr (Nonship) 96363	TRACOC
ATTH: DAEK-ZCF	Fac (ngr 10kinewa) 95331	HO, TRACOC, ATTN: ATEN-FE
ATTN: CAEN-ECB	Pocky Rt. Area 前時以	ATTN: Facilities Engineer
ATTN: DAEN-NO	3000	Fort Belvair 22060
ATTR: CAER-RCC	Area Engineer, AEDC-Area Office	Fort Benning 31905
ATTE: DAEN-BOM	Armold Air Force Station, TH 37389	Fort 31155 79916
ATTH: CAEN-RM ATTH: DAEW-ZCZ		Carlisle Barracks 1701)
ATTH: DAEN-ZCE	western Area Office, CE Tanderberg AFB, CA 33437	Fort Chaffee 72902 Fort Dix G6640
ATTN: GAEN-ZCI	•	Fort Ecitis 23604
ATTN: DAEN-ZCH	416th Engineer Commans 50623	Fort Gordon 309C5
	ATTN: Facilities Engineer	Fort Hamilton 11252
FESA, ATTM: Library 22040	·	Fort Benjemin Harrison 46216
FESA, ATTN: DET ELL 79506	US Military Academy 10495	Fort Jackson 25207
763A, A114: 961 (EC 17904	ATTM: Fectifities Engineer ATTM: Dept of Goography &	Fort Cock 40121
US Army Engineer Districts	Computer Science	Fort Leavenuorth 56027 Fort Lee 23801
ATTN: Library	ATTH: DSCPERMAEN-A	Fort McClellas 36205
Alaska 99501	and a second sec	Fort Menroe 23651
Al Batin 09616	Engr. Studies Center 20315	Fort Rucker 36342
Albequerque 27103	ATTH: Library	Fort 5113 73203
Builtimore 21203		Fort Leomard Wood 65473
Baffelo 14207 Cherlestan 25402	MORC, ATTH: DRIME-WE 02172	701000 1900. 17516 5 43130
	USA MARCON 61299	TSANCOM, ATTH: STSAS-F 63120
Detreit 482)1	ATTN: OFCIS-RI-I	USACE
Far Eest 96301	ATTN: DRSAR-IS	ATTE: Facilities Engineer
Fort Worth 76102	••••	Fort Huschuca 85613 (2)
Gallvestan 77550	DANCOR - Dir., Inst., & Sucs.	Fort Attchie 21719
MENERALINATION TOLLS	ATTN: Facilities Engineer	
Jacksonville 32232 Japan %343	AMAGEON 97801	VESTCOM
EAAS45 C1ty 64106	Aberdeen Printing Ground 21005	ATTH: Facilities Engineer Fort Shafter 96658
Listle Bock 72203	Army Matls, and Mochanics Eas. Ctr. Corpus Christi Army Deput 76419	ATTN: MEN-IR
Los Angeles 9005]	Marry Diamond Laboratories 20763	1119. 774-1A
Lowisville 40201	Deguty Proving Scoons \$4022	SHAPE 01055
Hemphis 38103	Jefferson Proving Ground 47250	ATTE: ServiceDility Section, CCS-OFS
Madfie 36628	Fort Formeuth 07703	Infrestructure Scanch, LANGA
MesArville 37202 New Espland 07154	Letterteeny Army Joset 17261	und understehen Schiede
New Orleans 7016G	Matick 980 Ctr. 01760 New Cumberland Army Sepat 17070	NO USEUCOM 09126 ATTH: EC2 4/7-LOE
the Tork 10007	Pueblo Army Depot \$1901	#11#. 100 1//-tot
worfelk 23510	Sed River Army Sepot 75501	Fort Belveir, VA 22060
Ometre 68192	Redstone Arsenal 35899	ATTN: ATZA-OTE-EM
Omehe 68192 Philadelphia 19106	Sack (sland ferage) 61790	ATTW: ATZĀ-OTE-EP. ATTW: ATZĀ-OTE-SW
Omehe 68102 Philadelphia 19106 Pittshargh 15222	Rock Island Arzenel 61299 Savance Army Depot 61274	ATTW: ATZĀ-OTE-EP. ATTW: ATZĀ-OTE-SW
Omehe 68102 Prilledighte 19106 Pistchurgh 15222 Pertland 97208	Rock Island Argenel 61299 Savanca Army Depet 61074 Sharpe Army Gepet 95331	AITH: ATZA-9TE-EM AITH: ATZA-9TE-SW AITH: ATZA-FE AITH: Empr. Library
Omeho 68102 Prillodelphio 19106 Pistokurgh 15222 Pertiana 92208 Riyadh G9036	Rock Island Artenal 61299 Savanca Army Depot 61874 Sharpe Army Depot 95331 Secoca Army Depot 18541	ATTW: ATZA-OTE-EM ATTW: ATZA-OTE-SM ATTW: ATZA-FE ATTW: Empr. Library ATTW: Cambrian Listson Office (2)
Omehe 58102 Prilodelpale 19106 Fitthwesh 15222 Pertland 97208 Rlyash 09035 Apriloland 51201	Rock Island Artena! 61299 Savanca Army Depot 61874 Sharpe Army Gepot 95331 Sereca Army Depot 18541 Tobysanna Army Depot 18466	AITH: ATZA-9TE-EM AITH: ATZA-9TE-SW AITH: ATZA-FE AITH: Empr. Library
Omeho 68102 Prillodelphio 19106 Pistokurgh 15222 Pertiana 92208 Riyadh G9036	Rock Island Artenal 61299 Savanca Army Depot 61874 Sharpe Army Depot 95331 Secoca Army Depot 18541	ATTW: ATZA-OTE-EM ATTW: ATZA-OTE-SM ATTW: ATZA-FE ATTW: Empr. Library ATTW: Cambrian Listson Office (2)
Omehe 68102 Priladelpate 19106 Pitthurph 15222 Portlend 97208 Riyash 09038 Apok Island 61201 Secrements 95614 San Francisco 94105 Sivennes 18402	Rock Island Artena! 61299 Savanca Army Depot 61874 Sharpe Army Depot 95331 Sereca Army Depot 18541 Tobyscone Army Depot 18466 Tecele Army Depot 84674 Matervilot Artena! 12189 Tume Praving Groupe 85364	ATTH: ATZA-OTE-EM ATTH: ATZA-ETE-SA ATTH: ATZA-EE ATTH: Empr. Library ATTH: Commetion Lideson Office (2) ATTH: INR Library
Omehe 68102 Prilledights 19106 Pfittherph 15222 Portland 97208 Riyash 09036 Ack Island 61201 Secrements 95814 San Francisco 94105 Savanneh 31802 Seattle 98124	Rock Island Artenat 61299 Savance Army Depot 61874 Sharpe Army Depot 95331 Sereca Army Bepot 14541 Tobyschne Army Depot 14541 Tobyschne Army Depot 94074 Watervilot Arsonal 12189	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Engr. Library ATTH: Commodian Listean Office (2) ATTH: Library Cold Regions Research Engineering LAD 03755 ATTH: Library
Omehe 68102 Prilledights 19106 Pittshurgh 15222 Pertland 97208 Riyesh 69036 Asck Island 51201 Secrements 55814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 61101	Rock Island Artenet 61299 Savance Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 56331: Serece Army Depot 14541 Tobyschne Army Depot 14546 Terele Army Depot 94074 Metaroliet Arsenet 12189 Tune Praving Graude 85364 White Sands Rissile Range 88062	AITH: ATZA-OTE-EM AITH: ATZA-OTE-SA AITH: ATZA-FE AITH: Empr. Library AITH: Camedian Listen Office (2) AITH: INR Library Cold Regions Research Engineering LAS 03755
Omehe 58102 Priladelpale 19106 Pittshargh 15222 Pertland 91208 Riyash 09035 Reck Island 51201 Secrements 95614 San Francisco 94105 Savannah 31802 Seattle 98124 St. Louis 61101 St. Pagl 55101	Rock Island Artena! 61299 Savanca Army Depot 61874 Sharpe Army Depot 95331 Sereca Army Depot 18541 Tobyscone Army Depot 18466 Tecele Army Depot 84674 Matervilot Artena! 12189 Tume Praving Groupe 85364	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Empt. Library ATTH: Canddian Liston Office (2) ATTH: Library Cold Regions Research Engineering LAS 03755 ATTH: Library 22060
Omehe 68102 Priladelphie 19106 Pfittherph 19222 Portland 97208 Riyadh 69036 Ack Island 81201 Secrements 95814 San Francisco 98105 Savanneh 31802 Seattle 98124 St. Louis 61101 St. Peil 55101 Igiaa 74102	Rock Island Artena: 61299 Savanca Army Depet 61074 Sharpe Army Depet 61074 Sharpe Army Depet 50331 Sereca Army Depet 14541 Tobyschna Army Depet 16546 Texele Army Depet 86074 Matervilet Arsonal 12189 Tyme Praving Graude 95364 Mite Sands Riss'te Hange 80062 GLA ATTW: DLA-W1 22214	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Engr. Library ATTH: Concilon Listen Office (2) ATTH: Library Cold Regions Research Engineering LAD 03755 ATTH: Library 22060 Waterways Experiment Station 38180
Omehe 58102 Priladelpale 19106 Pittshargh 15222 Pertland 91208 Riyash 09035 Reck Island 51201 Secrements 95614 San Francisco 94105 Savannah 31802 Seattle 98124 St. Louis 61101 St. Pagl 55101	Rock Island Artenat 61299 Savance Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 50331: Serece Army Depot 14541 Tobyschne Army Depot 14546 Terele Army Depot 94074 Material Artenat 12189 Tuma Praving Graude 85364 White Sands Rissile Hange 80062 CLA ATTW: SCA-WI 22316 FORSCOM	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Empt. Library ATTH: Canddian Liston Office (2) ATTH: Library Cold Regions Research Engineering LAS 03755 ATTH: Library 22060
Omehe 68102 Prilledighte 19106 Pfitthurph 15222 Portland 91208 Riyash 69036 Ack Island 61201 Secrements 95814 See Francisco 94105 Savanah 31802 Seattle 98124 St. Louis 61101 St. Paul 55101 Tulsa 74102 Vicksharp 35180	Rock Island Artena: 61299 Savanca Army Depet 61074 Sharpe Army Depet 61074 Sharpe Army Depet 50331 Sereca Army Depet 14541 Tobyschna Army Depet 16546 Terele Army Depet 86074 Matervilet Arsonal 12189 Tyme Praving Graude 95364 Mite Sands Riss'te Hange 80062 GLA ATTW: DLA-W1 22214	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Engr. Library ATTH: Concilon Listen Office (2) ATTH: Library Cold Regions Research Engineering LAD 03755 ATTH: Library 22060 Waterways Experiment Station 38180
Omehe 68102 Priladelphie 19106 Pitthurph 15222 Portland 91208 Riyash 09036 Ack Island 61201 Secrements 95814 San Francisco 94105 Savannah 31802 Seattle 98124 St. Louis 61101 St. Paul 55101 Telsa 74102 Vicksberg 35180 valle Walle 99362 dilmington 28401	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 58331 Sereca Army Depot 14541 Tobyschna Army Depot 14541 Tobyschna Army Depot 14546 Terele Army Depot 16074 Materiotet Arsonat 12189 Tuma Praving Graude 85364 MR-1te Sands Riss'to Hange 80062 CLA ATTH: DKA-MI 22116 FORSCOM FORSCOM Engineer, ATTH: AFEN-FE ATTH: Focilities Engineer Fort Backmann 00934	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: CAMPIES ATTH: Concellen Listeery ATTH: Concellen Listeer Office (2) ATTH: Library Cold Regions Research Engineering Lab 03755 ATTH: Library 22040 Waterneys Experiment Station 39180 ATTH: Library ATTH: Library 2040 Waterneys Experiment Station 39180 ATTH: Library ATTH: Library 2040
Omehe 58102 Prilledigate 19106 Pfittherp 15222 Pertlend 97208 Riyash 09036 Reck Island 51201 Secrements 95814 San Francisco 98105 Savanneh 31802 Seattle 98124 St. Louis 61101 St. Paul 55101 Luisa F4102 Vicksberg 35100 valle Usila 99362 viluington 28401 G3 Army Engimeer Olvisions	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 95331 Sereca Army Depot 95331 Sereca Army Depot 15541 Tobyscone Army Depot 14541 Tobyscone Army Depot 14666 Terele Army Depot 94074 Materylist Arzenat 12189 Tume Fraving Graude 95364 White Sands Riss'io Hampe 98062 CLA ATTH: DEA-H1 22216 FORSCON FORSCON Engineer, ATTH: AFEM-FE ATTH: Facilities Engineer Fort Bechaman 00936 Fort Bechaman 00936 Fort Beapa 28307	ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-SM ATTH: Engr. Library ATTH: Engr. Library ATTH: Conceton Listen Office (2) ATTH: INA Library Cold Regions Research Engineering Lab 03755 ATTH: Library 22060 Vaterneys Experiment Scatter 39180 ATTH: Library MD, XVIII Atrhorne Curps and 28307
Omehe 68102 Prilledigate 19106 Pfittherph 19222 Pertland 97208 Riyesh 09038 Acci Island 81201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 61101 St. Peel 55101 Telsa 74102 Vicksberg 35180 Valle Walle 99362 dilutegton 28401 75 Army Engineer Oleisions Affa: Liberry	Rock Island Artenat 61299 Savanca Army Depet 61074 Sharpe Army Depet 61074 Sharpe Army Depet 50371 Sereca Army Depet 14541 Tobystena Army Depet 16541 Tobystena Army Depet 1656 Terele Army Depet 96074 Matervilet Arsonat 12169 Tyma Praving Grause 95364 Mite Sands Riss'te Range 98062 ELA ATTH: DLA-N1 22216 FORSCOM Engineer, ATTH: AFEM-FE ATTH: Facilities Engineer Fort Bachanam 00934 Fort Brogg 28307 Fort Campbell 42223	ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-SM ATTH: Engr. Library ATTH: Engr. Library ATTH: Constian Listen Office (2) ATTH: SM Library Cold Regions Research Engineering Lab 03755 ATTH: Library 22060 Waterways Experiment Scatter 39180 ATTH: Library MD, XVIII Atrhorne Curps and 28307 Ft. Brage ATTH: AFZA-FE-EE
Omehe 68102 Prilledighte 19106 Pritthurph 15222 Portland 91208 Riyash 09036 Ack Island 61201 Secrements 95818 San Francisco 94105 Savannah 31802 Seattle 98124 St. Louis 61101 St. Paul 55101 Leisa 74102 Vicksberg 35180 valle imited 28401 G3 Army Engineer Oleisions ATIM: Libeary Europe 99757	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Sereca Army Gepot 65371 Sereca Army Gepot 14541 Tobyschna Army Gepot 14541 Tobyschna Army Gepot 14546 Terele Army Gepot 46074 Materoliet Arsenat 12189 Tuna Praving Graude 85364 Mitte Sands Rissile Range 80062 CLA ATTH: SCA-HI 22116 FORSCOM Engineer, ATTH: AFEM-FE ATTH: Fectilises Engineer Fort Bechanam 00924 Fort Brags 28307 Fort Carsum 60913	ATTH: ATZA-STE-ER ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: Canadian Listen ATTH: Condition Listen ATTH: Condition Listen ATTH: Library Cald Regions Research Engineering Lab 03755 ATTH: Library 22040 Waterneys Experiment Station 39180 ATTH: Library 2040 Waterneys Experiment Station 39180 ATTH: Library ATTH: ATTA-STE-EE Chearte AFS, IL 61868
Omehe 68102 Prilledigate 19106 Pfittherph 19222 Pertland 97208 Riyesh 09038 Acci Island 81201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 61101 St. Peel 55101 Telsa 74102 Vicksberg 35180 Valle Walle 99362 dilutegton 28401 75 Army Engineer Oleisions Affa: Liberry	Rock Island Artenat 61299 Savanca Army Depet 61074 Sharpe Army Depet 61074 Sharpe Army Depet 50371 Sereca Army Depet 14541 Tobystena Army Depet 16541 Tobystena Army Depet 1656 Terele Army Depet 96074 Matervilet Arsonat 12169 Tyma Praving Grause 95364 Mite Sands Riss'te Range 98062 ELA ATTH: DLA-N1 22216 FORSCOM Engineer, ATTH: AFEM-FE ATTH: Facilities Engineer Fort Bachanam 00934 Fort Brogg 28307 Fort Campbell 42223	ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-SM ATTH: Engr. Library ATTH: Engr. Library ATTH: Constian Listen Office (2) ATTH: SM Library Cold Regions Research Engineering Lab 03755 ATTH: Library 22060 Waterways Experiment Scatter 39180 ATTH: Library MD, XVIII Atrhorne Curps and 28307 Ft. Brage ATTH: AFZA-FE-EE
Omehe 68102 Prilledighte 19106 Pritthurph 19222 Portland 91208 Riyesh 09036 Ack Island 61201 Secrements 95814 San Francisco 94105 Savannah 31802 Seattle 98124 St. Louis 61101 St. Pacl 55101 Telsa 74102 Vicksberg 35100 Halla 184102 Vicksberg 35100 Halla 184103 GS Army Engineer Oldisions ATIM: Library Europe 09757 Huntsetle 35307 Lower Mississippi Malley 39180 Middle 6851 09038	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Sereca Army Gepot 65371 Sereca Army Gepot 14541 Tobyschna Army Gepot 14541 Tobyschna Army Gepot 14546 Terele Army Gepot 46074 Materoliet Arsenat 12189 Tuna Praving Graude 85364 White Sands Rissile Hange 88062 CLA ATTH: SCA-HI 22116 FORSCOM Engineer, ATTH: AFEM-FE ATTH: Focilities Engineer Fort Bechanan 00924 Fort Braps 28307 Fort Carsum 60913 Fort Carsum 60913 Fort Core 13561 Fort Spot 75544	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Empr. Library ATTH: Condition Limitson Office (2) ATTH: Condition Limitson Office (2) ATTH: Library Cold Regions Research Engineering Lab 03755 ATTH: Library 22040 Waterneys Experiment Station 39180 ATTH: Library 22040 Waterneys Experiment Station 39180 ATTH: Library 22040 TO STEME Library TO, NYILL Atthorne Corps and 28307 Ft. Bragg ATTH: AFZA-FE-EE Chemite AFB, IL 61868 3345 CES/OE, Step 27 Morton AFS 92409
Omehe 58102 Prilledigate 19106 Prittherp 15222 Pertlend 97208 Riyash 09038 Reck Island 51201 Secrements 95814 San Francisco 98105 Savannéh 31802 Seattle 98124 St. Louis 61001 St. Paul 55101 Teles 74102 Vicksberg 35180 Valla Walfa 99362 Vilosherg 35180 Valla Walfa 99362 Vilosherg 35801 Carone G9757 Huntsethe 15907 Lower Mississippi Valley 39180 Riddle East (9038 Riddle East (9038)	Rock Island Artena? 61299 Savanca Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 10541 Iobyschan Army Depat 10541 Iobyschan Army Depat 10541 Iobyschan Army Depat 10646 Incele Army Depat 10674 Watervilet Arsena! 12185 Tume Proving Groupe 05364 WHITE Sands Riss*'s Rampe 08002 CLA ATTH: DLA-M! 22116 FORSCOM	ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-SM ATTH: ATZA-DTE-SM ATTH: Engr. Library ATTH: Condina Liation Office (2) ATTH: Library Cold Regions Resourch Engineering Lab 03755 ATTH: Library 22060 Waterways Experiment Scatter 39180 ATTH: Library MR, RYILL Airbarne Curps and 28307 Ft. Brang ATTH: AFZA-FE-EE Chemica AFB, IL 61868 3345 CES/DE, Stop 27
Omehe \$8102 Prilledigate 19106 Pfittherp 15222 Pertlend 97208 Riyesh 09038 Ack Island 81201 Secrements 95814 San Francisco 94105 Savameh 31402 Seattle 98124 St. Louis 61101 St. Ped 55101 Telsa 74102 Vicksberg 35100 valle islia 99362 dilutegton 28401 75 Army Engineer Oleisions Affa: Library Europe 09757 muntseille 35407 Lower Mississippi Valley 39180 Riddle East 09038 Riddle East 09038 Riddle East 19eori 22501 Hissouri Alber 68101	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 50331 Seneca Army Depot 14541 Tobyschem Army Depot 16541 Tobyschem Army Depot 16566 Terele Army Depot 86074 Materialist Arsenat 12109 Tuma Praving Grasse 95364 Maite Sands Riss'te Hange 80062 GLA ATTH: DLA-N1 22216 FORSCOM Engineer, ATTH: AFEM-FE ATTH: Fectitistes Engineer Fort Bechannn 00934 Fort Brage 28307 Fort Campbell 42223 Fort Carsom 60913 Fort Drym 13561 Fort Drym 13561 Fort Drym 13561 Fort Tode 75544 Fort Indiantum Gap 17003 Fart Iruin 92311	ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-SM ATTH: ATZA-DTE-SM ATTH: Engr. Library ATTH: Condina Liston Office (2) ATTH: Condina Liston Office (2) ATTH: Library Cold Regions Resourch Engineering Lab 03755 ATTH: Library 22060 Waterways Experiment Scatton 39180 ATTH: Library MR, RVIII Airbarne Curps and 28307 Ft. Bragg ATTH: AFZA-FE-EE Chemica AFS, IL 61868 3345 CES/OE, Stop 27 Morton AFE 92409 ATTH: MFCE-ME/DEE
Omehe 58102 Prifidelights 19106 Pfitthargh 15222 Pertland 97206 Riyash 09035 Ack Island 51201 Scormmete 95614 San Francisco 94105 Sarannah 31402 Seattle 98124 St. Louis 61101 St. Parl 55101 Teles 74102 Vicisherg 35100 valla Galia 99362 dilmington 28401 03 Army Engineer Dielsions Affix: Library Europe 09757 muntscile 35407 Lower mississippi Valley 39180 misde (ast 09038 Middle East (9008) Missouri Alber 68101 Narth Atlantic 10007	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Sereca Army Gepot 65371 Sereca Army Gepot 14541 Tobyschna Army Gepot 14541 Tobyschna Army Gepot 14541 Tobyschna Army Gepot 14546 Terele Army Gepot 46074 Materoliot Arsonat 12189 Tuna Fraving Graude 85364 Milte Sands Rissile Range 80062 CLA ATTH: ScA-HI 22116 FORSCON Engineer, ATTH: AFEN-FE ATTH: Sectificies Engineer Fort Sechanam 00934 Fort Brange 28307 Fort Carsum 60913 Fort Carsum 60913 Fort Corum 13601 Fort Sond 76544 Fort Indiastoma Gep 17003 Fort Iruna 92111 Fort Sam Houston 78214	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: EMPT. Library ATTH: Condition Listson Office (2) ATTH: Condition Listson Office (2) ATTH: Library Cold Regions Research Engineering LAD 03755 ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library RD, 1VIII Atthorne Corps and 28307 Ft. Bragg ATTH: AFZA-FE-EE Chemita AFB, IL 61868 3345 CES/DE, Stop 27 Morton AFB 91809 ATTH: MRCE-ME/DEE Tymdall AFB, FL 32403
Omehe 58102 Prilledigate 19106 Pistchargh 15222 Portlend 97208 Riyash 09036 Rock Island 51201 Secrements 95814 San Francisco 98105 Savannéh 31802 Seattle 98124 St. Louis 61101 St. Paul 55101 Tuisa 74102 Vicksberg 35180 Valla Halfa 99362 Viloshory 35180 Valla Halfa 99362 Viloshory 15800 Louer mississippi valley 39180 Middle Cast 09038 Middle East (Peerl 2250) Missouri Alber 68101 Varth Atlantic 10007 April Central 60605	Rock Island Artena? 61299 Savanca Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 61074 Indepated Army Depat 18541 Indepated Army Depat 18541 Indepated Army Depat 18541 Indepated Army Depat 1866 Incele Army Depat 96074 Materialist Arsenal 12185 Tume Proving Groupe 95364 Mitte Sands Riss*'s Rampe 98002 CLA ATTH: DLA-MI 22116 FORSCOM FORS	ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-SM ATTH: ATZA-DTE-SM ATTH: Engr. Library ATTH: Condina Liston Office (2) ATTH: Condina Liston Office (2) ATTH: Library Cold Regions Resourch Engineering Lab 03755 ATTH: Library 22060 Waterways Experiment Scatton 39180 ATTH: Library MR, RVIII Airbarne Curps and 28307 Ft. Bragg ATTH: AFZA-FE-EE Chemica AFS, IL 61868 3345 CES/OE, Stop 27 Morton AFE 92409 ATTH: MFCE-ME/DEE
Omehe 58102 Prifidelights 19106 Pfitthargh 15222 Pertland 97206 Riyash 09035 Ack Island 51201 Scormmete 95614 San Francisco 94105 Sarannah 31402 Seattle 98124 St. Louis 61101 St. Parl 55101 Teles 74102 Vicisherg 35100 valla Galia 99362 dilmington 28401 03 Army Engineer Dielsions Affix: Library Europe 09757 muntscile 35407 Lower mississippi Valley 39180 misde (ast 09038 Middle East (9008) Missouri Alber 68101 Narth Atlantic 10007	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Seneca Army Gepot 16531 Seneca Army Gepot 16541 Tobyschna Army Gepot 16541 Tobyschna Army Gepot 16566 Terele Army Gepot 16566 Terele Army Gepot 1671 Materoliot Arsenat 12169 Tuma Praving Grasse 95364 Mite Sands Riss'te Hange 80062 GLA ATTH: DLA-N1 22216 FORSCOM FORSCOM Engineer, ATTR: AFEM-FE ATTH: Fectitises Engineer Fort Bachanan 00936 Fort Brage 28307 Fort Campbell 42223 Fort Carsom 60913 Fort Drives 13561 Fort Drives 13561 Fort Drives 13561 Fort Indiastowa Gep 17003 Fart Indiastowa Gep 17003 Fart Indiastowa Gep 17003 Fort Lowis 98433 Fort Lowis 98433 Fort Lowis 98433 Fort Lowis 98433 Fort McCoy 54456	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: EMPT. Library ATTH: Condition Listson Office (2) ATTH: Condition Listson Office (2) ATTH: Library Cold Regions Research Engineering LAD 03755 ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library RD, 1VIII Atthorne Corps and 28307 Ft. Bragg ATTH: AFZA-FE-EE Chemita AFB, IL 61868 3345 CES/DE, Stop 27 Morton AFB 91809 ATTH: MRCE-ME/DEE Tymdall AFB, FL 32403
Omehe 58102 Prilledigate 19106 Pittharph 15222 Pertlend 97208 Riyash 09038 Ack Island 51201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 61101 St. Parl 55101 Island 74102 Victhary 35180 Valle Walle 99362 Viluthary 15180 Valle Walle 99362 Viluthary 15180 Valle Walle 99367 Viluthary 15180 Valle Walle 99367 Viluthary 15180 Riddle Cast 09038 Riddle Cast 09038 Riddle Cast 09038 Riddle East Feerl 22501 Varth Cantral 50605 Narth Pacific 97208 Quip Wiser 45201 Facific Ocean 98358	Rock Island Artena? 61299 Savanca Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 50371 Sereca Army Depat 18541 Tobyscana Army Depat 18541 Tobyscana Army Depat 1866 Tenete Army Depat 86074 Materialist Arsenal 12185 Tume Proving Groupe 65364 Mitte Sands Riss'in Hampe 68062 GLA ATTH: SLA-MI 22216 FORSCOM Engineer, ATTH- AFEM-FE ATTH: Facilistes Engineer Fort Bachanan 00934 Fort Bachanan 00934 Fort Bachanan 00934 Fort Campbell A2223 Fort McFherson 70334 Fort McFherson 70330 Fort George G. Reade 20755	ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-SM ATTH: ATZA-DTE-SM ATTH: Engr. Library ATTH: Condita Liston Office (2) ATTH: Condita Liston Office (2) ATTH: Library Cold Regions Resourch Engineering Lab 03755 ATTH: Library 22060 Waterways Experiment Station 39380 ATTH: Library MALTH: Library 22060 Waterways Experiment Station 39380 ATTH: Library MALTH: Library ATTH: ATTA-FE-EE Chemica ATB, IL 61868 3345 CES/DE, Stop 27 Morton ATE 92409 ATTH: MRCE-ME/DCE Tymdell ATB, FL 32403 ATESC/Engineering & Service Lab
Omehe 58102 Prilledigate 19106 Pittharph 15222 Pertlend 97208 Riyash 09038 Ack Island 51201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 61101 St. Parl 55101 Island 74102 Victhary 35180 Valle Walle 99362 Viluthary 15180 Valle Walle 99362 Viluthary 15180 Valle Walle 99367 Viluthary 15180 Valle Walle 99367 Viluthary 15180 Riddle Cast 09038 Riddle Cast 09038 Riddle Cast 09038 Riddle East Feerl 22501 Varth Cantral 50605 Narth Pacific 97208 Quip Wiser 45201 Facific Ocean 98358	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Seneca Army Gepot 16541 Tobyschna Army Gepot 16541 Tobyschna Army Gepot 16541 Tobyschna Army Gepot 16566 Terele Army Gepot 16566 Terele Army Gepot 1674 Matervilet Arsenat 12169 Tume Praving Graude 95364 Maite Sands Riss'te Rampe 80062 CLA ATTH: DLA-N1 22116 FORSCOM Engineer, ATTR: AFEM-FE ATTH: Focilties Engineer Fort Bachanan 00936 Fort Bragg 28307 Fort Carpell A2223 Fort Carsem 60913 Fort Devens 01653 Fort Dryn 13561 Fort Dryn 13561 Fort Dryn 13561 Fort Indiastown Gep 17003 Fort Indiastown Gep 17003 Fort Indiastown 78234 For, Lowis 96433 Fort Lowis 96433 Fort McCoy 54656 Fart McFherson 30330 Fort George G. Meade 20755 Fort Ord 93941	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: EMPT. Library ATTH: Commodian Library ATTH: Commodian Library ATTH: INR Library Cald Regions Research Engineering Lab 03755 ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library ATTH: Library ATTH: ATZA-FE-EE Chemica AFS, IL 61868 3345 CES/OE, Stop 27 morton AFS 92409 ATTH: MACE-ME/DEE Tymdell AFS, FL 32403 ATESC/Engineering & Service Lab DAFEC ATTH: MOIN Limiton Office Atlantic Division 22511
Omehe 58102 Prifidelights 19106 Pritthargh 15222 Pertland 97206 Riyash 09036 Ack Island 51201 Secrements 95614 San Francisco 96105 Savanah 31802 Seattle 98124 St. Louis 61101 St. Parl 55101 Teles 74102 Vicisherg 35180 Valla 68116 99362 Vicisherg 35180 Valla 68116 99363 Prope 69757 Puntsville 35807 Lower Mississippi Valley 39180 Middle East (9008 Middle East (9008) Middl	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Sereca Army Gepot 65371 Sereca Army Gepot 18541 Tobyschna Army Gepot 18541 Tobyschna Army Gepot 18546 Teoele Army Gepot 1866 Teoele Army Gepot 1866 Teoele Army Gepot 1876 Maistroliot Arsonal 12189 Tuna Fraving Graude 85364 Milta Sands Rissile Range 80062 ELA ATTH: Scall 22116 FORSCON FORSCON Engineer, ATTH: AFEN-FE ATTH: Focilities Engineer Fort Bechanam 00934 Fort Brange 28307 Fort Brange 28307 Fort Carsum 60913 Fort Carsum 60913 Fort Corum 13601 Fort Corum 13601 Fort Brook 76544 Fort Indiastown Gep 17003 Fort Tool 18501 Fort Sam Haustan 78214 For, Louis 98433 Fort McCherson 30130 Fort McCherson 30130 Fort McCherson 30130 Fort George G. Redde 20755 Fort Ord 93941 Fort Ord 93941 Fort Polk 71459	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Edgr. Library ATTH: Condition Listson Office (2) ATTH: Condition Listson Office (2) ATTH: Library ATTH: Library 22060 Valuriags Esperiment Station 39180 ATTH: ATZA-FE-EE Chemita AFB, IL 61868 3345 CES/DE, Stop 27 Morton AFB 92009 ATTH: MFACE-ME/DEE Tymdell AFB, FL 32403 AFESC/Engineering & Service Lab DAFEC ATTH: MOISE Liaison Office Atlactic Bivision 23511 Consequence 201914
Omehe 58102 Prilledigate 19106 Pittharph 15222 Pertlend 97208 Riyash 09038 Ack Island 51201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 61101 St. Parl 55101 Island 74102 Victhary 35180 Valle Walle 99362 Viluthary 15180 Valle Walle 99362 Viluthary 15180 Valle Walle 99367 Viluthary 15180 Valle Walle 99367 Viluthary 15180 Riddle Cast 09038 Riddle Cast 09038 Riddle Cast 09038 Riddle East Feerl 22501 Varth Cantral 50605 Narth Pacific 97208 Quip Wiser 45201 Facific Ocean 98358	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 61074 Indepot 6331 Sereca Army Depot 18541 Tobyschna Brmy Depot 18541 Tobyschna Brmy Depot 18541 Tobyschna Brmy Depot 18546 Temele Army Depot 18546 Temele Army Depot 18546 Tume Praving Groupe 65364 Mitte Sands Rissite Hampe 68062 GLA ATTH: SLA-N1 22216 FORSCOM Engineer, ATTH- NFEM-FE ATTH: Facilities Engineer Fort Brook 28500 Fort Brook 28500 Fort Carsom 60913 Fort McCarsom	ATTH: ATZA-DTE-EM ATTH: ATZA-DTE-SM ATTH: ATZA-DTE-SM ATTH: EMPT. Library ATTH: Canadian Listen Office (2) ATTH: Canadian Listen Office (2) ATTH: Canadian Listen ATTH: Canadian Listen Cald Regimes Research Engineering LAD 03755 ATTH: Library 22060 Waterneps Especiannt Station 39180 ATTH: Library 22060 Waterneps Especiannt Station 39180 ATTH: Library SR, RYILL Atthorne Carps and 28307 Ft. Brage ATTH: ATZA-FE-EE Chemica AFB, IL 61868 3345 CIS/OE, Stop 27 Rectan AFB, IL 61868 THE MACE-ME/DEE Tymdell AFB, FL 32403 ATTH: MACE-ME/DEE Tymdell AFB, FL 32403 ATTH: MOINT Listen Office ATTH: ROINT Listen Office Attactic Division 23511 Cresapeane Division 23511 Cresapeane Division 23541
Omnhe 58102 Prilladighte 19106 Pfittherph 15222 Partland 97208 Riyash 09038 Ack Island 51201 Secrements 95814 San Francisco 94105 Sanamah 1802 Seattle 98124 St. Louis 61101 St. Paul 55101 Telsa 74102 Vicksberg 35100 Valla Walla 99362 dilmington 28401 75 Army Engineer Oleisions Alla: Library Europe 09757 Muntseille 35807 Lower Mississippi Valley Risdle East 190038 Riddle	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Seneca Army Gepot 16541 Tobyschna Army Depot 16541 Tobyschna Army Depot 16541 Tobyschna Army Depot 16566 Terele Army Depot 86074 Matervilet Arsenat 12185 Tuma Praving Graude 85364 Maite Sands Riss'te Range 88062 ELA ATTH: DLA-N1 22116 FORSCOM Engineer, ATTR: AFEM-FE ATTH: Focilties Engineer Fort Bechanan 00936 Fort Brage 28307 Fort Campbell A2223 Fort Carsem 60913 Fort Devens 01653 Fort Crems 13561 Fort Devens 01653 Fort Crems 13561 Fort Armed 16546 Fort Indiasteum Gep 17003 Fort Indiasteum Gep 17003 Fort Indiasteum 78234 For, Lowis 98433 Fort Lowis 98433 Fort McCoy 54456 Fart McCoy 54456 Fart McCoy 54456 Fart McCoy 54456 Fort George G. Reade 20755 Fort Ord 93941 Fort Folk 71459 Fort Rickerdsen 99505 Fort 211ey 54442	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: CARACTER LIBRARY ATTH: Connection Library ATTH: Connection Library ATTH: Connection Library Cald Regions Research Engineering Lab 03755 ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library ATTH: ATZA-FE-EE Chemita AFS, IL 61068 3345 CES/OE, Stop 27 morton AFS 92409 ATTH: MACE-ME/DEE Tymdell AFS, FL 32403 ATESC/Engineering & Service Lab DAFEC ATTH: ROIM Limitan Office Atlantic Division 23511 Cresapeante Striston 25411 Factific Sivision 25641 Factific Sivision 25641
Omehe 58102 Prifidelights 19106 Pritthargh 15222 Pertland 97206 Riyash 09036 Ack Island 51201 Secrements 95614 San Francisco 96105 Savanah 31802 Seattle 98124 St. Louis 61101 St. Parl 55101 Teles 74102 Vicisherg 35180 Valla 68116 99362 Vicisherg 35180 Valla 68116 99363 Prope 69757 Puntsville 35807 Lower Mississippi Valley 39180 Middle East (9008 Middle East (9008) Middl	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 61074 Indepot 6331 Sereca Army Depot 18541 Tobyschna Brmy Depot 18541 Tobyschna Brmy Depot 18541 Tobyschna Brmy Depot 18546 Temele Army Depot 18546 Temele Army Depot 18546 Tume Praving Groupe 65364 Mitte Sands Rissite Hampe 68062 GLA ATTH: SLA-N1 22216 FORSCOM Engineer, ATTH- NFEM-FE ATTH: Facilities Engineer Fort Brook 28500 Fort Brook 28500 Fort Carsom 60913 Fort McCarsom	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: EAST. Library ATTH: Condition Listson Office (2) ATTH: Condition Listson Office (2) ATTH: Library Library Cold Regions Research Engineering Lab 03755 ATTH: Library 22060 Waterneys Esseriment Station 39180 ATTH: ATZA-FE-EE Chemica AFB, IL 61868 3345 CES/DE, Stop 27 Morizon AFB 92409 ATTH: MFACE-ME/DEE Tymdell AFB, FL 32403 AFESC/Engineering & Service Lab DAFEC ATTH: MOISE Liminon Office Atlactic Division 23511 Consequent Stripton 23511 Consequent Stripton 23511 Postfic Division 23611 Postfic Division 23610 Reftern Division 19112
Omnhe 58102 Prilladipate 19106 Pfittherph 19222 Partland 97208 Riyash 09038 Ack Island 51201 Secrements 95814 San Francisco 94105 Sanamah 1802 Seattle 98124 St. Louis 61101 St. Paul 55101 Telsa 74102 Vicksherg 35100 Valla Walla 99362 diluington 28401 75 Army Engineer Oleisions Alla: Library Europe 09757 Muntselle 35807 Lower Mississippi Valley 39180 Riddle East 190038 Ri	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Sereca Army Gepot 65371 Sereca Army Gepot 18541 Tobyschna Army Gepot 18541 Tobyschna Army Gepot 18546 Terele Army Gepot 18666 Terele Army Gepot 48674 Matervitet Arsenat 12189 Tuma Praving Graude 85344 Maite Sands Rissite Hange 80062 ELA ATTH: DLA-HI 22146 FORSCOM Engineer, ATTH: AFEM-FE ATTH: Sectities Engineer Fort Bechanan 00934 Fort Bragg 28307 Fort Bragg 28307 Fort Carson 80913 Fort Carson 80913 Fort Compell A2223 Fort Carson 80913 Fort Drivin 13561 Fort Drivin 13561 Fort Comp 13561 Fort Comp 15544 Fort Indiastowa Gep 17003 Fort Town 82311 Fort Sam Mauston 78234 For, Louis 98413 Fort McCap 54656 Fart McFherson 30330 Fort George G. Meade 20755 Fort Ovd 93941 Fort Polk 718459 Fort 816442 Presidia of San Francisca 94129 Fort Stevert 31113	ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: Canodian Listeon Office (2) ATTH: Canodian Listeon Office (2) ATTH: Canodian Listeon Office (2) ATTH: Listeory Cald Regions Research Engineering Lab 03755 ATTH: Listeory 22060 Waterneys Experiment Station 39180 ATTH: Listeory 22060 Waterneys Experiment Station 39180 ATTH: Listeory RE, NYILL Airborne Corps and 28307 Ft. Bragg ATTH: AFZA-FE-EE Cheaute AFS, IL 61868 3345 CES/OE, Stop 27 morton AFS 92409 ATTH: MACE-ME/DEE Tymdell AFS, FL 32403 ATESC/Engineering & Service Lab DAFEC ATTH: MOIN Listeon 0951ce Atlantic Division 23511 Consequent Division 29411 Pactific Sivision 504660 Revibers Division 19112 Western Division 19112 Western Division 19112 Western Division 14066 ATTH: Sr. Tech. FAC-011 22332
Omehe 58102 Prillodipate 19106 Prittharph 15222 Pertland 91208 Riyash 09036 Reck Island 51201 Secrements 95814 San Francisco 98105 Savanneh 31802 Seattle 98124 St. Louis 61101 St. Paul 55101 Island F4102 Vicksberg 35100 Vicksberg 35201 Vicksberg 35202 Vicksberg 35203 Vi	Rock Island Artena? 61299 Savanca Army Depat 61074 Sharpe Army Gepat 61074 Sharpe Army Gepat 61074 Sharpe Army Gepat 61074 Island Army Gepat 16541 Iobyscham Army Gepat 16541 Iobyscham Army Gepat 16541 Iother Army Gepat 16541 Value Fraving Groupe 95364 White Sands Riss'te Rampe 98002 CLA ATTH: DKA-M! 22116 FORSCOM FO	ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: EARTH Library ATTH: Connotion Listson Office (2) ATTH: Connotion Listson Office (2) ATTH: Connotion Listson Office (2) ATTH: Library ETL, ATTH: Library 22060 Waterneys Especiannt Station 39180 ATTH: Library 22060 Waterneys Especiannt Station 39180 ATTH: Library MR, RYILL Atthorne Corps and 26307 Ft, Brage ATTH: ATZA-FE-EE Chemica AFB, IL 61868 3345 CIS/OE, Stop 27 Morton AFE 93409 ATTH: MACC-ME/DEE Tymbell AFB, FL 32403 AFESCIEngineering & Service Lab MAFEC ATTH: MOIN Lisison Office Atlactic Division 23511 Consequence Division 23511 Consequence Division 23611 Pactific Division 23611 Pactific Division 39411 Pactific Division 3940666
Omehe 58102 Prilledigate 19106 Prittherp 15222 Pertlend 97208 Riyash 09038 Ack Island 51201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 61101 St. Paul 55101 Teles 74102 Vicksharg 35180 Valle Walle 99362 Vicksharg 35180 Vicksharg 35180 Vicksharg 35180 Vicksharg 153007 Varous 481804 Valle East Feerl 22501 Varous 481804 Valle Feet Feerl 22501 Varous 481804 Valle Feet Valle Varous 48201 Varous 48201 Valle Val	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Sereca Army Gepot 65371 Sereca Army Gepot 18541 Tobyschna Army Gepot 18541 Tobyschna Army Gepot 18546 Terele Army Gepot 18666 Terele Army Gepot 48674 Matervitet Arsenat 12189 Tuma Praving Graude 85344 Maite Sands Rissite Hange 80062 ELA ATTH: DLA-HI 22146 FORSCOM Engineer, ATTH: AFEM-FE ATTH: Sectities Engineer Fort Bechanan 00934 Fort Bragg 28307 Fort Bragg 28307 Fort Carson 80913 Fort Carson 80913 Fort Compell A2223 Fort Carson 80913 Fort Drivin 13561 Fort Drivin 13561 Fort Comp 13561 Fort Comp 13561 Fort Rode 76544 Fort Indiastoma Gep 17003 Fort Town 82311 Fort Sam Houston 78234 For, Louis 98413 Fort McCap 54656 Fart McFherson 30330 Fort George G. Meade 20755 Fort Ovd 93941 Fort Polk 718459 Fort Richardson 9505 Fort 21187 56442 Presidia of San Francisca 94129 Fort Stevert 31113	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE CARACTER LIBRARY ATTHE CARACTER LIBRARY ATTHE CARACTER LIBRARY ATTHE CARACTER LIBRARY ESTEL LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ATTHE LIBRARY ZZGGO ATTHE LIBRARY ATTHE ATZA-STE-EE Chemica AFB, IL 61868 3345 CLS/OE, Stop 27 MONTON AFB 92409 ATTHE MACK-ME/DEE Tymboll AFB, FL 32403 ATTHE MACK-ME/DEE Tymboll AFB, FL 32403 ATTHE MACK-ME/DEE ATTHE MOINT LIBRARY OFFICE ATTHE MOINT STATEMENT OF ST
Omehe 58102 Priladelpale 19106 Pritthargh 15222 Pertland 97208 Riyash 09036 Aock Island 51201 Scormmente 95614 San Francisco 94105 Sanamah 31402 Seattle 98124 St. Louis 51101 St. Pacl 55101 Tales 74102 Victohery 37180 Valle Walle 99362 dilutington 28401 US Army Engineer Oleisions Alis: Library Europe 99757 Huntselle 35807 Lower Mississippi Valley 39180 Middle East 19earl 22601 Missouri Riber 68101 North Entral 50605 Narth Pacific 97208 Quio River 45201 Pacific Ocean 98858 South Atlantic 10007 Aorth Central 50605 Narth Pacific 97208 Quio River 45201 Pacific Ocean 98858 South Atlantic 10007 South Pacific 54111 Southwestern 75702 US Army Curope NO, 718 Army Fraining Comment 09114 Alim: Alito-Dim (5) NO, 7th Army GOCS/Engr. 09403 Alim: Alito-Dim (4) V. Corps 90679	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Gepot 65371 Seneca Army Gepot 16541 Tobyschem Army Gepot 16541 Tobyschem Army Gepot 16541 Tobyschem Army Gepot 16546 Terele Army Gepot 16546 Terele Army Gepot 16546 Tume Praving Grasse 95344 Mite Sands Riss'te Rampe 80062 GLA ATTH: DLA-N1 22116 FORSCOM Engineer, ATTR: AFEM-FE ATTH: Focilties Engineer Fort Bachaman 00934 Fort Bragg 28307 Fort Carsem 60913 Fort Carsem 60913 Fort Devens 01653 Fort Cram 13561 Fort Arms 13711 Fort Sam Hawstom Gap 17003 Fort Invis 92311 Fort Sam Hawstom 78234 For, Lowis 96433 Fort McCoy 54656 Fart McRey 54656 Fart McRey 54656 Fart McRey 54656 Fort George G. Reade 20755 Fort George G. Reade 20755 Fort George G. Reade 20755 Fort 211ey 56442 Presidit of Sam Francisco 34129 Fort Sheriden 50037 Fort Stewert 3133 Fort Valmeright 99763 Vancouver Bks. 46660	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Canodian Listson Office (2) ATTH: Canodian Listson Office (2) ATTH: Canodian Listson Office (2) ATTH: Library Cald Regions Research Engineering Lab 03755 ATTH: Library ETL, ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library NO, RVIII Atthorne Curps and 28307 Ft. Bragg ATTH: AFZA-FE-EE Chemita AFS, IL 61868 3345 CES/OE, Stop 27 MORTON AFS 92609 ATTH: AFXA-FE-EE Tymdall AFS, FL 32403 AFESC/Engineering & Service Lab DAFEC ATTH: MOCE-ME/DEE Tymdall AFS, FL 32403 AFESC/Engineering & Service Lab DAFEC ATTH: MOTH Limitan Office Attactic Division 23511 Chesaponte Division 29411 Pacific Sivision 504660 Morthern Division 19112 Western Division 44066 ATTH: Sr. Teo. FAC-031 22332 ATTH: Asst. CDR 880, FAC-05 22332
Omehe 58102 Prillodipate 19106 Pritthargh 15222 Pertland 91208 Riyash 09038 Reck Island 51201 Secrements 95814 Sam Francisco 94105 Savannah 31802 Seattle 98124 St. Louis 61101 St. Paci 55101 Teles 78102 Vicesherg 35100 Valla 68164 99362 Vicesherg 35100 Valla 68164 99362 Vicesherg 35800 Valla 68164 99362 Vicesherg 35800 Vicesherg 358	Rock Island Artenat 61299 Savanca Army Depat 61074 Sharpe Army Gepat 61074 Sharpe Army Gepat 61074 Indepted Army Gepat 16541 Indepted Army Gepat 16541 Indepted Army Gepat 16541 Indepted Army Gepat 16541 Value Fraving Groupe 65364 White Sands Riss'te Rampe 68002 CLA ATTH: DLA-KI 22116 FORSCOM	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE CARACTER LIBRARY ATTHE CARACTER LIBRARY ATTHE CARACTER LIBRARY ATTHE CARACTER LIBRARY ESTEL LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ZZGGO VALUE LIBRARY ATTHE LIBRARY ZZGGO ATTHE LIBRARY ATTHE ATZA-STE-EE Chemica AFB, IL 61868 3345 CLS/OE, Stop 27 MONTON AFB 92409 ATTHE MACK-ME/DEE Tymboll AFB, FL 32403 ATTHE MACK-ME/DEE Tymboll AFB, FL 32403 ATTHE MACK-ME/DEE ATTHE MOINT LIBRARY OFFICE ATTHE MOINT STATEMENT OF ST
Omehe 58102 Priladelpale 19106 Pritthargh 15222 Pertland 97208 Riyash 09036 Aock Island 51201 Scormmente 95614 San Francisco 94105 Sanamah 31402 Seattle 98124 St. Louis 51101 St. Pacl 55101 Tales 74102 Victohery 37180 Valle Walle 99362 dilutington 28401 US Army Engineer Oleisions Alis: Library Europe 99757 Huntselle 35807 Lower Mississippi Valley 39180 Middle East 19earl 22601 Missouri Riber 68101 North Entral 50605 Narth Pacific 97208 Quio River 45201 Pacific Ocean 98858 South Atlantic 10007 Aorth Central 50605 Narth Pacific 97208 Quio River 45201 Pacific Ocean 98858 South Atlantic 10007 South Pacific 54111 Southwestern 75702 US Army Curope NO, 718 Army Fraining Comment 09114 Alim: Alito-Dim (5) NO, 7th Army GOCS/Engr. 09403 Alim: Alito-Dim (4) V. Corps 90679	Rock Island Artenat 61299 Savanca Army Depat 61074 Sharpe Army Gepat 61074 Sharpe Army Gepat 61074 Indepat 61074 I	ATTH: ATZA-STE-EM ATTH: ATZA-STE-SM ATTH: ATZA-STE-SM ATTH: Canodian Listson Office (2) ATTH: Canodian Listson Office (2) ATTH: Canodian Listson Office (2) ATTH: Library Cald Regions Research Engineering Lab 03755 ATTH: Library ETL, ATTH: Library 22060 Waterneys Experiment Station 39180 ATTH: Library NO, RVIII Atthorne Curps and 28307 Ft. Bragg ATTH: AFZA-FE-EE Chemita AFS, IL 61868 3345 CES/OE, Stop 27 MORTON AFS 92609 ATTH: AFXA-FE-EE Tymdall AFS, FL 32403 AFESC/Engineering & Service Lab DAFEC ATTH: MOCE-ME/DEE Tymdall AFS, FL 32403 AFESC/Engineering & Service Lab DAFEC ATTH: MOTH Limitan Office Attactic Division 23511 Chesaponte Division 29411 Pacific Sivision 504660 Morthern Division 19112 Western Division 44066 ATTH: Sr. Teo. FAC-031 22332 ATTH: Asst. CDR 880, FAC-05 22332
Omehe 58102 Prillodipate 19106 Prittharph 15222 Pertland 91208 Riyash 09038 Reck Island 51201 Secrements 95814 San Francisco 94105 Savannah 31802 Seattle 98124 St. Louis 61101 St. Paci 55101 Teles 74102 Vicksberg 35100 valla 6816a 99362 vilusserg 35100 valla 6816a 99362 vilusserg 35800 Vicksberg 35800	Rock Island Artenat 61299 Savanca Army Depat 61074 Sharpe Army Gepat 61074 Sharpe Army Gepat 61074 Indepted Army Gepat 16541 Indepted Army Gepat 16541 Indepted Army Gepat 16541 Indepted Army Gepat 16541 Value Fraving Groupe 65364 White Sands Riss'te Rampe 68002 CLA ATTH: DLA-KI 22116 FORSCOM	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE Engr. Library ATTHE Condition Listson Office (2) ATTHE Condition Listson Office (2) ATTHE Condition Listson Office (2) ATTHE Library STL, ATTHE Library 22060 Vaterneys Especiannt Station 39180 ATTHE Library RELITATION Library 22060 Vaterneys Especiannt Station 39180 ATTHE Library RELITATION LIBRARY ATTHE ATTHORNE Corps and 28307 Ft. Bragg ATTHE ATZA-FE-EE Chemica AFB, IL 61868 3345 CIS/OFE, Stop 27 MONTHS AFZA-FE-EE Tymbell AFB, IL 61868 3345 CIS/OFE, Stop 27 MONTHS AFZA-FE-EE Tymbell AFB, IL 61868 3345 CIS/OFE, Stop 27 MONTHS AFZA-FE-EE Tymbell AFB, IL 61868 3345 CIS/OFE, Stop 27 MONTHS AFZA-FE-EE Tymbell AFB, IL 32403 ATTHE ANTACT-METOLE ATTHE MONTHS Limitson Office Atlantic Styriston 23511 Consumpante Division 23511 Consumpante Division 23511 Consumpante Division 23511 POLIFIC Styriston 18912 Western Styriston 18912 Western Styriston 1890 ATTHE ASST. COR 880, FAC-05 22332 MEE, 93041 ATTHE Library (Come 1984)
Omnhe 58102 Prilladighte 19106 Prittherph 15222 Partland 97208 Riyash 09038 Ack Island 51201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 51101 St. Paul 55101 Island F4102 Vicksharg 35180 Valle Walle 99362 Vicksharg 35180 Vicksharg 35180 Vicksharg 35180 Vicksharg 35180 Vicksharg 35180 Vicksharg 35180 Vicksharg 35201 Vary Carte Savanth 10067 Vickshard Savanth 10067	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 61074 Indepot 63311 Seneca Army Depot 18541 Tobyschem Army Depot 18541 Tobyschem Army Depot 1856 Temele Army Depot 48074 Materoliot Arsenat 12185 Tume Praving Graude 85344 Maite Sands Riss'to Rampe 80062 ELA ATTH: DLA-N1 22146 FORSCOM Engineer, ATTR: AFEM-FE ATTH: Focilties Engineer Fort Rachaman 00934 Fort Rampe 2307 Fort Rampe 2307 Fort Campbell A2223 Fort Carsem 60913 Fort Devens 01853 Fort Crems 13561 Fort Devens 01853 Fort Devens 01853 Fort Devens 01853 Fort Devens 01853 Fort Devens 13561 Fort Hocky 54656 Fart McCay 54656 Fart McCay 54656 Fart McCay 54656 Fort 31111 Fort McCay 54656 Fort 31111 Fort Stenert 31133 Fort Valameright 99763 Vancouver Rks. 46660 MCC ATTR: MSLO-F 78234 ATTR: Facilities Engineer	ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: Canadian Listeon Office (2) ATTH: Canadian Listeon Office (2) ATTH: Listeory Cald Regions Research Engineering Lab 03755 ATTH: Listeory ETL, ATTH: Listeory 22060 Waterneys Esperiment Station 39180 ATTH: Listeory MR, Every RR, Every RR, Every RR, Every RR, Every ATTH: AFZA-FE-EE Chemica AFS, IL 61868 3345 CES/OE, Stop 27 morton AFS 92409 ATTH: MACE-ME/DEE Tymdell AFS, FL 32403 AFESC/Engineering & Service Lab DAFEC ATTH: MOINT Listeon Office Atlantic Division Office Atlantic Division 25511 Cresapente Division 25511 Cresapente Division 59411 Pecific Division 59411 Pecific Division 59650 Reothern Division 19112 Western Division 4860 ATTH: Arst. CDR RAG, FAC-05 22332 MCEL 93041 ATTH: Asst. CDR RAG, FAC-05 22332 MCEL 93041 Defense Technical Info. Center 22319 ATTH: ODA 6123
Omehe 58102 Priladelpate 19106 Pristhargh 15222 Perstand 97208 Riyash 09036 Ack Island 51201 Secrements 95614 San Francisco 96105 Saramah 31802 Seattle 98124 St. Louis 51101 St. Pacl 55101 Teles 74102 Vicesherg 15180 Valle 6812 9532 distington 28401 73 Army Engineer Oleisions Affir: Library Europe 99757 Huntselle 35807 Lower mississippi valley Forope 99757 Huntselle 35807 Lower mississippi valley Riddle East 19eerl 22601 Hissouri Riber 68107 North Central 50605 North Central 50605 North Pacific 97208 Quio River 45201 Facific Ocean 98856 South Ribartic 30302 South Pacific 97208 Quio River 45201 Facific Ocean 98856 South Ribartic 30302 South Pacific 54111 Southwestern 75702 US Army Curopa NO, 7th Army fraining Cemmed 09114 ATTH: AFIGN-06 (5) NO, 7th Army faciling (6) FILL Corps 09079 ATTH: AFIGN-06 (5) FILL Corps 09154 FILL Corps 09142	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 16541 Tobyschem Army Depot 16541 Tobyschem Army Depot 16541 Tobyschem Army Depot 16546 Terele Army Depot 46074 Matervilet Arsenat 12165 Tume Praving Graude 8534 Maite Sands Riss'te Rampe 80062 ELA ATTH: DLA-N1 22116 FORSCOM Engineer, ATTR: AFEM-FE ATTH: Focilties Engineer Fort Bachanan 00934 Fort Bragg 28307 Fort Carsen 60913 Fort Carsen 60913 Fort Devens 01653 Fort Devens 01653 Fort Crown 13561 Fort Devens 01653 Fort Crown 13561 Fort Devens 01653 Fort Crown 13561 Fort Devens 01653 Fort Devens 01653 Fort Devens 01653 Fort Devens 01653 Fort Devens 13561 Fort Devens 13565 Fort 1061astown Gap 17003 Fort Devens 13565 Fort 1061astown Gap 17003 Fort Steneys 01656 Farm McCay 54656 Farm McCay 54656 Farm McCay 54656 Fort 31115 Fort McCay 54656 Fort 31115 Fort McCay 54660 MCC ATTM: MSLO-F 78234 ATTM: Facilities Engineer Fitsimons Arc 80240 Maiter Reva RC 20012	ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: Canadian Listson Office (2) ATTH: Canadian Listson Office (2) ATTH: Canadian Listson Office (2) ATTH: Listson Cald Regions Research Engineering Lab 03755 ATTH: Listson ETL, ATTH: Listson 22060 Waterneys Experiment Station 39180 ATTH: Listson ATTH: Listson FL, Bragg ATTH: ATTA-STE-EE Chemita AFS, IL 61868 3345 CES/OE, Stop 27 MORTON AFS 91809 ATTH: MFACE-ME/DEE Tyndall AFS, FL 32403 ATTH: MOSE-ME/DEE Tyndall AFS, FL 32403 ATTH: MOSE-ME/DEE ATTH: MOSE-ME/DEE ATTH: MOSE-ME/DEE ATTH: SOIN Listson Office Attactic Division 23511 Chesapeane Division 2941 PACIFIC Sivision 2940 ATTH: SOIN Listson 19112 Western Sivision 54064 ATTH: S. F. Ted. FAC-031 22332 ATTH: ASSL. CDR REG, FAC-05 22332 ACEE, 93041 ATTH: CDA (12) Engineering Societies Library (0017
Omnhe 58102 Prillodipate 19106 Prittharph 15222 Pertland 91208 Riyash 09038 Anck Island 51201 Secrements 95814 San Francisco 94105 Savannah 31402 Seattle 98124 St. Louis 61101 St. Pagi 55101 Ieles 74102 Vicksberg 35100 valla 6816a 99362 vilusystem 35401 03 Army Engineer Divisions Affir: Library Europe 69757 Huntselle 35401 Lower Mississippi Valley 39180 Middle 6851 (Page) 22401 Missouri Alber 68101 Varth Atlantic 10067 North Central 60605 Namth Pactfic 91208 Onto River 68101 Facific Ocean 98858 South Activity 10067 Anthe Factfic 91208 Onto River 68101 South Pactfic 51208 Onto River 68101 South Pactfic 50605 Namth Factfic 91208 Onto River 68101 South Pactfic 50111 Southwestern 75202 US Army Curopa MO, 7th Army foctorings. 09403 ATTH: Afficoln (5) FITH: Affich (6) FITH: Affich (5) FITH: Affich	Rock Island Artenat 61299 Savanca Army Depat 61074 Sharpe Army Gepat 61074 Sharpe Army Gepat 61074 Indeptation Juny Gepat 1846 Incele Army Gepat 1846 Incele Army Gepat 86074 Materolict Arsenat 12189 Tume Proving Groupe 65364 Mitte Sands Riss'te Rampe 68062 CLA ATTH: SLA-MI 22316 FORSCOM FORSCOM Engineer, ATTH: AFEM-FE ATTH: Facilities Engineer Fort Bachanam 00934 Fort Bachanam 00934 Fort Bachanam 00936 Fort Caryon 18503 Fort Caryon 18503 Fort Caryon 18503 Fort Down 18503 Fort Caryon 18504 Fort Indiastown Gap 17003 Fart Invia 92131 Fort Sand Fastat Fort Lowis 98433 Fort Caryon 54646 Fort McFherson 20330 Fort George G. Reade 20755 Fort Ovel 93941 Fort Stement 31333 Fort Polk 18459 Fort Stement 31333 Fort Polk 18459 Fort Stement 31333 Fort Polk 18459 Fort Stement 31333 Fort McFherson 20307 Fort Stement 31333 Fort Hollmaright 99703 Vancouver Bks. 46660 MSC ATTH. MSLO-F 18234 ATTH: Facilities Engineer Fitzsimon Art. 80240 Walter Reed RC 20012 FMSCOX - Ch. Insti. Div.	ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: ATZA-STE-SH ATTH: Canadian Listeon Office (2) ATTH: Canadian Listeon Office (2) ATTH: Listeory Cald Regions Research Engineering Lab 03755 ATTH: Listeory ETL, ATTH: Listeory 22060 Waterneys Esperiment Station 39180 ATTH: Listeory MR, Every RR, Every RR, Every RR, Every RR, Every ATTH: AFZA-FE-EE Chemica AFS, IL 61868 3345 CES/OE, Stop 27 morton AFS 92409 ATTH: MACE-ME/DEE Tymdell AFS, FL 32403 AFESC/Engineering & Service Lab DAFEC ATTH: MOINT Listeon Office Atlantic Division Office Atlantic Division 25511 Cresapente Division 25511 Cresapente Division 59411 Pecific Division 59411 Pecific Division 59650 Reothern Division 19112 Western Division 4860 ATTH: Arst. CDR RAG, FAC-05 22332 MCEL 93041 ATTH: Asst. CDR RAG, FAC-05 22332 MCEL 93041 Defense Technical Info. Center 22319 ATTH: ODA 6123
Omnhe 58102 Prilladighte 19106 Prittharph 15222 Portland 97208 Riyash 09038 Anck Island 51201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 51101 St. Paul 55101 Teles 74102 Vicksharg 35180 Valle Walle 99362 Vilesharg 35180 Vilesharg 153001 Lower Mississippi Valley 39180 Missiouf River 68101 Martin Allantic 10007 Varth Central 50505 Narth Pactfic 97208 Onio River 45201 Varth Pactfic 97208 Onio River 45201 Pactfic Ocean 9856 South Atlantic 10007 Varth Pactfic 54111 Southwestern J5202 US Army Curtus MO, Jih Army Fraining Commend 09114 ATTH: AfTIL-0th (5) MO, Jih Army Fraining Commend 09114 ATTH: AfTIL-0th (5) Vileshard Commend 09125 ATTH: AfTING(N (5) Vileshard Commend 09125 ATTH: AfTING(N (5) Vileshard Commend 09125 ATTH: AfTHE Commend 09125 ATTH: AfTHE Commend 09125 ATTH: AfTHE AFTHE (S) Bartin 09742 ATTH: Afthe (S) Southern Commend 09125 ATTH: Afthe (S) Southern Commend 09125 ATTH: Afthe (S) Southern Commend 09125 ATTH: Afthe (S) Southern Commend 128 ATTHE Afthe (S) ATTHE Afthe (S) ATTHE Afthe (S) ATTHE Afthe (S) ATTHE Aft	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 18541 Tobyschem Army Depot 18541 Tobyschem Army Depot 18541 Tobyschem Army Depot 18546 Tenete Army Depot 36074 Materiated Arsonat 12185 Tyme Proving Groupe 65364 Mitte Sands Rissite Hange 88062 GLA ATTH: SLA-MI 22216 FORSCOM Fogineer, ATTR: NFEM-FE ATTH: Facilities Engineer Fort Brogg 28307 Fort Brogg 28307 Fort Brogg 28307 Fort Campell 42223 Fort Commelliation Gap 17003 Fort Brode 78544 Fort Indiastona Gap 17003 Fort India 92111 Fort Sam Massiam 78234 Fort HoCoy 54656 Fort McCoy 54656 Fort George G. Meede 20755 Fort Cod 93941 Fort Polk 71459 Fort Shoriden 50027 Fort Scheriden 50027 For	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE CANADIAN Listean Office (2) ATTHE CANADIAN Listean Office (2) ATTHE CANADIAN Listean Office (2) ATTHE CANADIAN Listeany Cold Regimes Research Engineering LAD 03755 ATTHE Library 22060 Waterneys Especiannt Station 39180 ATTHE Library 22060 Waterneys Especiannt Station 39180 ATTHE Library MR, RYLLI Atthorne Carps and 28307 Ft. Brogg ATTHE ATZA-FE-EE Chemica AFB, IL 61868 3345 CLS/OE, Stop 27 Morton AFB 92409 ATTHE MACE-ME/DEE Tymbell AFB, FL 32403 AMESCIEngineering & Service Lab NAFEE ATTHE MOIN Listean Office Atlantic Division 23511 Cresapeante Division 23511 Cresapeante Division 23511 Cresapeante Division 23511 Cresapeante Division 23511 Pactific Division 54646 ATTHE ST. Tech. FAC-031 22332 ATTHE ASSE. COR 880, FAC-03 22332 ATTHE ASSE. COR 880, FAC-03 22332 ATTHE COR 6123 Defense Technical Info. Center 22319 ATTHE COR 6123 Engineering Societies Library 10017 New York, NT
Omehe 58102 Prillodigate 19106 Pritthargh 15222 Pertland 97208 Riyash 09036 Ack Island 51201 Secrements 95614 San Francisco 96105 Saramah 31802 Seattle 98124 St. Louis 61101 St. Paci 55101 Teles 74102 Vicisherg 15180 Valle 6816 99362 Vicisherg 15180 Valle 6816 99362 Vicisherg 15180 Valle 6816 99367 Muntselle 35401 US Army Engineer Divisions Affir: Library Furge 99757 Muntselle 35407 Lower Mississippi Valley 39180 Middle 6810 18007 North Central 65605 Marth Facific 97208 Onlo Rieser 45201 Pacific Ocean 98856 South Atlantic 10007 Aporth Central 65605 Marth Facific 97208 Onlo Rieser 45201 Pacific Ocean 98856 South Atlantic 10007 Aporth Central 65605 Marth Facific 97208 Onlo Rieser 45201 Pacific Ocean 98856 South Atlantic 10007 Aporth Central 65605 Marth Facific 97208 Onlo Rieser 45201 Pacific Ocean 98856 South Atlantic 10007 Aporth Central 65605 Marth Facific 97208 Onlo Rieser 45201 Facific Ocean 98856 South Atlantic 10007 Aporth Central 65605 Marth Facific 97208 Onlo Rieser 45201 Facific Ocean 98856 South Atlantic 10007 Aporth Central 66605 Marth Facific 97208 Onlo Rieser 45201 Facific Ocean 98856 South Atlantic 10007 Aporth Central 65605 Marth Facific 97208 Onlo Rieser 45201 Facific Ocean 98856 South Atlantic 10007 Aporth Central 65605 Marth Facific 97208 Old Pacific Ocean 98856 South Atlantic 10007 Aporth Central 66605 Marth Facific 97208 Mart	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 16541 Tobyschna Army Depot 16541 Tobyschna Army Depot 16541 Tobyschna Army Depot 16546 Terele Army Depot 40074 Matervitet Arsonat 12185 Tuma Praving Graude 8534 Maite Sands Riss'te Range 80062 ELA ATTH: DLA-N1 22146 FORSCOM Engineer, ATTR: AFEM-FE ATTH: Socilities Engineer Fort Bechanan 00934 Fort Brage 28307 Fort Carson 60913 Fort Devens 01453 Fort Carson 60913 Fort Devens 01453 Fort Carson 16544 Fort Indiastown Gap 17003 Fort Indiastown Gap 17003 Fort Indiastown Gap 17003 Fort Indiastown 78234 For, Lowis 98433 Fort Cory 54654 Fort Indiastown 78234 For, Lowis 98433 Fort McCop 54654 Fort Richerdson 78234 For Becomp G. Neede 20755 Fort George G. Neede 20755 Fort Stevent 31333 Fort McCop 546542 Presidit of San Francisco 14129 Fort Stevent 31333 Fort Valamright 99763 Vancouver Bks. 16660 MCC ATTR. MSLO-F 78234 ATTR: Facilities Engineer Fitsimons Art. 80240 Walter Reed RC. 20012 IMSCOR - Ch. Insti. Div. 4TTR., Facilities Engineer Arlington 2611 Station 121 22212	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE Canadian Listson Office (2) ATTHE Consider Listson Office (2) ATTHE Consider Listson Office (2) ATTHE Consider Listson Office (2) ATTHE Listson' Cold Regions Research Engineering Lab 03755 ATTHE Listson' ETL, ATTHE Listson' ETL, ATTHE Listson' ETL, ATTHE Listson' ATTHE Listson' ATTHE Listson' ATTHE ATZA-FE-EE Chemica ATB, IL 61868 3345 CES/OE, Stop 27 MONTES ATZA-FE-EE Chemica ATB, IL 61868 3345 CES/OE, Stop 27 MONTES ATZA-FE-EE Tymdall ATB, FL 32403 ATTHE MACE-ME/DEE Tymdall ATB, FL 32403 ATTHE MOSE-ME/DEE Tymdall ATB, FL 32403 ATTHE MOSE-ME/DEE Tymdall ATB, FL 32403 ATTHE MOSE-ME/DEE Tymdall ATB, FL 32403 ATTHE ATTHE MOSE-ME/DEE ATTHE MOSE-ME/DEE ATTHE SOLDHARD STALL WESTERN BIVISION STALL ATTHE ST. Tech. FAC-031 22332 ATTHE ASSE. COR RAD, FAC-03 22332 ATTHE ASSE. COR RAD, FAC-03 22332 ATTHE COA (12) Engineering Societies Library (001) New York, NT WESTERN Guare Burray 20310
Omnhe 58102 Prilladighte 19106 Prittharph 15222 Portland 97208 Riyash 09038 Anck Island 51201 Secrements 95814 San Francisco 94105 Savanneh 31402 Seattle 98124 St. Louis 51101 St. Paul 55101 Teles 74102 Vicksharg 35180 Valle Walle 99362 Vilesharg 35180 Vilesharg 153001 Lower Mississippi Valley 39180 Missiouf River 68101 Martin Allantic 10007 Varth Central 50505 Narth Pactfic 97208 Onio River 45201 Varth Pactfic 97208 Onio River 45201 Pactfic Ocean 9856 South Atlantic 10007 Varth Pactfic 54111 Southwestern J5202 US Army Curtus MO, Jih Army Fraining Commend 09114 ATTH: AfTIL-0th (5) MO, Jih Army Fraining Commend 09114 ATTH: AfTIL-0th (5) Vileshard Commend 09125 ATTH: AfTING(N (5) Vileshard Commend 09125 ATTH: AfTING(N (5) Vileshard Commend 09125 ATTH: AfTHE Commend 09125 ATTH: AfTHE Commend 09125 ATTH: AfTHE AFTHE (S) Bartin 09742 ATTH: Afthe (S) Southern Commend 09125 ATTH: Afthe (S) Southern Commend 09125 ATTH: Afthe (S) Southern Commend 09125 ATTH: Afthe (S) Southern Commend 128 ATTHE Afthe (S) ATTHE Afthe (S) ATTHE Afthe (S) ATTHE Afthe (S) ATTHE Aft	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 18541 Tobyschem Army Depot 18541 Tobyschem Army Depot 18541 Tobyschem Army Depot 18546 Tenete Army Depot 36074 Materiated Arsonat 12185 Tyme Proving Groupe 65364 Mitte Sands Rissite Hange 88062 GLA ATTH: SLA-MI 22216 FORSCOM Fogineer, ATTR: NFEM-FE ATTH: Facilities Engineer Fort Brogg 28307 Fort Brogg 28307 Fort Brogg 28307 Fort Campell 42223 Fort Commelliation Gap 17003 Fort Brode 78544 Fort Indiastona Gap 17003 Fort India 92111 Fort Sam Massiam 78234 Fort HoCoy 54656 Fort McCoy 54656 Fort George G. Meede 20755 Fort Cod 93941 Fort Polk 71459 Fort Shoriden 50027 Fort Scheriden 50027 For	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE CARACTER LIBRARY Cald Regions Research Engineering Lab 03755 ATTHE Library Cald Regions Research Engineering Lab 03755 ATTHE Library 22060 Waterneys Experiment Station 39180 ATTHE Library ATTHE Library 22060 Waterneys Experiment Station 39180 ATTHE Library ATTHE ATZA-STE-EE Chemita AFS, it 61068 3345 CES/OE, Stop 27 MORTON AFS 92409 ATTHE ATZA-FE-EE Tymdell AFS, ft 32403 ATESC/Engineering & Service Lab DAFEC ATTHE MORE-ME/DEE Tymdell AFS, ft 32403 ATTHE MORE-ME/DEE Tymdell AFS, ft 32403 ATTHE MORE-ME/DEE ATTHE MORE-ME/DEE Tymdell AFS, ft 32403 ATTHE MORE-ME/DEE ATTHE MORE-ME/DEE ATTHE MORE-ME/DEE ATTHE ST. Tech. FAC-031 22332 ATTHE ASSE. COR 880, FAC-05 22332 ACEE 93041 ATTHE COA 1121 Engineering Societies Library 10017 New York, NT Wattonal Guera Burrow 70310 Installation Ofvision
Omehe 58102 Prillodipate 19106 Prittharph 15222 Perithad 91208 Riyash 09038 Ack Island 51201 Secrements 95814 San Francisco 94105 Savannah 31402 Seattle 98124 St. Louis 61101 St. Padi 55101 Ieles 74102 Vicesherg 35100 valla 6816a 99362 vilungton 28401 03 Army Engineer Divisions Affir: Library Europe 09757 Manterile 35401 Lower Mississippi Valley 39180 Riddle 6xst 09038 Riddle Exst (Peorl 22401 Missouri Alber 68101 Varth Atlantic 10067 April Central 60605 April Facific 97208 Onio Riedle 15201 Facific Ocean 98558 South Artific 517208 Onio Riedle 15201 Facific Ocean 98558 South Pactfic 57208 US Army Curope MO, 2th Army fratalna Command 09114 Affir: Affic-Oin (5) RO, 7th Army GOCS/fampr. 09403 Affir: Affich (6) V. Corps 0959 Affir: Affich (5) FITH: Affich (6) FITH: Affich (7) FITH	Rock Island Artenat 61299 Savanca Army Depot 61074 Sharpe Army Depot 61074 Sharpe Army Depot 16541 Tobyschna Army Depot 16541 Tobyschna Army Depot 16541 Tobyschna Army Depot 16546 Terele Army Depot 40074 Matervitet Arsonat 12185 Tuma Praving Graude 8534 Maite Sands Riss'te Range 80062 ELA ATTH: DLA-N1 22146 FORSCOM Engineer, ATTR: AFEM-FE ATTH: Socilities Engineer Fort Bechanan 00934 Fort Brage 28307 Fort Carson 60913 Fort Devens 01453 Fort Carson 60913 Fort Devens 01453 Fort Carson 16544 Fort Indiastown Gap 17003 Fort Indiastown Gap 17003 Fort Indiastown Gap 17003 Fort Indiastown 78234 For, Lowis 98433 Fort Cory 54654 Fort Indiastown 78234 For, Lowis 98433 Fort McCop 54654 Fort Richerdson 78234 For Becomp G. Neede 20755 Fort George G. Neede 20755 Fort Stevent 31333 Fort McCop 546542 Presidit of San Francisco 14129 Fort Stevent 31333 Fort Valamright 99763 Vancouver Bks. 16660 MCC ATTR. MSLO-F 78234 ATTR: Facilities Engineer Fitsimons Art. 80240 Walter Reed RC. 20012 IMSCOR - Ch. Insti. Div. 4TTR., Facilities Engineer Arlington 2611 Station 121 22212	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE Conciliant Library ATTHE Conciliant Library ATTHE Conciliant Library ATTHE Conciliant Research Engineering Lab 03755 ATTHE Library Cold Regions Research Engineering Lab 03755 ATTHE Library 22060 Vaturings Especiannt Station 39180 ATTHE Library 22060 Vaturings Especiannt Station 39180 ATTHE Library ATTHE Library 22060 ATTHE ATZA-FE-EE Chemita AFS, IL 61868 3345 CES/DE, Stop 27 MONTON AFS 92409 ATTHE MACE-ME/DEE Tymdall AFS, EL 32403 MESC/Engineering & Service Lab DAFEC ATTHE MOTH Liaison Office Atlantic Division 23511 Consumpant Division 29511 Consumpant Division 29511 PACIFIC Division 05660 Recture Division 54016 ATTHE ST. Tech. FAC-031 22312 ATTHE ASSE. COR 880, FAC-05 22332 MEE 93041 ATTHE COA 6123 Engineering Societies Library 10017 New York, NT Wational Guard Burrow 20310 Installation Division US Government Privation 9571cc 22304
Omnhe 58102 Prillodipate 19106 Prittharph 15222 Pertland 91208 Riyash 09038 Rock Island 51201 Secrements 95814 San Francisco 94105 Savannah 11002 Seattle 98124 St. Louis 61101 St. Paci 55101 Ielea 74102 Vicksherg 35100 Valle 6816 99362 Vicksherg 35100 Valle 6816 99362 Vicksherg 35100 Valle 6816 99362 Vicksherg 35800 Valle 6816 99362 Vicksherg 35800 Valle 6816 99363 Riddle 681 09038 Riddle 69388 09038 Riddle 681	Rock Island Artenat 61299 Savanca Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 10541 Iobyscana Army Depat 10541 Iobyscana Army Depat 10541 Iobyscana Army Depat 10541 Iobyscana Army Depat 10541 Interview	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE CARACTER LIBRARY Cald Regions Research Engineering Lab 03755 ATTHE Library Cald Regions Research Engineering Lab 03755 ATTHE Library 22060 Waterneys Experiment Station 39180 ATTHE Library ATTHE Library 22060 Waterneys Experiment Station 39180 ATTHE Library ATTHE ATZA-STE-EE Chemita AFS, it 61068 3345 CES/OE, Stop 27 MORTON AFS 92409 ATTHE ATZA-FE-EE Tymdell AFS, ft 32403 ATESC/Engineering & Service Lab DAFEC ATTHE MORE-ME/DEE Tymdell AFS, ft 32403 ATTHE MORE-ME/DEE Tymdell AFS, ft 32403 ATTHE MORE-ME/DEE ATTHE MORE-ME/DEE Tymdell AFS, ft 32403 ATTHE MORE-ME/DEE ATTHE MORE-ME/DEE ATTHE MORE-ME/DEE ATTHE ST. Tech. FAC-031 22332 ATTHE ASSE. COR 880, FAC-05 22332 ACEE 93041 ATTHE COA 1121 Engineering Societies Library 10017 New York, NT Wattonal Guera Burrow 70310 Installation Ofvision
Omnhe 68102 Prilladelphie 19106 Prittherph 15222 Pertland 97208 Riyash 09038 Anck Island 61201 Secrements 95814 San Francisco 94105 Savannah 31402 Seattle 98124 St. Louis 61101 St. Paul 55101 Taina 74102 Vicksharg 35180 Villa 1818 99362 Villadelphia 99362 Villadelphia 99362 Villadelphia 99362 Villadelphia 99363 Villadelphia 99363 Villadelphia 99363 Riddle East 9908 Riddle East	Rock Island Artenat 61299 Savanca Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 61074 Indepated Army Depat 18541 Indepated Army Depat 18541 Indepated Army Depat 18541 Indepated Army Depat 18541 Indepated Army Depat 18184 Indepated Army Depat 18185 Indepated Army Depat 18184 Indepated Army Depat 18184 Indepated Army Depat 18184 Indepated Army Depated 18184 Indepated Army Depated Indepated In	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE Conciliant Library ATTHE Conciliant Library ATTHE Conciliant Library ATTHE Conciliant Research Engineering Lab 03755 ATTHE Library Cold Regions Research Engineering Lab 03755 ATTHE Library 22060 Vaturings Especiannt Station 39180 ATTHE Library 22060 Vaturings Especiannt Station 39180 ATTHE Library ATTHE Library 22060 ATTHE ATZA-FE-EE Chemita AFS, IL 61868 3345 CES/DE, Stop 27 MONTON AFS 92409 ATTHE MACE-ME/DEE Tymdall AFS, EL 32403 MESC/Engineering & Service Lab DAFEC ATTHE MOTH Liaison Office Atlantic Division 23511 Consumpant Division 29511 Consumpant Division 29511 PACIFIC Division 05660 Recture Division 54016 ATTHE ST. Tech. FAC-031 22312 ATTHE ASSE. COR 880, FAC-05 22332 MEE 93041 ATTHE COA 6123 Engineering Societies Library 10017 New York, NT Wational Guard Burrow 20310 Installation Division US Government Privation 9571cc 22304
Omehe 58102 Prilidelighte 19106 Prittharph 15222 Pertland 97208 Riyash 09036 Ack Island 51201 Secrements 95614 San Francisco 96105 Saramah 31802 Seattle 98124 St. Louis 61101 St. Pacl 55101 Teles 74102 Vicishery 35180 Valle 68161 VI Army Engineer Divisions Affix: Library Europe 09757 Muntselle 35807 Lower Mississippi Valley 39180 Misde East (9038 Misde East (9039 Misse Misde (9039 Misse Misse (9039 Mis	Rock Island Artena? 61299 Savanca Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 16541 Tokyacona Army Depat 16541 Tokyacona Army Depat 16541 Tokyacona Army Depat 16541 Tokyacona Army Depat 16541 Value Praving Groupe 95364 White Sands Riss*iv Rampy 98002 GLA ATTH: DKA-K! 22116 FORSCOM FOR	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE Canadian Listson Office (2) ATTHE Canadian Listson Office (2) ATTHE Canadian Listson Office (2) ATTHE Listson Cald Regions Research Engineering Lab 03755 ATTHE Listson STEM: Listson STEM: Listson 22040 Waterways Experiment Station 39180 ATTHE Listson ATTHE Listson Ft. Bragg ATTHE ATTA-STE-EE Chemica AFS, IL 61868 3345 CES/OE, Stop 27 MONTON AFS 91409 ATTHE MACE-ME/DEE Tymdall AFS, FL 32403 ATTHE MACE-ME/DEE Tymdall AFS, FL 32403 ATTHE MOSE-ME/DEE ATTHE SON-Short Stop 2941 PROSESSON Stop 2944 MOSE-ME/DEE ATTHE ST. FCA. FAC-031 22332 ATTHE ASSE. CDR REG. FAC-05 22332 MCEE 93041 ATTHE ST. FCA. FAC-031 22332 ATTHE ASSE. CDR REG. FAC-05 22332 MCEE 93041 ATTHE MSSE. CDR REG. FAC-05 22332 MCEE 93041 A
Omnhe 68102 Prilladelphie 19106 Prittherph 15222 Pertland 97208 Riyash 09038 Anck Island 61201 Secrements 95814 San Francisco 94105 Savannah 31402 Seattle 98124 St. Louis 61101 St. Paul 55101 Taina 74102 Vicksharg 35180 Villa 1818 99362 Villadelphia 99362 Villadelphia 99362 Villadelphia 99362 Villadelphia 99363 Villadelphia 99363 Villadelphia 99363 Riddle East 9908 Riddle East	Rock Island Artenat 61299 Savanca Army Depat 61074 Sharpe Army Depat 61074 Sharpe Army Depat 61074 Indepated Army Depat 18541 Indepated Army Depat 18541 Indepated Army Depat 18541 Indepated Army Depat 18541 Indepated Army Depat 18184 Indepated Army Depat 18185 Indepated Army Depat 18184 Indepated Army Depat 18184 Indepated Army Depat 18184 Indepated Army Depated 18184 Indepated Army Depated Indepated In	ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE ATZA-STE-SH ATTHE Canadian Listson Office (2) ATTHE Canadian Listson Office (2) ATTHE Canadian Listson Office (2) ATTHE Listson' 22060 Value of the Carpy 22060 Valu

Chief of Engineers ATTN: DAEN-ZCF-U ATTN: DAEN-ECZ-A ATTN: DAEN-ECS

त्य पुरस्केत् स्थान्य स्थान्य कार्याच्या कार्याच्या विश्वेत्र स्थान्य वर्षेत्र स्थान्य स्थान्य वर्षेत्र स्थान् स्थान

US Army Engineer District Philadelphia 19106 ATTN: Chief, MAPEN-D Saltimore 21203 ATTM: Chief, Engr Div Morfolk 23510 ATTM: Chief, MAGES-D Wilmington 28401 ATTN: Chief, SAVES-D Charleston 29402 ATTN: Chief, Eagr Div Savannah 31402 ATTH: Chief, SASAS-L Jacksenville 32232 ATTM: Const Div Mobile 34428 ATTN: Chief, SAMEN-C ATTH: Chief, SAMEN-D Memphis 38103 ATTN: Chief, LOGED-DM Vickeburg 3918G ATTN: Chief, Engr Div Louisvillo 40201 ATTN: Chief, Eagr Div St. Feel 55101 ATTN: Chief, ED-D Onche 58102 ATTM: Chief, Eagr Div New Orleans 70160 ATTN: Chief, LORED-DG Little Reck 72203 ATTM: Chief, Eagr Div Sam Francisco 54105 ATTH: Chief, Engr Div Secrements 95814 ATTH: Chief, EFKED-U Fortland 57208 ATTK: Chief, DS-6 Seattle 98124 ATTH: Chief, MFSCO Walla Walls 95362 ATTN: Chief, Engs Siv Alaska 99501 ATTN: Chief, NASA-2

US Army Engiseer Division New England ATTN: Chief, MEDED-T North Atlastic 19007 ATTH: Chief, MADEN-T South Atlantic 30303 ATTH: Chief, SADEN-TS Buntsville 35807 ATTN: Chief, NEDED-CS ATTN: Chief, NEDED-SR Thio River 45201 ATTN: Chief, Eagr Div Scutingestern 75202 HT-GBCV2 : HTTA Pacific Geesa 55858 ATTH: Chief, Engr Div Forth Pacific 97208 ATTM: Chief, Engr usv

USA-WES 39150 ATTY: C/Structures

Vost Point, MY 10796 ATTR: Dept of Hechanics ATTR: Library

Fort Legezmerth, IS 66027 ATTE: ATELCA-SA

Fact Clayton Canal Zone 34004 ATTB: DFAE

fort HcFhersen, GA 30330 ATTH: AFEN-CD

For: Monroe, VA 23651 ATTH: ATEN-AD (3)

6th US Army 94129 ATTE: AFEC-EN

7th US Army 09407 ATTM: AETTH-HED-SED

US Army Science & Technology 95301 Center - Far East Office

Tymeall AFB, FL 32403 AFESC/MIT

Tinker AFS, OK 73145 2854 ABG/DEEE

Patrick AFS, FL 32923 ATTE: UMO

Meval Air Systems Command 2036C ATTE: Library

Noval Facilities Engr Command 22332

ATTE: Code 04

Transportation Research Seard 20418

Dept of Transportation Library 20590

Petional Defense Betteuerters CEERNA, CANADA KIA OKZ

Airports and Construction Services Dir Ottawn, CAMBA RIA OME

56 2.10/43

Mr. H. Pearl (10) Naval Underwater Systems Center Materials Lab Code 36622 Newport, RI 02840

--